Marion Township		
Section 1  Date Established 7/15/2005  Corner NW	NW	
Marker RR Spike		
42.60' E.S.E. to "+" in south end conc. headwall.	_	
47.64' S.E. to duplex W/side of power pole	_	
14.76' S.W. to "+" in NW corner of catch basin.		
39.57' W. to SW corner, Sec. 36, Monroe Twp.	-	
	- - -	
Section 1		N1/4
Date Established7/15/2005_		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
121.99' W.N.W. to duplex S/side of telephone pole	-	
85.96' N.N.E. to SW corner of conc. foundation	_	
31.73' N.E. to duplex S/side of telephone pole	_	
57.33' S.E. to duplex N/side of power pole		
	- - -	
Section 1		
Date Established 7/15/2005		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker RR Spike.		
15.32' N.W. to iron pin along west edge of pavement	W <sup>1</sup> / <sub>4</sub>	
36.91' E.S.E. to "+" top of east end NE bridge wing.		
24.93' S.E. to NW corner of banister, east bridge rail	-	
25.73' S.W. to NE corner of banister, west bridge rail		
20.70 S. W. to The completed west offage full	_	
	-	
	-	
	-	

# **Marion Township**

Section	1	
<b>Date Estab</b>	lished	8/2/2005
Corner	$E^{1/4}$	
Marker	Iron Pin	ı
32.82' S.W.	<u>to "+" in no</u>	orth end of RCP (P)
66.28' S.S.V	W. to "+" sou	uth end of RCP (P)
89.72' S.S.I	E. to duplex	E/side of power pole
84.80' S to	W¼ Post, Se	ec. 6, Bartlow Twp.
46.85' S to	small RR Sp	pike C/L Road F2

<b>E</b> ½ Rd. F2 46.85' ↓ <b>&gt;</b>
Rd. F2 46.85' 🗘 🔪

Marion 10	ownsnip		
Section 2	2	NW	
<b>Date Establi</b>	shed <u>7/19/2005</u>		
Corner	NW		
Marker	RR Spike		
38.17' N.E. to	o shiner SW/side of power pole		
26.64' W. to	SW corner, Sec. 35, Monroe Twp.		
58.53' N.W.	to "+" in SE corner of headwall		
67.72' S.W. 1	to "+" in south end of conc. box.		
,			
			1.147
Section 2			N <sup>1</sup> / <sub>4</sub>
Date Establi	shed <u>7/19/2005</u>		
Corner	$N^{1/4}$		
Marker	RR Spike		
20.64.6	1 1 337/ 11 6 1		
	luplex W/side of power pole		
	to iron pin on south ditch bank		
	S <sup>1</sup> / <sub>4</sub> Post, Sec. 35, Monroe Twp.		
19.75' N.W.	to iron pin 1' north of north edge of pavement		
		•	•
Section 2		1	
Section 2 Date Establi			
Corner			
Marker	<u>W<sup>1</sup>/<sub>4</sub></u> Stone		
Marker	Stone	v	
Found stone	and cut X in stone per Survey Vol. 26, Pg. 59	x	
	pike on west side of stone for locating purposes only.		
	of 103.12' to stub pole is believed to be in error.		
	ail/shiner in west side of power pole.		
	• •		
	to small RR spike 1.2' E of W edge of paved berm		
44.69' SSE to	o small RR spike 1.4' E of W edge of paved berm		

Marion To	ownship		
	3	NW	
Date Establ			
Corner	NW		
Marker	RR Spike		
83.11' N.W.	to "+" in NW corner of catch basin		
	o shiner W/side of telephone pole 4' tall		
37.63' S.W.	to PK nail SE/side of power pole		
29.75' W. to	SW corner, Sec. 34, Monroe Twp.		
Section -	3		N¹⁄4
Date Establ	ished <u>7/19/2005</u>		
Corner	N <sup>1</sup> / <sub>4</sub>		
Marker	RR Spike		
42.54' S.E. t	o PK in SW/side of power pole		
30.88' S. to '	"+" on witness stone		
27.56' W. to	S <sup>1</sup> / <sub>4</sub> Post, Sec. 34, Monroe Twp.		
		•	
Section _	3		
Date Establ	ished <u>7/19/2005</u>		
Corner	$W^{1/4}$		
Marker	RR Spike		
27.30' N.W.	to sawed "+" north end of CMP (P)	W1⁄4	
44.41' N.E. t	to PK W/side of power pole		
	to "+" in top of iron pipe (P) (no field check)		

<b>Marion Tow</b>	nship		
Section 4	•	NW	
Date Establish	ed7/19/2005		
Corner	NW		
Marker	RR Spike		
70.32' W.N.W.	to shiner SE/side of power pole	-	
27.63' S.S.W. t	o "+" in top of conc. headwall		
31.52' W. to SV	W corner, Sec. 33, Monroe Twp.		
53.08' N.W. to	"+" in north end of elliptical pipe		
	"+" in south end of elliptical pipe.	-	
	+" in east end of 54" RCP	-	
Section 4		-	N <sup>1</sup> / <sub>4</sub>
Date Establish	ed8/2/2005		1374
Date Establish Corner	N <sup>1</sup> / <sub>4</sub>		
Marker	Small RR Spike		
	4 corner, Sec. 33, Monroe Twp.	-	
34.61' N.W. to	"+" in north end of elliptical RCP	_	
37.18' S.W. to	"+" in south end of elliptical RCP	_	
58.83' N.W. to	nail and shiner in SE/side of power pole	-	
		-	
Section 4			
	ed7/19/2005		
Corner	W <sup>1</sup> / <sub>4</sub>		
Marker	Iron pin.		
	1	- W <sup>1</sup> / <sub>4</sub>	
27.05' E to PK	nail in near face of corner post	_	
50.57' S.E. to "	+" in NE corner of catch basin	_	
		-	<b>I</b>
		-	
		_	
		-	

Marion Township		
Section 5	NW	
Date Established7/19/2005		
Corner NW		
Marker RR Spike		
36.02' N.W. to nail and shiner, S/side of power pole		
82.24' S. to duplex W/side of power pole		
65.72' W. to SW corner, Sec. 32, Monroe Twp.		
Section 5		N1/4
Date Established7/19/2005		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
53.65' W.N.W. to nail/shiner SE/side of power pole		
48.29' W. to S <sup>1</sup> / <sub>4</sub> post, Sec. 32, Monroe Twp.		
20.28' N.E. to 5/8" iron pin along north edge of pavement		
Section 5 Date Established 2/26/2018		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Stone		
	W1/4	
Stone 5" below ground surface. Shot high point of stone.	VV /4	
Placed witness post 8" south of high point of stone		
2.3' E to duplex in power pole		
83.93' NE to duplex in 24" tree		
53.51' N to "+" in SW corner conc. pad for small windwill		
Set RR spike for locating purposes only on southerly		
side of stone.		

Marion Township		
Section 6		N1/4
Date Established 7/19/2005		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
61.25' N.E. to nail and shiner in SW/side of power pole		
26.15' S. to chisled "+" in NW corner conc. anchor post		
77.98' W. to S <sup>1</sup> / <sub>4</sub> post, Sec. 31, Monroe Twp.		
23.46' S.E. to "+" in SW corner of catch basin		
Section 6		
Date Established7/19/2005_		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin		
	W1/4	
45.68' WNW.near face gate post W/side field dr (no field check)	V V /4	
66.15' N. to E <sup>1</sup> / <sub>4</sub> post, Sec.1, Pleasant Twp. (not field checked)(P)		
49.94' S.E. to "+" in NW corner of c. b. (not field checked)(P)		
60.81' S.E. to duplex N/side of wood post (P)		
52.07' S.W. to "+" in SE corner of c. b. (not field checked)(P)		
60.80' S.W. to duplex E/side of power pole		
O.O. S. W. to duplek Enside of power pole		
Section 6		
Date Established 7/19/2005		
Corner CENTER Morley		
Marker Iron Pin		
2'± north of north edge of pavement		$\uparrow$
16.96' N. to "+" in conc. corner post 8.72' S. to RR spike		
44.30' S. to PK nail in N/side of power pole		
44.50 S. to FK fiant in N/side of power pole		

# **Marion Township**

Section 6	
Date Established	
Corner N <sup>1</sup> / <sub>4</sub> SE	
Marker <sup>3</sup> / <sub>4</sub> " Rebar	
2.5' N. of north edge of pavement	X
151.00' W.S.W. to inside corner of south bridge rail	N¼SE
139.06' W. to inside corner of north bridge rail	
27.41' S.E. to 5/8" iron pin along south edge of pavement	
27.88' S.W. to 5/8" iron pin along south edge of pavement	

Marion Township	
Section 7	NW
Date Established	
Corner NW	
Marker RR Spike	
99.64' S.W. to PK nail E/side of power pole	
35.77' N.E. to "+" in top of large rock (P)	
53.55' N. to NE corner, Sec. 12, Pleasant Twp.	
Section 7	
Date Established7/20/2005	
Corner W <sup>1</sup> / <sub>4</sub>	
Marker RR Spike	
	W¹/₄
55.52' N.W. to PK nail east end of 18" CMP (P)	
28.65' N.E. to 5/8" iron pin at east edge of pavement	
47.55' N. to E <sup>1</sup> / <sub>4</sub> post, Sec. 12, Pleasant Twp.	
43.82' S.W. to 5/8" iron pin on west ditch bank (P)	
Section 7 Date Established 7/20/2005	
Corner W <sup>1</sup> / <sub>4</sub> SW	
Marker RR Spike	
58.61' N.W. to duplex NE/side of power pole	
38.14' S.E. to duplex SW/side of power pole	<b>K</b> w¼sw
29.89' N.E. to 5/8" iron pin along east edge of pavement	
	<u> </u>

Marion Township		
Section 8	NW	
Date Established 8/2/2005		
Corner NW		
Marker Iron Pin		
85.22' E.S.E. to sawed "+" in conc. hdwl. for drive		
12.64' W. to "+" in north end of 66" CIP		
70.30' E.S.E. to duplex N/side of power pole (P)		
27.59' S.W. to "+" in south end of 66' CIP (P)		
Section 8		N½
Date Established 7/20/2005		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
26.29' S.E. to 5/8" iron pin on south ditch bank (P)		
28.56' S.W. to 5/8" iron pin on south ditch bank (P)		
18.44' N. to 5/8" iron pin along north edge of pavement		
140.42' E.S.E. to duplex N/side of power pole (no field check)		
Section 8		
Date Established 7/20/2005		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
	W1/4	
32.31' W. to duplex S/side of brace pole	V V /4	
20.20' E. to duplex W/side of power pole		
70.94' S.S.E. to "+" in NE corner of catch basin (P)		
68.66' S.S.W. to "+" in west end of conc. pipe (P)		
	L	I

<b>Marion To</b>	ownship		
	9	NW	
Date Establ			
Corner	_NW		
Marker	Iron Pin		
38.27' N.W.	to duplex NE/side of power pole		
35.67' N.E. t	to PK nail SW/side of power pole		
66.21' N.E. t	to "+" in NW wing		
70.87' S.E. t	o "+" in SW wing		
-	o PK nail in SW/side of power pole	L	
<b>Section</b>	9		N¹/₄
<b>Date Establ</b>	ished <u>7/20/2005</u>		
Corner	<u>N¹/4</u>		
Marker	RR Spike		
26.31' N.N.V	V. to SW corner of catch basin		
27.00' N. ot	PK nail E/side of power pole		
20.71' S.W.	to 5/8" iron pin along south edge of pavement		
32.44' to "+	" in face of RR iron fence post.		
	9 ished7/20/2005_		
Corner			
Marker	<u>w / 4</u> 3/4" Rebar		
11201	/4 1 <b>C</b> 001	10/1/	
19.70' S.E. t	o "+" in headwall	W1⁄4	
	to NE corner of catch basin		
26.08' W. to	"+" cut in face of steel fence post		

Marion Township		
Section 10	NW	
Date Established7/20/2005		
CornerNW		
Marker RR Spike		
35.81' N.E. to duplex in SW/side of power pole		
63.50' S.E. to duplex in W/side of telephone pole		
42.06' N.W. to duplex in telephone pole (not field checked)		
27.66' N.W. to PK nail in north end of CMP (P)		
30.14' S.W. to PK nail in west end of 30" CMP (P)		
Section 10		N1/4
Date Established		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
146.03' E.N.E. to duplex S/side of power pole		
87.20' N.W. to PK nail in S/side of power pole		
16.87' N. to 5/8" iron pin along north edge of pavement		
1000, 11, vo e, o non par meng norm cage of parement		
Section 10		
Date Established7/20/2005		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin		
2' west of west edge of pavement	W1/4	
65.12' N.N.E. to PK in SW/side of power pole		
32.99' N.W. to PK in north end of 36" corr. plastic tile		
15.70' W.S.W. to PK in south end of 36" corr. plastic tile		

Marion Township		
Section 11	NW	
Date Established7/21/2005		
Corner NW		
Marker PK Nail		
39.26' N.W. to "+" in north end of CMP (P)		
45.20' N.W. to duplex SW/side of power pole		
50.08' N.W. to nail/shiner in SE/side of power pole		
71.69' S.W. to PK nail in E/side of power pole		
41.14' S.W. to "+" in south end of CMP (P)		
Section 11		N½
Date Established <u>7/21/2005</u>		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
25.23' N.E. to PK E/side of power pole		
25.00' S.E. to "+" in S/end of headwall		
51.95' S.W. to PK nail in W/end of 24" corr. plastic pipe		
39.95' S. to PK nail in W/side of power pole		
Section 11		
Date Established 7/21/2005		
Corner <u>CENTER</u>		
Marker RR Spike		V
8.97' S.W. to 5/8" iron pin along west edge of pavement		
9.68' N.W. to 5'8" iron pin along west edge of payment		
17.57' N.E. to "+" in jog of conc. drive (2½' east of SW corner)		

Marion Township		
Section 12	NW	
Date Established7/18/2005		
Corner NW		
Marker RR Spike		
49.25' S.W. to PK in NE/side of telephone pole		
100.83' N.N.W. to PK in SW/side of telephone pole		
50.13' N.N.E. to sawed "+" in N/end of elliptical RCP		
50.18' S.S.E. to sawed "+" in S/end of elliptical RCP		
Section 12		N1⁄4
Date Established 8/2/2005		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker 5/8" Iron Pin		
41.28' N.E. to duplex SE/side of power pole		
27.98' N.W. to iron pin edge of berm 3' N of S edge of pavement		
27.56 1v. vv. to from pin eage of berning 1v of 5 eage of pavement		
Section 12		NE
Date Established 7/18/2005		
Corner NE		
Marker RR Spike		
48.25' W. to "+" in top center of conc. headwall (P)		
66.04' N.N.E. to duplex NW/side of power pole		
76.43' S. to NW corner, Sec. 7, Bartlow Twp.		
27.92' E.N.E. to PK in W/side of guard rail post, S/end of rail		
2.7.2 2.1.12. to 112 in 17 order of game fair poor, 67 one of fair		

Marion Township		
Section 12  Date Established 7/18/2005  Corner W <sup>1</sup> / <sub>4</sub> NW  Marker Iron Pin	<b>K</b> W14NW	
123.95' N.N.W. to PK in E/side of telephone pole 60.43' S.W. to duplex NW/side of telephone pole		
35.00' S.S.E. to PK in E/end of 12" N12 pipe		
40.05' S.W. to "+" in NE corner of catch basin		
Section 12  Date Established 7/18/2005  Corner W <sup>1</sup> / <sub>4</sub> Marker RR Spike  111.70' N.N.W. to PK in SW/side of telephone pole 84.25 S.S.E. to PK in NW/side of power pole 60.44' S.S.W. to PK in NE/side of telephone pole 39.07' S.E. to metal tee stake in conc. drainage structure	W <sup>1</sup> / <sub>4</sub>	
Section 12  Date Established 7/18/2005  Corner E½  Marker RR Spike		
42.24' W.N.W. to "+" in north end of drainage structure 56.71' N.E. to duplex SE/side of power pole 58.68' S to W <sup>1</sup> / <sub>4</sub> post, Sec. 7, Bartlow Twp. 39.49' W. to "+" in south end of drainage structure		E1

Marion Township		
Section 13	NW	
Date Established5/15/2012		
Corner Wit. Stone to		
Marker Mag Nail over Witness Stone		
55.17' W.S.W. to mag nail in plastic tile (P)		
45.54' N.W. to "+" N/side manhole rim		
74.51' E.S.E. to mag nail in plastic tile (P)		
40.05' S.E. to duplex N/side power pole		
41.82' S.W. to duplex SE/side brace pole		
9.90' E to Section Corner		
Section 13	NW	<del></del>
Date Established5/15/2012		
Marker RR Spike		
Marker RR Spike		
64.67' W.S.W. to mag nail in plastic tile (P)		
52.86' N.W. to "+" N/side manhole rim		
64.76' E.S.E. to mag nail in plastic tile		
35.47' S.E. to duplex N/side power pole		
49.87' S.W. to duplex SE/side brace pole		
9.90' W. to mag nail/witness stone		
7.70 W. to mag man writiess stone		
Section 13		N1⁄4
Date Established 7/18/2005		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin		
30.70' S.S.E. to PK nail E/side of wood post		
19.53' W.N.W. to "+" in E/end of 24" VCP (P)		
17.55 W.IV. W. to   III E/Clid of 24 VC1 (1)		

### **Marion Township** ΝE 13 Section **Date Established** \_\_7/18/2005 Corner NE Marker RR Spike 37.02' N.W. to duplex SE/side of telephone pole 44.25' S.E. to "+" NW cap bolt of fire hydrant 84.07' S. to NW corner, Sec. 18, Bartlow Twp. 33.58' S.W. to "+" in SW corner of catch basin 57.72' N.E. to "+" in S/side of man hole rim 66.06' S.W. to nail & shiner in NE/side of power pole 79.28' E.N.E. to "+" in N/side of man hole rim \_13 Section **Date Established** \_\_7/18/2005 Corner $E^{1/4}$ Marker Iron Pin E1/4 27.92' E.S.E. to nail/shiner W/side of power pole

Marion Township		
Section 14	NW	
Date Established		
Corner NW		
Marker Small RR Spike		
73.35' N.W. to conc. house foundation		
33.45' N.E. to shiner in light pole		
52.54' S.E. to nail/shiner in power pole		
49.48' S.W. to shiner in telephone pole		
11.21' S.S.W. to "+" in north rim of man hole		
40.98' S.E. to "+" in SW corner of catch basin		
36.88' S.E. to nail/shiner in NW/side of power pole		
34.60' N.W.to "+" in S/end of conc. curb		
Section 14		N½
		IN /4
Date Established 7/21/2005		
Corner N <sup>1</sup> / <sub>4</sub> Marker RR Spike		
Marker RR Spike		
55.60' N.W. to "+" in elliptical RCP		
37.95' N.E. to "+" in south flange bolt of fire hydrant		
49.79' S.W. to "+" in elliptical RCP		
91.92' S.E. to PK in NW/side of power pole		
51.52 S.E. to TR in TVW/side of power pole		
Section 14		
Date Established7/21/2005_		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker PK Nail		
101000000	W1/4	
104.80' N.N.E. to nail/shiner SW/side of power pole		
84.62' S.S.E. to nail/shiner NW/side of power pole		
99.12' N.N.W. to PK nail in SE/side of power pole		

# Marion Township Section 14 Date Established \_\_7/21/2005 Corner \_\_CENTER \_\_ Marker RR Spike 90.22' N.N.E. to duplex SW/side of power pole 18.66' W. to PK nail 15" from end of 8" CMP (P) 13.54' S.E. to 5/8" iron pin along east edge of pavement

Marion Township		
Section 15	NW	
Date Established7/21/2005		
CornerNW		
Marker RR Spike		
64.32' W.N.W. to PK nail NE/side of power pole		
40.18' N.E. to PK nail NW/side of power pole		
48.91' S.W. to "+" in west end of RCP		
54.35' S.E. to "+" in east end of RCP		
Section 15  Date Established 7/21/2005  Corner N <sup>1</sup> / <sub>4</sub> Marker RR Spike  25.86' N. to corner of angle iron anchor post		N½
32.20' N.E. to nail/shiner SW/side of power pole		
18.31' S. to PK nail in east end of 36" corr. plastic tile		
18.51 S. to 1 K half in cast clid of 30 Conf. plastic the		
Section 15		
Date Established 7/21/2005		
Corner W <sup>1</sup> / <sub>4</sub> Marker RR Spike		
Marker RR Spike		
66.56' S.S.E. to "+" in NW corner of building foundation	W1⁄4	
26.90' S.W. to duplex N/side of power pole		
101.99' S.S.W. to PK nail in top of 18" corr. plastic tile		

### **Marion Township** NW 16 Section **Date Established** \_\_7/21/2005 Corner NWRR Spike Marker 34.62' N.E. to "+" N/end of west face of headwall 28.77' N.E. to "+" on face of headwall 18.19' S.E. to "+" in NW corner of conc. headwall 29.13' E.S.E. to "+" on top of conc. headwall (P) 59.28' S.W. to PK nail in N/side of power pole $N\frac{1}{4}$ 16 Section 7/21/2005 **Date Established** Corner $N^{1/4}$ Marker RR Spike 20.41' N. to duplex W/side of corner post 10.38' S.W. to 5/8" iron pin along south edge of pavement 9.15' S.E. to 5/8" iron pin along south edge of pavement

Marion Township		
Section 17	NW	
Date Established7/21/2005		
CornerNW		
Marker RR Spike		
81.50' N.E. to PK nail W/side of power pole		
33.45' N.W. to "+" north end of 66" conc. pipe (P)		
27.36' S.W. to "+" south end of 66" conc . pipe (P)		
Section 17		N1/4
Date Established <u>7/21/2005</u>		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
37.26' N.E. to duplex SE/side of power pole		
41.40' N.E. to "+" north end of 15" CIP (P)		
58.85' E. to iron pin on centerline of Road 10A		
92.51' E.S.E. to "+" east wall of catch basin (P)(no field check)		
52.71' E.S.E. to "+" in conc. headwall (P)		
Section 17		
Date Established 7/21/2005		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker #6 Rebar		
	W1/4	
121.81' N.N.E. to duplex W/side of telephone pole		
155.20' N.E. to SW corner of house foundation (no field check)		
25.06' E. to duplex N/side of power pole		
16.90' W. to "+" chiseled in top center rivet of pipe (P)		
22.70' N.E. to "+" chiseled in top center rivet of pipe (P)	u.	•

Marion Township		
Section 18	NW	
Date Established 7/21/2005		
Corner NW		
Marker RR Spike		
31.96' S.E. to duplex W/side of power pole		
14.85' N.W. to duplex E/side of north end post guard rail		
13.45' S.W. to duplex E/side of south end post guard rail		
53.99' E.S.E. to "+" in headwall (P)		
Section 18		N1/4
Date Established 7/21/2005		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
21 201 N N / 5/911		
31.29' N.W. to 5/8" iron pin at edge of pavement		
28.60' N.E. to 5/8" iron pin at edge of pavement		
Section 18		
Date Established7/22/2005_		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Rebar		
50.30' N.W. to duplex NE/side of power pole (no field check)	W <sup>1</sup> ⁄ <sub>4</sub>	
23.25' E.S.E. to duplex S/side of power pole		
80.41' N.N.E. to "+" SE corner of catch basin		
41.03' N.W. to "+" in south end of 48" RCP		
71.93' N.N.W. to "+" in north end of 48" RCP		

NW	
	N¹/₄
W1/4	

Marion Township		
<b>Section</b>		
Date Established		
Corner N <sup>1</sup> / <sub>4</sub> SW		
Marker Iron Pin		
18.38' N.W. to duplex SW/side of power pole 51.55' S.S.E. to "+" in NW corner of catch basin (P) 50.63' S.S.W. to "+" north end of conc. headwall (P)	N¹/₄SW	

Marion Township		
Section 20	NW	
Date Established 7/25/2005		
Corner NW		
Marker RR Spike		
43.42' S.W. to PK nail SE/side of power pole		
86.30' N.N.E. to near face of well casing		
34.29' S.W. to "+" south end of RCP (P)		
45.37' N.W. to "+" north end of RCP (P)		
39.17' NE to PK nail NW/side of power pole	L	
Section 20		N¹⁄4
Date Established		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
25 59! N.N.E. to duplay W/gido of payor pole		
25.58' N.N.E. to duplex W/side of power pole 29.50' S.S.E. to "+" east end of RCP (P)		
41.29' S.W. to "+" west end of RCP (P)		
40.59' S.E. to PK nail SW/side of power pole		
		1
Section .20		
Date Established 7/25/2005		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
27.86' N.W. to duplex SW/side of power pole	W1⁄4	
51.61' S.W. to NE corner of conc. foundation		
24.92' N.E. to PK in W/side of telephone pole		
1		

# **Marion Township**

Section	_20
Date Estab	olished <u>7/25/2005</u>
Corner	OTHER
Marker	RR Spike
20.66' N.E.	to duplex W/side of power pole
34.55' N.E.	. to "+" SW corner of catch basin (P)
46.27' S.E.	to duplex SW/side of power pole
51.08' S.W	to duplex NW/side of power pole
23.48' S.W	. to "+" in NE corner of catch basin
-	

Marion Township		
Section 21	NW	
Date Established 7/25/2005		
Corner NW		
Marker RR Spike		
24.25' N. to duplex W/side of telephone pole		
23.01' S.S.E. to duplex E/side of power pole		
15.75' N.E. to iron pin along north edge of pavement		
12.04' N.W. to iron pin along north edge of pavement		
Section 21		N½
Date Established 7/25/2005		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
41.13' N.W. to PK nail SE/side of power pole		
19.46' S.E. to iron pin along south edge of pavement		
80.51' S.W. to duplex N/side of power pole		
Section 21		
Date Established 7/25/2005		Rd. 10B
Corner N1/4 NE		
Marker Iron Pin		
20.02' N.W. to "+" in SW corner of catch basin		
37.04' S.W. to PK in W/side of power pole		
43.92' S.E. to iron pin along south edge of pavement		

Marion Township		
Section 21	1	1
Date Established2/12/2018		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Stone	v	
Found Iron Pin beside stone for locating.	x	7
Placed witness post approx. 1 ft. north of high point of stone		
Placed clay tile around stone.		
Found stone from Survey Vol. 34, Pg. 175		
Section 21		
Date Established		Rd. 10B
Corner N <sup>1</sup> / <sub>4</sub> SE		
Marker RR Spike		V
21.88' W. to duplex N/side of power pole		
36.70' N.W. to <sup>3</sup> / <sub>4</sub> " iron pin		
19.82' E. to ¾" iron pin		
17.83' S.E. to "+" S/side of round catch basin		
27.85' S.W. to PK nail south end of 12" CMP		
17.04' S.W. to PK nail north end of 12" CMP		
Section 21		
Date Established 4/2/2014		Rd. 10B
Corner OTHER Northern N. N. 11 0.75 in the CR of the CR		
Marker Mag. Nail 0.75 mi. south of Road D		
45.16' S.W. to duplex on E/side of power pole		
17.91' W.S.W. to mag nail in south end 12" CMP		<b>x</b>
21.60' N.W. to PK nail on north end 12" CMP		1 1
9.38' S.E. to iron pin at edge of pavement		
10.92' N.E. to iron pin at edge of pavement		

### **Marion Township** NW 22 Section **Date Established** 7/25/2005 Corner NWRR Spike Marker 25.50' S. to angle iron 32.87' S.W. to duplex on power pole 57.67' N.E. to PK SE/side of power pole 74.46' N.W. to "+" in SE corner of school foundation $N\frac{1}{4}$ 22 Section 7/25/2005 **Date Established** Corner $N^{1/4}$ Marker RR Spike 24.70' S.W. to duplex in power pole 18.70' N.W. to iron pin along north edge of pavement 20.61' N.E. to iron pin along north edge of pavement

Marion Township		
Section 23	NW	
Date Established 7/25/2005		
Corner NW		
Marker PK Nail		
41.64' S.E. to PK east end of 12" CMP (P)	-	
35.15' S.W. to PK west end of 12" CMP (P)	_	
35.10' S.W. to TR west end of 12 CMM (1)	_	
57.35' N.W. to PK SW/side of power pole	_	
57.55 W. to 1 K 5 W/side of power pole		
	_	
	_	
Section 23		N1/4
Date Established		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
57.96' N.W. to "+" in north end of RCP (P)	_	
40.51' N.E. to duplex SE/side of power pole		
21.82' S.E. to duplex NW/side of power pole		
45.00' S.W. to "+" in south end of RCP (P)	_	
	_	1
	_	
Section 23	_	
Date Established 7/25/2005		
Corner W1/4		
Marker PK & Shiner		
	- W <sup>1</sup> / <sub>4</sub>	
22.72' W.S.W. to PK nail east end of 12" CMP (P)	V V 74	
24.21' S.E. to iron pin along east edge of pavement		
27.61' N.E. to iron pin along east edge of pavement		
	- L	
	_	
	_	
	_	

# Marion Township Section 23 Date Established \_\_7/25/2005 Corner \_\_CENTER Marker RR Spike 53.08' N.N.W. to PK nail west end of 8" corr. plastic pipe 25.47' S.E. to duplex W/side of power pole 16.69' S.S.W. to 5/8" iron pin at west edge of pavement

Marion T	ownship		
	24	NW	
Date Establ			
Corner	NW		
Marker	RR Spike		
27.27' N.W.	to "+" west end of conc. headwall (P)	_	
20.06' N.N.'	W. to "+" east end conc. headwall (P)		
24.53' S.S.V	V.to "+" in conc. headwall (P)		
23.95' W.S.	W. to "+" in conc. headwall (P)	_	
Section -	24		N1/4
<b>Date Establ</b>	lished <u>7/18/2005</u>		
Corner	$N^{1}/_{4}$		
Marker	RR Spike		
56.81' S.W.	to duplex N/side of power pole	_	
68.89' W.S.	W. to "+" inside corner of south bridge rail	_	
61.44' W.N.	W. to inside corner north bridge rail	_	
24.48' S.S.E	E. to PK in east end of 15" corr. plastic pipe		
		  _	
Section -	24		NE
<b>Date Establ</b>	lished		
Corner	<u>NE</u>		
Marker	RR Spike.		
8.05' S.W. to	o duplex SE/side of guard rail post	_	
10.76' N.W.	to duplex E/side of guard rail post	_	
79.53' S. to	NW corner, Sec. 19, Bartlow Twp.	_	
		_	
		_	
		_	

Marion Township		
Section 24		
Date Established7/18/2005		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin		
	— W <sup>1</sup> / <sub>4</sub>	
25.79' N.W. to 5/8" iron pin on west ditch bank (P)		
22.91' S.W. to 5/8" iron pin on west ditch bank (P)	_	
18.66' E. to 5/8" iron pin 1' east of east edge of pavement	_	
Section 24		
Date Established 7/26/2005		
Corner E <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
16.36' S.W. to duplex on power pole	_	E1/4
117.72' S.E. to "+" in NW corner of conc. catch basin	_	
68.58' S.to W <sup>1</sup> / <sub>4</sub> corner, Sec. 19, Bartlow Twp.	_	
	_	
21.17' S.E.to iron pin along east edge of pavement	_	
Section 24		
Date Established7/26/2005		
Corner _E <sup>1</sup> / <sub>4</sub> SE		
Marker RR Spike		
8.04' W. to duplex N/side of power pole		
49.50' N.E. to duplex SE/side of buried cable marker		E1/4SE>
72.89' S. to RR spike in pavement		L/40L
92.31' S.S.E. to "+" in east side of catch basin	_	
	_	
	_	

<b>Marion To</b>	ownship		
	25	NW	
Date Establi	shed7/18/2005		
Corner	NW		
Marker	RR Spike		
27.56' N.W.	to "+" north end of 72" RCP (P)		
38.87' N.E. to	o duplex SE/side of underground cable marker		
36.63' S.E. to	duplex NE/side of underground cable marker		
92.76' S.S.E.	to duplex W/side of power pole		
30.68' S.W. t	to "+" south end of 72" RCP (P)	<u> </u>	I
Section 2	25		N1⁄4
<b>Date Establi</b>	shed <u>8/1/2005</u>		
Corner	N¹/4		
Marker	Iron Pin		
66 16' E.S.E.	to PK nail in CMP		
	8" iron pin on ditch bank		
	<u> </u>		
Section 2	25		NE
Date Establi			
Corner	NE		
Marker	RR Spike		
19.80' W.N.V	W. to "+" south end of 10' CMP arch (P)		
66.16' N.N.V	V. to duplex E/side of power pole		
55.25' S.S.W	. to duplex E/side of north guard rail post		
55.82' N.N.V	V. to "+" in north end of 10' CMP arch (P)		
15.73' E. to 5	i/8" iron pin along east edge of pavement	<u> </u>	

### **Marion Township** 25 Section **Date Established** 7/26/2005 Corner $W^{1/4}$ Marker RR Spike W1/4 34.93' W. to 30d spike N/side of wood anchor post 26.22' N.E. to duplex NW/side of power pole 55.09' S.S.W. to PK nail in west end 8" CMP (P) 30.54' S.E. to iron pin along east edge of pavement 25 Section **Date Established** 7/26/2005 Corner $E^{1/4}$ Marker RR Spike E1/4 147.41' N. to duplex E/side of power pole 119.11' S.S.E. to "+" NW corner conc. catch basin (P) 68.63' S. to E<sup>1</sup>/<sub>4</sub> Post, Sec. 30, Bartlow Twp. 87.13' S.S.W. to duplex E/side of power pole 31.69' S.W. to 5/8" iron pin on ditch bank (P) 36.65' N.W. to 5/8" iron pin on ditch bank (P)

Marion Township		
Section 26	NW	
Date Established 7/25/2005		
Corner NW PK Nail		
Marker PK Nail		
17.93' W.S.W. to "+" west end of stone headwall (P)		
30.86' S.E. to iron pin along east edge of pavement		
27.72' S.W. to nail and shiner NE/side of power pole		
102.75' S.W. to NE corner church foundation		
Section 26		N½
Date Established 7/25/2005		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
84.30' N.N.E. to PK nail SE/side of power pole		
55.93' E.N.E. to PK nail W/side of power pole		
10.35' S.W. to iron pin along south edge of pavement		
Total at the first along boats sage of pavelions		
Section 26		
Date Established		
Corner <u>W<sup>1</sup>/<sub>4</sub></u>		
Marker PK & Shiner		
71.02' N.E. to nail/shiner SW/side of underground cable marker	W¹⁄₄	
36.56' S.W. to nail/shiner NE/side of power pole		
42.68' S.E. to "+" in south end of 12" CMP		
24.48' E.S.E. to "+" in north end of 12" CMP		

Marion Township		
Section 27	NW	
Date Established7/26/2005		
Corner NW		
Marker RR Spike		
20.07! N.W. to dymlay E/side of nevyon mela		
29.97' N.W. to duplex E/side of power pole		
11.94' N.N.E. to "+" east end abandoned wing(P)(no field check) 64.94' S.S.E. to duplex W/side of power pole		
99.40' S.W. to NE corner block foundation of house		
15.00' N.E. to PK nail in SE/side of guard rail post		
Section 27	N½NW	
Date Established 7/26/2005	11/41111	
Corner N <sup>1</sup> / <sub>4</sub> NW		
Marker RR Spike		
127.07' W.N.W. to PK S/side of power pole		
23.02' S.S.W. to PK W/side of wood corner post		
16.98' N.E. to iron pin along north edge of pavement		
~		N11/
Section 27		N1⁄4
Date Established 7/26/2005		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin		
111.05' S.S.E. to PK nail in N/side of light pole		
32.98' N.E. to PK in NW corner of metal building foundation		
44.71' S.E. to PK in SW corner of metal building foundation		

<b>&lt;</b> W1/4NW	
W <sup>1</sup> / <sub>4</sub>	

## **Marion Township** $N\frac{1}{4}$ \_28\_ Section **Date Established** 7/26/2005 Corner $N^{1/4}$ Marker RR Spike 5.92' W.S.W. to NE corner Urban E. Edwards tombstone 19.16' N.W. to SE corner Josiah L. Kieth tombstone 24.45' N.W. to SE corner Dr. C.M. Overhulse tombstone 22.10' N. to SE corner Joseph D. Kinney tombstone N¼NE 28 Section **Date Established** 7/26/2005 Corner $N^{1/4}$ NE Marker Small RR Spike 34.08' N.W. to duplex SE/side of power pole 76.20' S.E. to PK SW/side of telephone pole 26.55' N.E. to iron pin along edge of pavement radius 23.72' S.W. to iron pin along south edge of pavement

Marion Township		
Section 29	NW	
Date Established 7/27/2005		
Corner NW		
Marker RR Spike		
21.30' N.N.W. to "+" in conc. curb		
54.83' N.N.W. to "+" in SE corner conc. drive		
106.60' N.N.E. to duplex E/side of telephone pole		
82.82' S.S.W. to PK in E/side of power pole		
Section 29		N½
Date Established 7/27/2005		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin		
39.72' N.E. to 5/8" iron pin on east ditch bank (P)		
34.26' S.E. to 5/8" iron pin on east ditch bank (P)		
12.47' W. to an iron pin on west top of bank		
Section 29		
Date Established 7/27/2005		XW¼NE
Corner W <sup>1</sup> / <sub>4</sub> NE		
Marker Iron Pin		
39.30' N.E. to 5/8" iron pin on east ditch bank (P)		
24.47' E. to duplex N/side of power pole		
34.17' S.E. to 5/8" iron pin on east ditch bank (P)		

Marion Township		
<b>Section</b> <u>29</u>		
Date Established		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
19.90' W.N.W. to duplex NE/side of power pole 14.44' E. to PK in S/side of telephone pole 20.54' S.W. to iron pin along west edge of pavement	W1/4	

## **Marion Township** NW \_30\_ Section 7/27/2005 **Date Established** Corner NWMarker RR Spike 120.54' W. to "+" in south end conc. headwall (P) 26.25' N.N.E. to PK east end of 18" CMP (P) 17.15' N.W. to iron pin along north edge of pavement 19.24' N.E. to iron pin along north edge of pavement N¹¼NW \_30 Section 7/27/2005 **Date Established** Corner $N^{1/4}NW$ Rd. 12A Marker RR Spike 24.70' N.W. to "+" in center of conc. headwall (P) 24.69' S.E. to "+" NE corner of catch basin (P) Rd. Y 17.78' S.W. to iron pin along mid radius \_30 Section **Date Established** \_\_7/27/2005 Corner OTHER

RR Spike

23.48' W.N.W. to duplex N/side of telephone pole

27.75' N.N.E. to 5/8" iron pin 1' east of edge of pavement

25.71' S.S.E. to 5/8" iron pin 1' east of edge of pavement

Marker

Rd. 12A

Rd. Y

Marion Township		
Section 31	NW	
Date Established8/19/2020		
CornerNW		
Marker Iron Pin		
20.48' N.W. to "+" south end of 84" CMP (P)		
71.06' N.N.W. to "+" north end of 84" CMP (P)		
37.15' N. to NE corner, Sec. 36, Pleasant Twp.		
79.79' N.W. to duplex SW/side of power pole		
36.01' S.E. to duplex W/side of telephone pole		
Section 31		
Date Established 8/19/2020		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin		
non i m	10/1/	
18.22' N. to E <sup>1</sup> / <sub>4</sub> Post, Sec. 36, Pleasant Twp.	W1⁄4	
65.90' N.N.W. to "+" in north end of 56" RCP		
23.67' S.W. to "+" in south end of 56" RCP		
51.47' N.W. to duplex NE/side power pole		
51.17 1 to duplex 1/E/slae power pole		
Section 31		
Date Established		
Corner _SW		
Marker RR Spike		
42.74' N.W. to duplex SW/side of power pole		
47.26' N.E. to PK nail S/side of telephone pole		
39.82' S.W. to duplex NW/side of telephone pole		
44.61' S.W. to "+" in west end of CMP	sw	

S¼SW
S1/ <sub>4</sub>

Marion Township		
Section <u>32</u>	NW	
Date Established 9/12/2017		
Corner <u>NW</u>		
Marker Position of Stone that has moved		
28.93' W.S.W. to MAG in south side of power pole		
45.46' E.S.E. to "+" in NW corner catch basin		
74.17' N.N.E. to MAG in NW/side power pole		
16.04' E. to RR Spike		
Section 32		
Date Established 9/12/2017	16'	
Corner OTHER		
Marker RR Spike (Offset Spike to Stone)		
32.06' S.E. to "+" in NW corner catch basin (P)		
68.20' N.N.E. to MAG NW/side of power pole		
18.41' S.W. to PK nail in 10" CMP		
43.87' W.S.W. to MAG in south side power pole		
Section 32		N1/4
Date Established		
Corner N1/4		
Marker RR Spike		
15.25' E.S.E. to 5/8" iron pin at south edge of pavement		
18.14' W.S.W. to 5/8" iron pin along south edge of pavement		
11.07' N. to 5/8" iron pin along north edge of pavement		

<b>Marion To</b>	wnship		
Section 3	2		
<b>Date Establis</b>	shed7/27/2005		
Corner	$W^{1/4}$		
Marker	Iron Pin		
	13½' west of west edge of pavement	W <sup>1</sup> / <sub>4</sub>	
No Ties		V V /4	
Section 3	2		
Date Establis			
Corner	SW		
Marker	5/8" Rebar		
172011101	576 Recui		
47.21' N.W. t	o duplex SW/side of power pole		
43.76' N.W. t	o "+" west end conc. headwall (no field check)		
36.40' N.N.W	. to "+" east end conc. headwall (no field check)		
4.32' S.S.W. 1	to duplex in NW/side first brace of guard rail	sw	
33.39' W.S.W	. to duplex N/side last guard rail post		
	duplex SE/side of telephone pole		
Section 3	2		
	shed7/27/2005		
Corner			
Marker	Iron Pin		
26.55' S.E. to	"+" in east end of RCP (P)		
21.25' S.W. to	o "+" in west end of RCP (P)		
22.73' N. to to	op of leaning iron pin		
		S1/4	

Marion Township		
Section 33	NW	
Date Established		
Corner NW		
Marker RR Spike		
19.45' N.N.W. to duplex E/side of telephone pole		
22.51' N.E. to 5/8" iron pin N/side of pavement		
21.89' S. to near edge angle iron post (no field check)		
11.36' S.E. to 5/8" iron pin along south edge of pavement		
Section 33		
Date Established9/23/2014		
Corner <u>OTHER</u>	RD 10A	
Marker RR Spike		
Intersection of 10A & B		
No Ties to Stone		
The first to stone		
Section 33		N½
Date Established 7/28/2005		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
20.49' N. to "+" W/side of conc. anchor post		
28.01' N.E. to "+" east end conc. headwall		
95.00' E.N.E. to duplex S/side of telephone pole		
13.38' S.E. to "+" in headwall		
23.02' S.S.E. to "+" in conc. headwall	<u> </u>	

Marion Township		
Section 33		
Date Established11/16/2016		
Corner <u>W<sup>1</sup>/4</u>		
Marker Found stone (12 x 10 x 6) with Iron Pin on SE		
side of stone	W1/4	
Iron Pin is for locating purposes only. Placed sign post and	V 74	
sign indicating surveying marker. Center of stone is 0.7' west		
of sign post. Refer to County GPS co-ordinates for location		
of stone.		
Section 33		
Date Established1/26/2018		
Corner CENTER		
Marker Mag Nail in Concrete Remains	L ,	
Placed mag nail in center of concrete remains that were still in the	î	
ground. Used mag nail as point for GPS shot. Placed witness		
post to the west of described point. Placed pieces of clay tile and		
loose concrete over described point. Mag nail is around 9"		
below the ground.		
Concrete post called for in Survey Vol 23, Pg. 208 and in old		
section corner field book.		
Section 33		
Date Established 7/28/2005		
Corner SW		
Marker Small RR Spike over Iron Pin		
33.03' S. to duplex E/side of wood corner post		
20.30' S.W. to 5/8" iron pin on north bank of roadside ditch		
20.10' S.E. to 5/8" iron pin on north bank of roadside ditch		
	SW	

## **Marion Township**

Section 33		
Date Established		
Corner S <sup>1</sup> / <sub>4</sub>		
Marker 5/8" Iron Pin		
15.70' E. to Putnam Co. stone (no field check)		
47.05' E.S.E. to 5/8" iron pin on north ditch bank		
31.86' S.E. to duplex N/side of wood anchor post		
16.66' S.W. to iron pin on north ditch bank		S1⁄4
	•	

Marion T	ownship		
	34	NW	
Date Establ			
Corner	NW		
Marker	RR Spike		
		_	
	to "+" north end of RCP (P)		
	to duplex SE/side of power pole		
31.07' S.E. t	to "+" in center of conc. headwall		
20.25' S.W.	to "+" in center of conc. headwall (P)		
Section -	34	_	N1/4
<b>Date Establ</b>	lished		
Corner	$N^{1/4}$		
Marker	RR Spike		
52 68' F N F	E. to nail/shiner S/side of power pole	_	
	S.W. to duplex N/side of power pole	_	
	to iron pin along north edge of pavement	_	
27.31 IN. W.	to from pin along flortif edge of pavement	_	
Section -	34		
<b>Date Establ</b>	ished <u>7/28/2005</u>		
Corner	<u>W¹/₄</u>		
Marker	Iron Pin		
		— W¹⁄₄	
	to SE corner block house foundation		
	to duplex SE/side power pole		
	to PK nail in 24" CMP (P)		
49.37' N.N.	W. to "+" in north end of 48" CIP	_	
33.23' S.E. t	to duplex in NE/side of power pole		

Marion Lownship		
Section 34		
Date Established 7/28/2005		
Corner W <sup>1</sup> / <sub>4</sub> SW		
Marker Iron Pin		
21.77' E. to duplex N/side of wood post (post is loose)		
31.80' S.E. to duplex NE/side of power pole	<b>K</b> W½SW	
39.03' S.W. to PK nail in 18" CMP (P)		
20.24' N.E. to iron pin along east edge of pavement		
	u I	
g		
Section 34		
Date Established 7/28/2005		
Corner <u>SW</u>		
Marker Iron Pin		
33.00' E. to RR spike (Putnam Co.)		
58.84' E.S.E. to "+" in 6" CIP (P)		
30.31' S.S.E. to stud in north end of 15" CIP (P)		
62.24' S.S.E. to duplex W/side of power pole	sw	
02.24 S.S.L. to duplex w/side of power pole		
Section 34		
Date Established 7/28/2005		
Corner S <sup>1</sup> / <sub>4</sub> SW		
Marker RR Spike		
11.10' N.W. to 5/8" iron pin along north edge of pavement		
11.91' N.E. to 5/8" iron pin along north edge of pavement		
	S1/4SW	

## **Marion Township**

20.13' S.W. to "+" SW bridge wing (P)

Section	34		
Date Esta	ablished <u>8/1/2005</u>		
Corner	<u>S¹/4</u>		
Marker	Small RR Spike		
	37.5 Links (27.75') east of stone		
Ties to sto	one:		
24.20' N.I	E. to "+" NW bridge wing (P)		
12.57' S.E	E. to "+" SW bridge wing (P)		
Ties to S½ Corner:			S1⁄4
21.51' N.	.W. to "+" NW bridge wing (P)	I	
34.82' N.	E. to "+" NE bridge wing (P)		
28.64' S.I	E. to "+" SE bridge wing (P)		

Marion Township		
Section 35	NW	
Date Established7/28/2005		
Corner NW		
Marker Small RR Spike		
36.28' N.W. to "+" NE corner of catch basin (P)		
49.31' N.E. to nail/shiner SW/side of underground cable marker		
37.69' S.W. to "+" in west end of RCP (P)		
40.89' E.N.E. to "+" in east end of RCP		
Section 35		N1⁄4
Date Established 7/28/2005		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
27.97' S.E. to duplex SW/side of power pole		
40.43' S.W. to "+" in south end of RCP		
38.18' N.W. to "+" in north end of RCP		
20.24' N.E. to iron pin along edge of pavement radius		
Section 35  Date Established 7/28/2005  Corner W1/4  Marker Small RR Spike		
11 101 C W/ 42 Jan 1 1 NW/-1 1 C 1 1 1 4	W1/4	
11.18' S.W. to duplex in NW/side of guard rail post 67.36' S.E. to "+" in northeast corner of catch basin		
47.97' S.E. to nail/shiner NW/side of power pole		
40.55' N.N.W. to "+" in southwest wing		
59.91' N.E. to "+" in southeast wing		

Marion Township	
<b>Section</b> <u>35</u>	
Date Established 7/28/2005	
Corner <u>CENTER</u>	
Marker RR spike	
	X
18.74' E. to duplex S/side of power pole	
82.30' S.S.W. to duplex W/side of meter pole	
15.75' N.E. to iron pin along east edge of pavement	
	1
25	
Section 35	
Date Established	
Corner SW 17/29/95	
Marker ODOT Monument Box - Found 7/28/05	
	CVV
	SW
Section 35	
Date Established7/28/2005	
Corner S <sup>1</sup> / <sub>4</sub>	
Marker RR Spike	
28.11' N.W. to 5/8" iron pin mid radius along edge of pavement	
35.78' N.E. to 5/8" iron pin	
28.25' S. to 5/8" iron pin on south ditch bank (P)	
	S1/4
	L L

Marion Township	
Section 35	
Date Established 7/28/2005	
Corner S <sup>1</sup> / <sub>4</sub> SE	
Marker Iron Pin	
20.37' N.W. to 5/8" iron pin along north edge of stone road 25.38' N.E. to 5/8" iron pin along north edge of stone road 30.18' S.E. to PK nail north end of 12" plastic pipe (P)	S½SE

Marion Township		
Section 36	NW	
Date Established7/28/2005		
Corner NW		
Marker RR Spike		
36.29' N.W. to duplex NE/side of underground cable marker		
29.57' N.W. to "+" north end of RCP (P)		
32.78' S.E. to duplex SW/side of power pole		
29.40' S.W. to "+" south end of RCP (P)		
Section 36	N <sup>1</sup> / <sub>4</sub> NW	
Date Established7/28/2005	IN 74IN VV	
Corner N <sup>1</sup> / <sub>4</sub> NW		
Marker RR Spike		
17.41' N.E. to 5/8" iron pin along north edge of pavement		
123.01' E.S.E. to duplex N/side of power pole		
17.25' W.S.W. to 5/8" iron pin at south edge of pavement		
		1
Section 36		N½
Date Established7/28/2005		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin		
27 40! W. to 5/9!! iron nin at south adap of novement		
37.40' W. to 5/8" iron pin at south edge of pavement		
23.45' N.W. to "+" southeast corner of catch basin (P)		
25.14' N.E. to 5/8" iron pin along north edge of pavement		
	u.	•

Marion Township		
Section 36		NE
Date Established7/28/2005		
Corner NE		
Marker RR Spike		
73.72' S.W. to PK in SE/side of power pole	_	
57.55' S.S.W. to duplex in N/side of power pole	_	
43.35' N.W. to "+" in north end of CMP	_	
31.76' N.E. to PK in SE/side of 4" wood fence post		
	<u> </u>	
Section <u>36</u>		
Date Established 7/29/2005		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
22 101N1N1W1	── W¹⁄₄	
23.10' N.N.W. to 5/8" iron pin at west edge of pavement	_	
11.60' S.W. to "+" west end of CIP (P)	_	
53.44' S.E. to duplex in SW/side of telephone pole	_	
Section 36		
Date Established 7/29/2005		
Corner E <sup>1</sup> / <sub>4</sub> Marker RR Spike		
ret Spike		
33.18' N.N.W. to duplex E/side of power pole		E!
22.71' S.E. to 5/8" x 24" iron pin along east edge of pavement		
174.54' S.S.W. to duplex E/side of power pole		
40.67' S. to W <sup>1</sup> / <sub>4</sub> Post, Sec. 36, Bartlow Twp.		
70.07 S. 10 W /4 I OSI, Sec. 30, Dairiow I wp.		

Marion Township		
Section <u>36</u>		
Date Established 7/29/2005		
Corner W <sup>1</sup> / <sub>4</sub> SW		
Marker Iron Pin		
41.46' N.E. to 5/8" iron pin at east edge of payment (P)		
37.02' S.E. to 5/8" iron pin at east edge of pavement (P)	<b>K</b> W1/4SW	
	1	
Section 36		
Date Established 7/29/2005		
Marker RR Spike		
31.90' N.W. to "+" north end of RCP (P)		
22.57' S.W. to "+" south end of RCP (P)		
21.26' S.E. to iron pin along east edge of pavement		
21.20 S.L. to from pin along east edge of pavement	sw	
	SVV	
Section 36		
Date Established7/29/2005		
Corner S <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin		
26.04' N.W. to 5/8" iron pin		
28.40' N.E. to 5/8" iron pin		
22.15' S.W. to "+" in west end of CIP		
	S1/4	