Section 1		
Date Established 8/29/2007	NW	
Corner <u>NW</u>		
Marker RR Spike below surface		
45.94' SE to "+" east end concrete pipe (P)		
15.08' SW to "+" corner of concrete headwall (P)		
51.23' NE to duplex SE/side telephone pole (leans south)		
46.54' W to Harrison Twp. Corner (iron pipe)		

Section 1	N 14 /
Date Established 8/29/2007	N1⁄4
Corner <u>N¹/a</u>	
Marker RR Spike	
83.67' WNW to duplex NE/side telephone pole	
59.52' ENE to duplex S/side telephone pole	
42.02' SSW to duplex W/side power pole	
18.95' W to Harrison Twp. Corner (RR Spike)	

Section 1	(r	
Date Established 8/29/2007		NE
Corner <u>NE</u>		
Marker RR Spike		
29.55' NE to duplex SE/side telephone pole		
44.02' SE to duplex NE/side power pole		
42.61' SW to duplex NW/side power pole		
95.65' NNW to duplex E/side power pole		
79.85' SW to NE corner concrete foundation telephone building		

<i>Section</i> <u>1</u>		
Date Established 8/29/2007		
Corner <u>W¹/4</u>		
Marker Iron Pin		
PK's 5' NE and SE		
22.97' NW to "+" north end steel drive pipe	W1⁄4	
22.45' SW to "+" north end steel drive pipe		

Section 1	r	
Date Established 8/29/2007		
Corner <u>F1/4</u>		
Marker Iron Pin		
30.66' W to duplex SW/side power pole		
27.13' NW to 5/8" iron pin 1' west of pavement		E¼
37.71' SW to 5/8" iron pin 1' west of pavement		

Section 2	b 1) a /	
Date Established 8/29/2007	NW	
Corner <u>NW</u>		
Marker RR Spike		
48.00' NE to shiner SW/side power pole		
51.27' SE to shiner NW/side power pole		
54.50' WSW to "+" in 24" concrete pipe (P)		
83.16' W to Harrison Twp. Corner		
57.64' NW to "+" SE corner CB (P)		

N ¹ ⁄4

Section 2		
Date Established 8/29/2007		N¼NE
Corner <u>N¼ NE</u>		
<i>Marker</i> <u>RR Spike 2" below surface</u> 63.49' ESE to duplex N/side telephone pole	_	
60.85' NW to ³ / ₄ " iron pin		
23.33' SE to mag nail east end 15" corrugated plastic pipe		
97.94' WSW to duplex N/side power pole	_	
	_	
	_L	

Section 2		
Date Established 8/29/2007		
Corner <u>W1/4</u>		
Marker Nail/Shiner		
42.42' NW to duplex SW/side power pole		
76.33' NE to duplex SE/side power pole	W1⁄4	
80.18' SSE to nail/shiner NW side power pole (leans west)		
26.43' W to ¹ / ₂ " iron pipe (P)		

Section 3	N 1) A /	
Date Established 8/29/2007	NW	
Corner <u>NW</u>		
Marker Small RR Spike		
55.19' ESE to "+" NE corner CB (P)		
29.83' SE to duplex E/side telephone pole		
90.65' WSW to duplex S/side telephone pole		
29.92' NNW to duplex SE/side brace pole		
80.25' WSW to "+" east corner CB		
53.55' W to Harrison Twp. Corner (small RR spike)		

Section 3	1 17
Date Established 8/29/2007	N ¹ ⁄4
Corner <u>N¹/4</u>	
Marker Small RR Spike	
74.88' ESE to duplex N/side power pole	
44.23' WSW to PK nail N/side telephone pole	
67.14' W to S ¹ / ₄ Post, Sec. 34, Harrison Twp.	
65.57' WSW to "+" NE corner CB (P)	
49.12' NW to duplex SW/side power pole	

Section 3	r	
Date Established 8/29/2007		
Corner <u>W¹/4</u>		
Marker Small RR Spike		
100.19' SSW to mag nail N/side power pole (P)		
20.09' NW to "+" SW corner CB (P)	W1⁄4	
27.46' W to duplex S/side power pole		

Section 4	N 13 A 7	
Date Established 8/29/2007	NW	
Corner <u>NW</u>		
Marker Harrow Tooth 2" below surface		
80.71' ESE to duplex N/side telephone pole		
52.91' WSW to duplex NW/side power pole		
63.92' WSW to duplex E/side telephone pole		
63.82' NE to duplex S/side power pole		
59.35' W to Harrison Twp. Corner		
38.74' WNW to "+" NW corner CB (P)		

Section 4	N 11 /
Date Established 8/29/2007	N1⁄4
Corner <u>N¼</u>	
Marker RR Spike	
27.43' WSW to duplex N/side telephone pole	
14.66' NW to 5/8" iron pin 2' north of pavement	
87.88' ENE to duplex S/side power pole	
56.49' W to Harrison Twp. Corner (RR Spike)	

Section 4	0	
Date Established 8/29/2007		N¼NE
Corner <u>N¼ NE</u>		
Marker RR Spike		
27.87' SE to duplex W/side telephone pole (leaning north)		
18.57' SE to "+" NW corner CB (P)		
78.84' ENE to duplex S/side power pole		

Section 4		
Date Established 8/29/2007		
Corner <u>W1/4</u>		
Marker Small RR Spike		
38.83' NE to "+" SW/side steel post (2.4' above base)		
27.87' SE to 5/8" iron pin 1' east of pavement	W1⁄4	
64.34' NW to duplex SW/side power pole		
32.30' E to duplex S/side wooden corner post		

Section 5		
Date Established 8/29/2007	NW	
Corner <u>NW</u>		
Marker Iron Pin 4" below surface		
19.31' NNE to PK W/side power pole (new)		
69.73' ESE to duplex N/side telephone pole		
85.78' SW to duplex N/side power pole		
73.54' WSW to duplex NE/side telephone pole		
99.04' W to Harrison Twp. Corner		

Section 5		
Date Established 8/29/2007	N ¹ / ₄ NW	
Corner <u>N¼ NW</u>		
Marker RR Spike 1" below surface		
53.77' NE to duplex S/side power pole		
31.50' SE to "+" NW corner CB (P) (new top)		
20.80' SSE to duplex E/side telephone pole		
79.18' WSW to duplex N/side telephone pole		

Section 5	b 14 /
Date Established 8/29/2007	N1⁄4
Corner <u>N¼</u>	
Marker RR Spike 2" below surface	
87.46' WNW to PK nail S/side power pole	
64.65' WSW to duplex N/side telephone pole (leans north)	
77.52' ESE to duplex N/side telephone pole (leans north)	
80.26' W to Harrison Twp. Corner (RR Spike)	

Section 5		
Date Established 8/29/2007		
Corner <u>W¹/4</u>		
Marker Iron Pin 1" below surface		
24.34' W to duplex N/side power pole		
13.17' NE to 5/8" iron pin 1' east of pavement	W1⁄4	
13.34' SE to 5/8" iron pin 1' east of pavement		
36.35' E to mag nail N/side 12" tree		

Section 5		
Date Established 8/29/2007		
Corner <u>W1/4 SW</u>		
Marker Small RR Spike		
17.85' SW to PK nail north end 8" CMP (P)		
85.20' SW to NE corner foundation of cage house		
47.70' NE to PK nail SW/side of power pole	K w¼sw	
24.95' E to Iron Pin (property pin)		
	I	

Section 6	N 1) A <i>(</i>	
Date Established 8/29/2007	NW	
Corner <u>NW</u>		
Marker Iron Pipe 3" below surface		
29.76' NW to "+" SE corner CB (P)		
19.44' N to duplex W/side power pole		
44.32' SE to duplex N/side telephone pole		
19.86' S to iron pin 1' deep (P)		
29.84' SW to"+" NE corner CB (P)		

Section 6		
Date Established 8/29/2007	N¼NW	
Corner <u>N¼ NW</u>		
<i>Marker</i> <u>RR Spike 1" below surface</u> 26.99' NE to duplex SE/side power pole		
17.96' S to duplex N/side telephone pole		
		1

Section 6	b 14 /
Date Established 8/29/2007	N1⁄4
Corner <u>N¼</u>	
<i>Marker</i> <u>RR Spike 1" below surface</u> 81.55' ESE to duplex N/side telephone pole	
66.73' WSW to duplex N/side telephone pole	
39.95' NW to mag nail S/side 18" tree	

Section 6	
Date Established 8/29/2007	N ¹ /4NE
Corner <u>N¼ NE</u>	
Marker RR Spike 1" below surface	
17.82' S to PK nail E/side telephone pole	
17.22' NW to 5/8" iron pin 1' north of pavement	
16.77' NE to 5/8" iron pin 1' north of pavement	

Section 7	b 1) a (
Date Established 8/30/2007	NW	
Corner <u>NW</u>		
Marker RR Spike 1" below surface		
13.30' SE to 5/8" iron pin 1' south of pavement		
20.90' S to PK nail W/side of wood post		
10.63' SW to 5/8" iron pin 1' south of pavement		
78.10' ENE to duplex N/side power pole		
16.58' N to Flatrock Twp. corner (iron pin)		

Section 7	h ka z
Date Established 8/30/2007	N ¹ ⁄4
Corner <u>N¹/a</u>	
Marker RR Spike 1" below surface	
36.87' NW to duplex S/side power pole	
31.87' ESE to "+" SW corner CB (P)	
47.93' SW to mag nail NW root large tree	

Section 7	
Date Established 8/30/2007	N¼NE
Corner <u>N¼ NE</u>	
Marker RR Spike 1" below surface	
11.30' NE to 5/8" iron pin 1' north of pavement	
52.57' WSW to duplex N/side power pole	
18.83' N to duplex W/side wood post	
44.29' WNW to mag nail west end corrugated plastic drive pipe	

Section 7	
Date Established 4/19/2021	
Corner <u>W¹/4</u>	
Marker	
Searched for stone by County crew. Did not find stone.	
Found old buried fence line running N & S. (3 hr. search)	W¼
Area appeared undisturbed and feel stone is there somewhere.	
Began search midway and on line with NW corner and	
SW corner, Sec. 7, Monroe Twp.	
(Did not re-establish)	

Section 8	N 1) A <i>(</i>	
Date Established 8/30/2007	NW	
Corner <u>NW</u>		
Marker RR Spike 1" below surface		
42.46' NW to duplex S/side wood telephone post		
52.35' NNE to duplex SW/side telephone pole		
33.55' SW to duplex E/side power pole		
49.97' NE to duplex SE/side power pole		
37.97' NW to duplex SW/side power pole		

Section 8		
Date Established 8/30/2007	N ¹ / ₄ NW	
Corner <u>N¼ NW</u>		
Marker <u>RR Spike 2" below surface</u> 46.40' NW to "+" SE corner CB cover (P)		
48.20' NE to duplex NW/side wood telephone post		
52.38' SE to duplex NE/side power pole		
33.18' SW to "+" NE corner CB cover (P)		

Section 8	h k k
Date Established 8/30/2007	N1⁄4
Corner <u>N¼</u>	
Marker RR Spike	
25.85' NW to "+" SE corner CB (P)	
40.96' SE to "+" east end concrete pipe (P)	
45.31' SW to "+" west end concrete pipe (P)	
72.27' NE to duplex NW/side telephone post	

Section 8		
Date Established 8/30/2007		
Corner <u>W¹/4</u>		
Marker RR Spike 1" below surface		
15.91' NE to 5/8" iron pin 1' east of pavement		
30.30' SE to 5/8" iron pin 1' east of pavement	W1⁄4	
19.87' WSW to "+" in CMP (P)		
15.79' ESE to mag nail east end corrugated helical pipe (P)		
	_	

Section 8	[
Date Established 8/30/2007		
Corner <u>CENTER</u>		
Marker Small RR Spike		
14.70' E to duplex S/side power pole	└──── >	(
15.69' W to duplex N/side power pole	CEN	TER
34.52' NE to duplex S/side mail box post		

Section 9	N 1347	
Date Established 8/30/2007	NW	
Corner <u>NW</u>		
Marker RR Spike		
35.18' NW to "+" north end concrete pipe (P)		
38.31' NE to "+" NW corner CB lid (P)		
34.31' SW to "+" south end concrete pipe (P)		
39.04' SE to "+" NE/side CB (P)		
45.18' SE to duplex SW/side power pole		

Section 9	
Date Established 8/30/2007	N ¹ ⁄4
Corner <u>N¼</u>	
<i>Marker</i> <u>Iron Pin 6" below surface. Place small RR Spike on surface</u> 46.27' NW to "+" in center south wall of CB (P)	
45.35' ESE to "+" NW corner CB lid (P)	
39.02' SE to duplex NE/side power pole (New)	
45.04' WSW to "+" NE corner CB lid (P)	

W¼	

Section 9	
Date Established 8/30/2007	
Corner <u>CENTER</u>	
Marker Small RR Spike	
10.25' NW to 5/8" iron pin 1' west of pavement	
10.39' NE to 5/8" iron pin 1' east of pavement	CENTER
79.04' NNE to duplex W/side power pole	

<i>Section</i> 10	N 104	
Date Established 8/30/2007	NW	
Corner <u>NW</u>		
Marker RR Spike		
33.74' NW to "+" north end concrete pipe (P)		
39.10' NE to duplex W/side telephone pole		
34.60' SSW to "+" south end concrete pipe (P)		
41.90' SW to PK nail NW/side power pole		
51.58' SE to "+" NW/side CB		

<i>Section</i> <u>10</u>	
Date Established 8/30/2007	N1⁄4
Corner <u>N¹/a</u>	
Marker RR Spike	
28.90' N to duplex W/side power pole	
31.17' S to duplex E/side power pole	
19.00' SW to 5/8" iron pin 2' south of pavement	
41.65' NW to "+" SE corner concrete drive	

Section 10		1
Date Established 8/30/2007		
Corner		
Marker Small RR Spike		
23.61' ESE to "+" center north wall CB (P)		
59.11' SSW to "+" north end concrete headwall	W1⁄4	
23.00' WSW to duplex N/side power pole		
45.85' NNW to mag nail north end drive pipe		

Section 11	N NA/	
Date Established 8/30/2007	NW	
Corner <u>NW</u>		
Marker Nail/Shiner		
40.74' NNE to "+" north end concrete headwall		
47.30' NE to shiner SW/side power pole		
42.90' ESE to "+" SW corner CB lid (P)		
32.66' SW to shiner NE/side light pole		
82.69' SSW to duplex W/side power pole		

<i>Section</i> <u>11</u>	
Date Established 8/30/2007	N1⁄4
Corner <u>N¹/a</u>	
Marker RR Spike	
77.70' ENE to duplex SW/side power pole	
80.10' ESE to 30d spike SW/side power pole	
27.03' SE to duplex SW/side wood telephone post	
27.25' SSW to duplex E/side power pole (new)	

<i>Section</i> 11		
Date Established 8/30/2007		
Corner		
Marker RR Spike		
31.54' NW to "+" NW corner CB (P)		
51.77' NE to corner house foundation (126 Turkeyfoot)	W1⁄4	
31.96' NE to shiner S/side brace pole		
35.04' SE to shiner NW/side power pole		
25.19' WSW to shiner E/side light pole		

Date Established 8/30/2007 Corner CENTER Marker Iron Pin 6" below grade 6' NE & NW to mag nails 27.03' NW to 5/8" iron pin 1' north of pavement 23.70' NE to 5/8" iron pin 1' north of pavement CENTER	
Marker Iron Pin 6" below grade 6' NE & NW to mag nails 27.03' NW to 5/8" iron pin 1' north of pavement CENTER	
6' NE & NW to mag nails27.03' NW to 5/8" iron pin 1' north of pavementCENTER	
27.03' NW to 5/8" iron pin 1' north of pavement CENTER	
· · · · · · · · · · · · · · · · · · ·	
23.70' NE to 5/8" iron pin 1' north of pavement	
46.27' ESE to barge spike in conc. encasement, NW culvert wing(P)	

Section 12		
Date Established 8/30/2007	NW	
Corner <u>NW</u>		
Marker Small RR Spike 2" below surface 43.89' SW to duplex SE/side power pole		
50.66' NE to "+" in north end RCP		
48.15' NW to "+" in SE corner CB		
51.06' SE to "+" in south end RCP		

<i>Section</i> 12	b 14 /
Date Established 8/30/2007	N ¹ ⁄4
Corner <u>N¹/a</u>	
<i>Marker</i> Iron Pin 6" deep. Set Small RR Spike on surface 21.96' N to duplex W/side power pole	
27.86' NE to PK east end CMP (P)	
22.74' WSW to 5/8" iron pin 2' south of pavement	

Section 12	
Date Established 11/5/2018	NE
Corner OTHER	
<i>Marker</i> <u>Point lost in construction. Point placed with aid of GPS</u> 35.03' ESE to "X" in NW corner of catch basin (P)	
53.29' ESE to duplex in SW side of power pole	
59.91' SSW to "X" in south end of conc. pipe	
"X" is in rear center of pipe (P)	
7.92' S to NE corner, Sec. 12, Monroe Twp.	

Section 12		
Date Established 11/5/2018		NE
Corner <u>NE</u>		
Marker RR spike.		
Point lost due to construction. Point placed with aid of GPS		
48.35' SSW to "X" in middle of south end of 4-sided box (P)	_	
32.21' ESE to sawed "X" in NW side of catch basin (P)	_	
48.60' ESE to duplex in SW side of power pole	_	
98.21' SSE to "X" in NE side of catch basin (P)	_	
73.92' S to iron pin w/HC cap, NW corner, Sec. 7, Richfield Twp.	_	
7.92' N to offset RR spike	_	

Section 12	 _	
Date Established 8/30/2007		
Corner <u>W1/4</u>		
<i>Marker</i> <u>RR Spike 2" below surface</u> 48.32' NW to duplex SW/side telephone pole		
40.94' NE to "+" north end concrete pipe (P)	W1⁄4	
47.80' NE to duplex SE/side power pole		
32.60' SE to "+" south end concrete pipe (P)		
38.69' SW to "+" west end concrete pipe (P)		

Section 12	r
Date Established 8/30/2007	
Corner <u>CENTER</u>	
Marker Small RR Spike	
18.77' NNW to ³ / ₄ " dia. witness pin (P)	k
20.17' ESE to 7/8" o.d. witness pipe (P)	
22.64' WSW to 7/8" o.d. witness pipe (P)	

Section 12		
Date Established 11/9/2017		
Corner <u>F¹/4</u>		
<i>Marker</i> <u>RR Spike lost during construction. Set RR Spike by</u> one remaining tie and GPS		
49.75' NW to "X" in NW corner of culvert		E¼
44.82' ESE to 30d spike W/side power pole		
37.50' SW to "X" in SW corner of culvert		
88.80' WSW to duplex in power pole		

Section 13		
Date Established 8/30/2007	NW	
Corner <u>NW</u>		
Marker RR Spike 2" below surface		
23.60' SW to "+" top center concrete headwall (P)		
50.77' NE to "+" in north end RCP		
42.92' SE to "+" in south end RCP		

Section 13	
Date Established 8/30/2007	N1⁄4
Corner <u>N¹/a</u>	
Marker Small RR Spike 23.99' NNW to "+" west end concrete pipe (P)	_
27.51' NE to "+" east end concrete pipe (P)	
28.96' S to center USGS triangulation station tablet	
35.01' SW to "+" east end concrete headwall (P)	_
	_
	_ L

Section 13	
Date Established 8/30/2007	NE NE
Corner <u>NE</u>	
Marker RR Spike 3" below surface	
46.01' NW to center USGS Station "Taylor 2 1963" (P)	
33.99' NNW to "+" north end concrete pipe (P)	
51.57' SE to 16d spike SW/side power pole	
37.50' SSW to "+" south end concrete pipe (P)	

Section 13		
Date Established 8/30/2007		
Corner <u>W1/4</u>		
Marker RR Spike 1" below surface		
18.83' NW to 5/8" iron pin 5' west of pavement		
63.20' NE to duplex NE/side power pole (new)	W1⁄4	
22.02' SE to PK in CMP 2.5' from east end (P)		

Section 13		
Date Established 8/30/2007		
Corner <u>E¹/a</u>		
Marker Iron Pin 6" below edge of pavement 29.36' E to "+" southwest corner CB (P)		
63.64' SE to duplex NE/side power pole		E¼
36.66' NE to 5/8" iron pin 2.5' east of east edge of pavement		
64.07' S to Richfield Twp. Stone		
24.01' E to center USGS Station "Couch 194?" (buried)		

Section 14	N 1) A <i>l</i>	
Date Established 8/30/2007	NW	
Corner <u>NW</u>		
Marker Shaft of Nail		
46.96' SW to shiner NE/side power pole		
55.50' NW to "+" in east bonnet bolt		
39.26' SE to nail/shiner NW/side telephone pole		
48.32' WSW to "+" in SE corner CB lid		
28.29' SE to "+" in NE corner CB lid		

<i>Section</i> 14	
Date Established 8/30/2007	N1⁄4
Corner <u>N¹/a</u>	
Marker Iron Pin 6" below edge of pavement	
26.31' NW to 5/8" iron pin 1' north of pavement	
23.59' NE to 5/8" iron pin 1' north of pavement	

Section 14	r
Date Established 8/30/2007	
Corner <u>W¹/4 NW</u>	Kw¼NW
Marker Nail/Shiner	
30.08' ENE to shiner W/side telephone pole	
57.63' SW to duplex NE/side power pole	
75.48' SE to duplex W/side telephone pole	

<i>Section</i> <u>14</u>		1
Date Established 8/30/2007		
Corner <u>W¹/4</u>		
Marker Nail/Shiner	_	
30.05' SW to shiner NE/side power pole		
35.46' NW to duplex E/side 1st wood GR anchor assembly post	W1⁄4	
50.31' NE to shiner in SW/side telephone pole	_	
	_	

Section 14	[]
Date Established 1/7/1979	
Corner _CENTER	
Marker Iron Pipe	_
21.65' ESE to "+" north end east headwall (P) (1979 Ties)	X
9.73' SE to "+" north end west headwall (P) (1979 Ties)	CENTER
14.82' SSE to "+" south end west headwall (P) (1979 Ties)	

Section 15		
Date Established 8/30/2007	NW	
Corner <u>NW</u>		
Marker Small RR Spike		
28.88' NW to "+" north end CMP (P)		
32.92' SE to punch mark in east end CMP (P)		
21.93' SW to "+" in concrete wing (P)		
31.89' SW to spike SE/side power pole		

Section 15	
Date Established 8/30/2007	N1⁄4
Corner <u>N¹/a</u>	
Marker Rebar 8" below edge of pavement 42.17' NW to "+" center east wall CB (P)	—
40.57' SW to "+" NE corner catch basin (P)	
	<u> </u>

Section 15		
Date Established 8/30/2007		
Corner <u>W¹/4</u>		
Marker Iron Pipe		
52.86' SW to 5/8" iron pin on west ditch bank		
30.38' NE to 5/8" iron pin 1' east of east edge of pavement	W1⁄4	
32.58' SE to 5/8" iron pin 1' east of east edge of pavement		

Section 16	N 1) A /	
Date Established 9/4/2007	NW	
Corner <u>NW</u>		
Marker RR Spike		
41.65' SE to 30d spike SW/side power pole		
31.55' SE to "+" east end concrete pipe (P)		
26.46' SW to "+" south end concrete pipe (P)		
32.63' NW to "+" north end RCP (P)		
24.59' SW to "+" west end RCP (P)		

<i>Section</i> <u>16</u>	
Date Established 9/4/2007	N1⁄4
Corner <u>N¼</u>	
<i>Marker</i> <u>Small RR Spike</u> 31.63' NW to 5/8" iron pin 2' from pavement radius	-
64.57' NE to duplex N/side buried cable marker	
23.69' S to duplex E/side power pole	
77.92' NNE to duplex E/side power pole	_
	_

Section 16		
Date Established 9/4/2007		
Corner <u>W¹/4</u>		
Marker RR Spike		
19.53' ESE to "+" SE corner CB (P)		
26.62' SE to duplex S/side 15" hickory	W1⁄4	
83.15' SSW to nail/shiner SE/side power pole		
10.76' W to "+" in east wall CB (P)		

Section 17	N 13 A 7	
Date Established 9/4/2007	NW	
Corner <u>NW</u>		
Marker Iron Pin 1" below surface	_	
26.90' SE to "+" north end concrete headwall (P)		
25.37' SW to "+" north end concrete headwall (P)	_	
30.27' NW to duplex SE/side power pole	_	
48.48' SW to duplex NW/side power pole	_	

<i>Section</i> <u>17</u>	
Date Established 9/4/2007	N1⁄4
Corner <u>N¹/a</u>	
<i>Marker</i> <u>Small RR Spike</u> 54.75' WNW to duplex NE/side power pole	_
48.24' NNW to "+" north end concrete headwall (P)	
37.31' NNE to "+" center east wall CB (P)	
31.66' SE to "+" NE corner CB (P)	
24.92' SW to mag nail west end plastic tile (P)	

Section 17		
Date Established 9/4/2007		
Corner <u>W¹/4</u>		
Marker RR Spike 3" below surface		
25.35' NE to 5/8" iron pin 1' east of pavement		
26.93' SE to 5/8" iron pin 1' east of pavement	W1⁄4	
18.58' SW to PK in 24" N12 (2' east of west end)		

Section 17		
Date Established 9/4/2007		
Corner <u>CENTER</u>		
Marker Small RR Spike		
14.43' W to rivet west end CMP (P)		(
18.29' E to "+" SW corner CB	CEN	TER
15.39' SE to 5/8" iron pin 1' east of pavement		

Section 18		
Date Established 9/4/2007	NW	
Corner <u>NW</u>		
Marker Small RR Spike		
83.61' ENE to "+" SW corner CB (P)		
58.90' ESE to "+" SW corner CB (P)		
15.80' N to Flatrock Twp. Corner (iron pipe)		
20.52' S to duplex N/side power pole		

<i>Section</i> 18	
Date Established 9/4/2007	N ¹ ⁄4
Corner <u>N¹/a</u>	
<i>Marker</i> <u>Small RR Spike</u> 28.22' NW to 5/8" iron pin 0.5' north of pavement	
12.55' NE to 5/8" iron pin 0.5' north of pavement	
30.06' SW to "+" NW corner CB (P)	
28.42' SE to mag nail W/side 15" walnut	
94.61' WSW to duplex N/side power pole	

Section 19		
Date Established 9/4/2007	NW	
Corner <u>NW</u>		
Marker Small RR Spike		
28.88' N to duplex W/side power pole		
40.34' WSW to NE corner concrete base of Austermiller headstone		
5.16' N to Flatrock Twp. Corner (RR Spike)		
24.57' SE to NW upper corner concrete base Cassie Bilow headstone		

Section 19	b 4 4
Date Established 9/4/2007	N ¹ ⁄4
Corner <u>N¼</u>	
Marker Small RR Spike 19.43' NNE to duplex W/side power pole	
38.27' SSE to duplex W/side power pole	
57.50' SW to duplex NW/side power pole	

Section 20	N 1) A /	
Date Established 9/4/2007	NW	
Corner <u>NW</u>		
Marker RR Spike		
38.37' NW to "+" north end CMP (P)		
38.06' NW to PK nail SW/side power pole		
36.21' SE to "+" east end CMP (P)		
30.30' SE to PK nail NW/side power pole		
28.27' SW to "+" south end CMP (P)		

<i>Section</i> 20	
Date Established 9/4/2007	N1⁄4
Corner <u>N¼</u>	
Marker Small RR Spike	
34.92' NW to "+" NE corner CB	
28.73' SE to duplex E/side power pole (new)	
31.37' NE to 5/8" iron pin at mid radius, 3' off edge of pavement	
58.84' SW to "+" east end backwall of ag inlet	

Section 20	I	
Date Established 9/4/2007		
Corner <u>W¹/4</u>		
Marker RR Spike		
17.17' NE to 5/8" iron pin 0.5' east of pavement		
17.61' SE to 5/8" iron pin 0.5' east of pavement	W1⁄4	
24.52' WSW to PK west end plastic pipe		
56.62' W to "+" center of back wall of ag inlet		

Section 21	N 1) A /	
Date Established 9/4/2007	NW	
Corner <u>NW</u>		
Marker RR Spike 3" below surface		
28.23' SE to "+" north end headwall (P)		
35.76' SE to "+" south end headwall (P)		
27.86' SW to "+" south end headwall (P)		
18.59' SW to "+" north end headwall (P)		
38.40' NE to duplex SW/side 33" tree		

Section 21	
Date Established 9/4/2007	N1⁄4
Corner <u>N¼</u>	
<i>Marker</i> <u>PK Nail 6' south of north edge of pavement</u> 22.46' NW to "+" north end concrete pipe (P)	_
19.63' S to "+" east end concrete headwall (P)	
32.52' SW to "+" west end concrete headwall (P)	
	_
	_

Section 21		
Date Established 9/4/2007		
Corner <u>W1/4</u>		
Marker Small RR Spike		
31.83' SE to "+" NE corner CB (P)		
27.65' SW to "+" north end concrete headwall (P)	W1⁄4	
21.27' NE to 5/8" iron pin at edge of pavement		

Section 22		
Date Established 9/4/2007	NW	
Corner <u>NW</u>		
Marker RR Spike		
31.50' NW to "+" north end concrete pipe (P)		
98.30' NE to "+" west end concrete step		
27.05' SW to "+" south end concrete pipe (P)		

Section 22	
Date Established 9/4/2007	N ¹ ⁄4
Corner <u>N¹/a</u>	
<i>Marker</i> <u>Iron Pin 8" below surface, 6" south of south edge of pavement</u> 29.24' NE to 5/8" iron pin 1' north of pavement (new)	
54.17' WSW to duplex N/side power pole	
29.19' NW to 5/8" iron pin 1' north of pavement	

Section 22		
Date Established 9/4/2007		25 ± AC
Corner OTHER		
<i>Marker</i> <u>RR Spike 2" below surface</u> 25.87' NW to 5/8" iron pin 1' north of pavement		
26.62' NE to 5/8" iron pin 1' north of pavement		
42.65' SW to duplex NW/side power pole		
	u	1

<i>Section</i> 22		
Date Established 9/4/2007		
Corner <u>W1/4</u>		
Marker Iron Pin 5" below surface		
36.33' NE to 5/8" iron pin 1'east of pavement		
30.25' ESE to "+" SE corner CB (P)	W1⁄4	
29.08' SE to 5/8" iron pin 1' east of pavement		
33.95' SW to "+" south end metal drive pipe		
19.48' SW to "+" south end metal drive pipe		

Section 23		
Date Established 9/4/2007	NW	
Corner <u>NW</u>		
Marker Mag Nail		
33.32' NE to "+" in bridge abutment cap		
23.23' ESE to "+" in bridge abutment cap		
54.79' WSW to "+" in bridge abutment cap		
59.80' WNW to "+" in bridge abutment cap		

Section 23		
Date Established 9/4/2007	35± AC	
Corner OTHER		
<i>Marker</i> Iron Pin 27.76' NE to 5/8" iron pin 1' north of north edge of pavement		
27.34' NW to 5/8" iron pin 1' north of north edge of pavement		
67.5'± E to center west rail		
	1	

Section 23	[]	N 14 7
Date Established 9/4/2007		N ¹ ⁄4
Corner <u>N¼</u>		
Marker Small RR Spike		
14.36' SE to iron pin on ditch bank (P)		
14.98' SW to iron pin on ditch bank (P)		

Section 23		
Date Established 9/4/2007		
Corner <u>W1/4</u>		
Marker PK Nail/Shiner		
31.78' WNW to center R/W monument (P)		
31.68' ENE to center R/W monument (P)	W1⁄4	
29.91' E to shiner W/side telephone pole		
30.75' SSW to "+" NE/corner CB (P)		
· · · · · · · · · · · · · · · · · · ·		

Section 24		
Date Established 9/4/2007	NW	
Corner <u>NW</u>		
Marker Small RR Spike		
49.39' SE to duplex NE/side power pole (new)		
41.46' SW to "+" in west end RCP		
31.95' ESE to "+" in east end headwall		
27.33' SE to "+" in headwall		

Section 24	b 14 /
Date Established 9/4/2007	N1⁄4
Corner <u>N¹/a</u>	
Marker Small RR Spike	
25.05' NW to PK nail north end N12 (P)	
26.13' N to duplex W/side wood corner post	
105.20' SW to duplex SE/side power pole (new)	
35.89' SW to mag nail west end drive pipe (P)	
14.82' S to PK nail south end 12" N12 pipe 1' north of pipe end	

Section 24	I	
Date Established 9/4/2007		NE
Corner <u>NE</u>		
Marker RR Spike		
63.58' WNW to duplex S/side telephone pole		
48.17' NW to "+" north end concrete pipe (P)		
60.74' SE to center USGS Bench Mark "F117 1947"		
43.67' SW to "+" south end concrete pipe (P)		
27.27' NE to duplex S/side power pole		
60.85' S to Richfield Twp. Corner		

Section 24		
Date Established 9/4/2007		
Corner <u>W¹/4</u>		
Marker Iron Pin and PK Nail Northeast. Reset Iron Pin. Set Mag Nails 6' SW and NE		
21.99' W to "+" N/side concrete corner post	W1⁄4	
36.27' NW to duplex SW/side power pole		
33.32' NE to duplex NW/side power pole		
23.09' E to "+" W/side concrete corner post		
32.70' ESE to duplex SW/side power pole		

Section 24	
Date Established 9/4/2007	
Corner <u>F1/4</u>	
Marker RR Spike	
22.45' NNW to 5/8" iron pin 1' west of pavement	
25.08' SSW to 5/8" iron pin 1' west of pavement	E¼
58.38' S to Richfield Twp. Corner	
64.98' SE to duplex SW/side power pole	

Section 25	h l) A (
Date Established 9/4/2007	NW	
Corner <u>NW</u>		
Marker Nail/Shiner		
52.53' SE to shiner NW/side power pole		
38.48' SE to "+" SE corner CB (P)		
41.80' SW to "+" in center north wall CB (P)		
54.29' SW to "+" south end concrete headwall (P)		
1.88' N to nail/shiner		

Section 25		
Date Established 9/4/2007	N ¹ / ₄ NW	
Corner <u>N¼ NW</u>		
Marker Headless Nail		
61.46' ESE to "+" NW corner concrete drive (P)		
51.83' SE to nail/shiner NW/side power pole		
26.37' S to PK nail west end CMP (P)		

Section 25	
Date Established 9/4/2007	NE
Corner <u>NE</u>	
Marker Iron Pin 12" below berm	
37.05' NW to shiner SE/side power pole	
89.30' NE to duplex W/side power pole	
38.33' SE to center USGS Bench Mark "E117 1947" (P)	
27.64' SSW to "+" in curb of bridge rail	
24.96' SSW to "+" in NE wing of bridge	

Section 25		
Date Established 9/4/2007		
Corner <u>W¼</u>		
Marker Small RR Spike		
17.54' NW to 5/8" iron pin 4' west of pavement		
96.31' SSE to duplex E/side power pole	W1⁄4	
102.30' SSW to duplex E/side power pole		
16.72' SW to 5/8" iron pin 4' west of pavement		

Section 25	Ĩ	
Date Established 9/4/2007		
Corner <u>F¹/a</u>		
<i>Marker</i> <u>RR Spike at west edge of pavement, 1" below surface</u> 43.12' S to W ¹ / ₄ Post, Sec. 30, Richfield Twp.		
28.70' SE to 5/8" iron pin 1' east of pavement		E¼
56.04' SE to duplex N/side power pole		
74.23' SE to "+" NW/corner CB (P)		
69.40' SSW to "+" west end concrete pipe (P)		
52.43' WSW to mag nail N/side 10" pine tree		

Section 26		
Date Established 9/4/2007	NW	
Corner <u>NW</u>		
Marker RR Spike 2" below surface		
61.57' SSW to "+" south end concrete pipe (P)		
48.68' SW to "+" NE corner CB (P)		
43.63' SW to duplex SE/side power pole		
55.01' SE to "+" SE corner concrete base		
51.05' NE to "+" SW corner Stop sign base		
53.99' NW to "+" north end RCP (P)		

<i>Section</i> <u>26</u>	
Date Established 9/4/2007	N ¹ ⁄4
Corner <u>N¼</u>	
Marker PK Nail	
39.35' N to "+" S/side concrete anchor post	
42.75' NE to "+" center east wall CB (P)	
47.12' SW to iron pin in concrete monument (P) (bent)	

Section 26	(F	
Date Established 9/4/2007		
Corner <u>W¹/4</u>		
<i>Marker</i> <u>Nail/Shiner 1' east of west edge of pavement</u> 28.87' W to duplex N/side power pole		
36.48' E to duplex W/side wood post	W1⁄4	
34.99' ESE to "+" center south wall CB (P)		
	u	

Section 27	N 1) A /	
Date Established 9/4/2007	NW	
Corner <u>NW</u>		
Marker Headless Nail		
53.75' NW to SE corner CB (P)		
53.32' SW to duplex E/side power pole (new)		
48.22' NW to "+" NW corner concrete box (P)		
40.16' SW to "+" south end concrete wingwall (P)		

Section 27	
Date Established9/4/2007	N¼
Corner <u>N¹/a</u>	
<i>Marker</i> <u>Nail/Shiner</u> 77.79' WNW to duplex SW/side power pole	_
28.66' N to "+" SW corner CB (P)	
73.85' SW to shiner NW/side power pole	
	_

<i>Section</i> 27		
Date Established 9/4/2007		
Corner <u>W¹/4</u>		
Marker Small RR Spike		
22.78' NE to 5/8" iron pin		
20.98' SE to 5/8" iron pin	W1⁄4	
90.51' SSE to duplex NE/side buried cable marker		
49.84' SW to PK nail west end 10" CMP (P)		
35.34' WSW to duplex S/side power pole		

Section 28	N 10 4 /	
Date Established 9/5/2007	NW	
Corner <u>NW</u>		
Marker Nail/Shiner		
52.35' NE to shiner in buried cable marker		
42.62' SE to "+" east end concrete pipe (P)		
56.26' SE to shiner N/side 12" pine tree		
49.41' SW to "+" west end concrete pipe		
54.48' SW to duplex NE/side power pole		

Section 28	
Date Established 9/5/2007	N ¹ ⁄4
Corner <u>N¹/a</u>	
Marker PK Nail	
28.74' N to "+" SW corner CB (P)	
27.36' SE to "+" north end concrete headwall (P)	
27.28' S to "+" NW corner CB (P)	

Section 28		
Date Established 9/5/2007		
Corner <u>W¹/4</u>		
<i>Marker</i> <u>RR Spike 6" deep. Placed Small RR Spike on surface</u> 23.22' W to PK nail in north end 12" CMP		
24.84' SW to 5/8" iron pin 1' west of west edge of pavement	W1⁄4	
16.66' NW to 5/8" iron pin 1' west of west edge of pavement		

Section 29	N 1) A (
Date Established 9/5/2007	NW	
Corner <u>NW</u>		
Marker PK Nail		
48.87' NW to "+" north end concrete pipe (P)		
42.94' NE to nail/shiner S/side telephone pole		
50.53' SW to nail/shiner NE/side power pole		
43.52' SW to "+" south end concrete pipe (P)		
54.08' SE to "+" east end RCP (P)		

Section 29	
Date Established 9/5/2007	N1⁄4
Corner <u>N¹/a</u>	
Marker Nail/Shiner	
31.83' NW to PK nail west end 12" N12 pipe	
42.22' NE to PK nail east end 12" N12 pipe	
39.42' S to face of plastic post	
48.80' NW to "+" NE corner CB (P)	

Date Established 9/5/2007 Corner W¼ Marker RR Spike 49.83' NW to 5/8" iron pin on west ditch bank		
Marker RR Spike 49.83' NW to 5/8" iron pin on west ditch bank		
49.83' NW to 5/8" iron pin on west ditch bank		
42.84' SW to 5/8" iron pin on west ditch bank	W1⁄4	
19.26' NE to 5/8" iron pin 1' east of edge of pavement		

Section 30	N 10.07	
Date Established 9/5/2007	NW	
Corner <u>NW</u>		
Marker Nail/Shiner		
57.30' NW to "+" top concrete headwall		
51.03' N to shiner S/side power pole		
26.57' SE to "+" north end concrete headwall (P) (new)		
55.12' SW to "+" south wall CB (P)		
35.72' NNE to "+" in SW corner CB	-	

Section 30		
Date Established 9/5/2007	N ¹	4
Corner <u>N¼</u>		
Marker Nail/Shiner 41.56' NW to "+" SE corner CB (P)		
35.66' SE to PK nail north end 12" CMP (P)		
36.19' SW to "+" south end concrete pipe (P)		
44.72' S to duplex W/side wood fence post		

Section 31		
Date Established 9/5/2007	NW	
Corner <u>NW</u>		
Marker Small RR Spike		
29.16' NNE to "+" north end concrete pipe (P)		
35.45' ESE to "+" south end concrete pipe (P)		
26.75' SW to PK nail west end 12" N12 pipe		
14.30' N to Flatrock Twp. Corner (RR Spike)		

Section 31	
Date Established 9/5/2007	N ¹ ⁄4
Corner <u>N¼</u>	
<i>Marker</i> <u>RR Spike 6" deep. Set Small RR Spike on surface</u> 21.04' N to PK nail north end 12" N12 pipe	
12.83' S to PK nail south end 12" N12 pipe	
83.59' ENE to duplex N/side power pole	
16.12' NW to 5/8" iron pin 1' north of pavement	
6.00' E to offset stone (Small RR Spike)	

Section 31	
Date Established 9/5/2007	RR Spike 6' East ofN¼
Corner OTHER	
Marker Small RR Spike 6' east of corner 14.72' SW to PK nail south end 12" plastic tile	
22.35' NW to PK nail south end 12" plastic tile	
20.84' NW to 5/8" iron pin 1' north of edge of pavement	
77.81' ENE to duplex N/side power pole (new)	
6.00' W to Section Corner	

Section 31		
Date Established 9/5/2007		
Corner <u>SW</u>		
<i>Marker</i> <u>Small RR Spike</u> 59.40' WNW to shiner SE/side power pole (near ground level)		
35.65' N to shiner S/side 12" maple		
44.92' NE to shiner SW/side 15" maple		
33.95' SW to PK nail north end 18" CMP (P)		
	sw	

Section 31	
Date Established 9/5/2007	
Corner <u>S1/4</u>	
Marker Small RR Spike	
77.99' E to N ¹ / ₄ Post, Sec. 6, Marion Twp. (Small RR Spike)	
96.44' WNW to shiner E/side power pole	
25.50' NE to 5/8" iron pin 1' north of edge of pavement	
82.48' ESE to "+" NW corner concrete anchor post	
	S1⁄4

Section 32		
Date Established 9/5/2007	NW	
Corner <u>NW</u>		
Marker Small RR Spike		
42.66' NW to duplex S/side power pole		
50.90' SE to "+" east end concrete pipe (P)		
85.53' SW to duplex E/side power pole		
41.02' SW to "+" west end concrete pipe		

Section 32	
Date Established 9/5/2007	N ¹ ⁄4
Corner <u>N¹/a</u>	
Marker Small RR Spike	
15.01'NW to 5/8" iron pin 1' north of pavement	
14.43' SW to 5/8" iron pin 1' south of pavement	
72.27' WNW to duplex S/side power pole	
15.04' NE to 5/8" iron pin 1' north of pavement	

Section 32	í
Date Established 9/5/2007	
Corner <u>W¼</u> NW	K W ¹ /4NW
Marker Small RR Spike	
14.70' NW to 5/8" iron pin 3' west of pavement	
15.82' SW to 5/8" iron pin 3' west of pavement	
29.90' ESE to "+" in SE corner CB	
	—

Section 32		
Date Established 9/5/2007		
Corner <u>W1/4</u>		
MarkerRR Spike 8" deep. Set Small RR Spike on surface22.10' SE to 5/8" iron pin (new) 3' east of pavement	_	
13.37' SW to 5/8" iron pin 3' west of pavement	W1⁄4	
27.13' W to duplex S/side power pole		
13.52' WNW to "+" in concrete GR base		
42.47' NE to "+" in concrete GR base		
29.48' E to "+" NE corner CB (P)		

Section 32		1
Date Established 9/5/2007		
Corner <u>SW</u>		
Marker Small RR Spike	_	
51.04' NE to shiner S/side power pole		
65.73' E to Marion Twp. Corner (Small RR Spike)	_	
31.48' NW to 5/8" iron pin mid radius 1' off edge of pavement (P)	_	
14.76' SW to 5/8" iron pin 2' south of edge of pavement	_	
	- SW	

Section 32	
Date Established 9/5/2007	
Corner <u>S¹/4</u>	
Marker Small RR Spike	
22.85' NW to 5/8" iron pin 1' north of pavement	
31.05' N to duplex E/side meter pole	
30.12' N to shiner SE/side power pole	
26.65' SE to 5/8" iron pin 1' south of pavement	
	C1/
	574

Section 33	N 1) A /	
Date Established 9/5/2007	NW	
Corner <u>NW</u>		
Marker Small RR Spike		
27.77' WNW to "+" in NE wingwall		
39.35' NNE to duplex SE/side telephone pole		
40.24' SE to "+" east end concrete pipe (P)		
23.91' WSW to "+" in SE wingwall		
67.16' ENE to duplex west side power pole		

Section 33	
Date Established 9/5/2007	N ¹ ⁄4
Corner <u>N¹/a</u>	
Marker Small RR Spike 1" below surface	
15.12' NE to 5/8" iron pin 1' north of pavement	
12.41' SE to 5/8" iron pin 1' south of pavement	
16.10' NW to 5/8" iron pin 1' north of pavement	

Section 33	i -	
Date Established 9/5/2007		
Corner <u>W¹/4</u>		
Marker Small RR Spike		
36.92' W to duplex E/side power pole (new nail)		
20.51' W to "+" top RCP (P)	W1⁄4	
58.93' ESE to PK nail W/side power pole		
26.91' NE to 5/8" iron pin 1' east of pavement		

Section 33		
Date Established 9/5/2007		
Corner <u>SW</u>		
Marker Small RR Spike		
43.42' NW to shiner SE/side power pole		
27.11' NW to "+" north end concrete pipe (P)		
29.79' SW to "+" south end concrete pipe (P)		
31.52' E to Marion Twp. Corner (Small RR spike)		
37.35' SSE to duplex W/side south GR post	- sw	
	- 300	

Section 33	
Date Established 9/5/2007	
Corner <u>S¼</u>	
Marker Small RR Spike	
35.39' NW to shiner SE/side power pole	
18.47' NNE to "+" north end concrete pipe (P)	
21.43' S to "+" south end concrete pipe (P)	
30.58' E to North 1/2 Post, Sec. 4, Marion Twp. (Small RR Spike)	
	S ¹ /4
	574

Section 34	N 1347	
Date Established 9/5/2007	NW	
Corner <u>NW</u>		
Marker Small RR Spike		
43.64' NW to duplex SW/side power pole (new)		
46.01' SW to duplex SE/side power pole (new)		
40.04' SW to "+" south end RCP		
46.73' NW to "+" north end RCP		
63.52' SE to duplex SW/side power pole		

Section 34	h
Date Established 9/5/2007	N ¹ ⁄4
Corner <u>N¹/a</u>	
Marker Small RR Spike	
17.55' NW to 5/8" iron pin 1' north of pavement	
16.01' NE to 5/8" iron pin 1' north of pavement	
91.80' WSW to duplex N/side power pole	

Section 34	(
Date Established 9/5/2007		
Corner <u>W¹/4</u>		
Marker Small RR Spike		
73.28' NNW to duplex E/side power pole		
24.71' ESE to "+" NW corner CB (P)	W1⁄4	
13.16' WSW to "+" north end concrete headwall (P)		
	_	
	-	
	_	

Section 34		
Date Established 9/5/2007		
Corner <u>SW</u>		
Marker Small RR Spike	_	
53.50' NW to "+" SE corner CB (P)	_	
55.37' SE to shiner NW/side buried cable marker		
64.92' SE to shiner NW/side power pole		
33.22' SSE to duplex N/side power pole		
29.74' E to Marion Twp. Corner (Small RR Spike)	- sw	
	- 500	

Section 34		
Date Established 9/5/2007		
Corner <u>S¹/4</u>		
Marker Small RR Spike	_	
16.16' NE to 5/8" iron pin 2' north of pavement	_	
63.75' ESE to shiner N/side power pole	_	
15.52' S to 5/8" iron pin 1' south of pavement	_	
27.58 E to N ¹ / ₄ Post, Sec. 3, Marion Twp. (Small RR Spike)	_	
		C1/
		S¼

Section 35	N 1) A /	
Date Established 9/5/2007	NW	
Corner <u>NW</u>		
Marker Nail/Shiner		
53.79' NW to shiner SE/side telephone pole		
44.99' NW to PK north end CMP (P)		
75.40' SW to NE corner church foundation		
43.55' SE to "+" east end RCP		
38.81' SW to duplex SE/side power pole		
28.69' SW to "+" center south wall CB		

Section 35	
Date Established 9/5/2007	N ¹ ⁄4
Corner <u>N¹/a</u>	
Marker Small RR Spike	
17.57' NE to 5/8" iron pin 1' north of pavement	
14.68' SE to 5/8" iron pin (7" deep)	
19.39' SW to 5/8" iron pin 5' south of pavement	

Section 35		
Date Established 9/5/2007		
Corner <u>W¹/4</u>		
Marker Nail/Shiner		
50.82' NW to shiner SE/side power pole		
41.79' SW to 5/8" iron pin on west ditch bank	W1⁄4	
42.97' NNW to duplex 1st GR post (west side)		
43.13' NE to mag nail north end plastic tile (P)		
40.72' SE to mag nail north end plastic tile (P)		

Section 35		
Date Established 9/5/2007		
Corner <u>SW</u>		
Marker RR Spike		
44.00' NW to "+" NE wingwall		
70.59' NW to shiner SE/side power pole		
84.81' ESE to shiner NW/side buried cable marker		
60.50' ENE to shiner W/side power pole		
39.11' NW to "+" in stub wall	sw	
49.46' SW to "+" south end 4-sided box		

26.64' E to NW corner, Sec. 2, Marion Twp. (RR Spike)

Section 35	
Date Established 9/5/2007	
Corner <u>S¹/a</u>	
Marker RR Spike 1" below surface	
15.80' NE to 5/8" iron pin (new) 1' north of pavement	
55.15' SE to duplex W/side power pole	
40.63' SSE to iron pin on south ditch bank	
34.30' E to N ¹ / ₂ Post, Sec. 2, Marion Twp. (RR Spike)	
	C1/
	S ¹ ⁄4

Section 36		
Date Established 9/5/2007	NW	
Corner <u>NW</u>		
Marker Small RR Spike 37.27' NE to "+" SE corner CB (P)		
33.22' SE to "+" north end headwall (P)		
35.45' SW to "+" north end headwall (P)		
41.21' SE to duplex SW/side power pole		

Section 36	b 14 /
Date Established 9/5/2007	N1⁄4
Corner <u>N¹/a</u>	
Marker Small RR Spike	
20.80' NW to 5/8" iron pin 1' north of pavement	
19.78' NE to 5/8" iron pin 1' north of pavement	
24.40' S to "+" in face of 4" post (severely leaning)	

Section 36	
Date Established 9/5/2007	NE
Corner <u>NE</u>	
Marker Small RR Spike	
41.92' NE to PK nail SW/side power pole (new)	
55.38' SW to duplex N/side power pole	
61.29' NW to "+" north end RCP	
47.71' SW to "+" south end RCP	
42.64' S to Richfield Twp. Stone (Small RR Spike)	

Section 36		
Date Established 9/5/2007		
Corner <u>W1/4</u>		
Marker Small RR Spike		
13.68' NW to 5/8" iron pin 4' west of pavement		
29.24' E to duplex N/side power pole	W1⁄4	
21.18' SW to 5/8" iron pin 4' west of pavement		

Section 36	ſ	
Date Established 9/5/2007		
Corner <u>F¹/a</u>		
Marker Small RR Spike 1" below surface		
38.17' W to duplex N/side 24" tree		
23.80' ESE to duplex N/side power pole		E¼
87.54' SSE to "+" NW corner CB		
90.90' SSW to mag nail in 12" N12 (P)		
21.36' S to Richfield Twp. Corner (Small RR Spike)		

Section 36	1	
Date Established 9/5/2007		
Corner <u>SW</u>		
Marker Iron Pin 7' South of Pavement		
81.00' W to "+" SE bridge abutment		
72.17' WNW to "+" NE bridge abutment		
26.77' ESE to "+" NW corner CB		
80.68' SE to duplex W/side power pole		
52.45' SW to duplex SE/side power pole	sw	
39.60' E to NW corner, Sec. 1, Marion Twp. (RR Spike)	500	

Section 36	[
Date Established 9/5/2007		
Corner <u>S¹/4</u>		
Marker RR Spike 1" below surface		
103.18' WNW to duplex S/side telephone pole		
96.46' NNE to SW corner concrete foundation		
47.46' NE to duplex S/side telephone pole		
75.56' ESE to duplex N/side power pole		
19.23' E to Marion Twp. Corner (RR Spike)		S¼
		5/4

Section 36		r
Date Established 9/5/2007		
Corner <u>SE</u>		
Marker <u>Small RR Spike</u> 43.23' WNW to duplex SW/side power pole		
56.63' NNE to duplex SE/side power pole		
40.22' SE to duplex SW/side power pole		
43.53' SE to "+" NW corner CB (P)		
42.33' SW to duplex NW/side power pole		SE
31.28' SW to "+" south end concrete pipe (P)		
41.05' NW to "+" north end concrete pipe	_	