

# Richfield Township

Section \_\_\_\_\_ 1

Corner NW

Date Established 12/4/2006

Marker RR Spike

49.64' WNW to duplex S/side buried cable marker

54.22' ESE to "+" east end concrete pipe (P)

43.25' WSW to "+" east end RCP (P)

38.93' SW to duplex E/side power pole

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

NW	

Section \_\_\_\_\_ 1

Corner N<sup>1</sup>/<sub>4</sub>

Date Established 12/4/2006

Marker Small RR Spike

68.28' WNW to "+" center east wing catch basin (P)

18.27' NNW to "+" east end concrete headwall (P) (Leaning North)

16.60' SW to "+" south end cast iron pipe (P)

30.28' S to duplex W/side wood corner post

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

	N <sup>1</sup> / <sub>4</sub>

Section \_\_\_\_\_ 1

Corner NE

Date Established \_\_\_\_\_

Marker Spike

Bridge being rehabed

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

	NE

**Richfield Township**

Section \_\_\_\_\_ 1

Corner W<sup>1</sup>/<sub>4</sub>

Date Established 12/4/2006

Marker RR Spike

55.56' SE to mag nail in plastic pipe

53.62' SSW to duplex NW/side power pole

21.96' W to mag nail in plastic pipe

44.90' SSW to mag nail in plastic pipe

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

W <sup>1</sup> / <sub>4</sub>	

# Richfield Township

Section           2          

Corner   NW          

Date Established   12/5/2006          

Marker   Small RR Spike          

  66.40' ENE to center USGS Bench Mark (P) (1988)          


  38.38' SE to "+" east end concrete pipe (P)          

  49.77' SE to duplex SW/side power pole (New)          

  27.35' SW to "+" west end concrete pipe (P)          

  32.34' E to Damascus Twn. Corner          

  51.47' N to duplex SE/side power pole          



Section           2          

Corner   N¼ NW          


Date Established   7/13/1988          

Marker   RR Spike          

  35.05' NW to duplex NE/side buried cable marker          

  17.03' NE to 5/8" iron pin 3' north of pavement          

  11.79' ESE to 5/8" iron pin 3' south of pavement          



Section           2          

Corner   N¼          

Date Established   12/5/2006          


Marker   RR Spike          

  11.91' E to S¼ Post Sec 35 Damascus Twn          

  28.10' NE to "+" west end concrete headwall (P)          

  17.22' SE to "+" west end stone headwall (P)          

  36.42' SSE to duplex NW/side power pole          



**Richfield Township**

Section 2

Corner W<sup>1</sup>/<sub>4</sub> NW

Date Established 7/13/1988

Marker RR Spike


30.84' NW to PK nail in aluminum pipe (P)

15.11' NE to 5/8" iron pin 1' east of pavement

14.81' SE to 5/8" iron pin 1' east of pavement

36.37' SW to PK nail in aluminum pipe (P)

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Section 2

Corner W<sup>1</sup>/<sub>4</sub>

Date Established 12/5/2006

Marker Small RR Spike

54.30' SW to "+" north end CMP (P)

34.39' WNW to "+" north end concrete block headwall (P) (New "+")


14.56' NE to 5/8" iron pin 1' east of pavement (7/13/88)

11.76' SE to 5/8" iron pin 1' east of pavement (7/13/88)

54.26' SSW to PK nail north end CMP (P)

34.99' WSW to "+" south end concrete block headwall (P)

\_\_\_\_\_  
\_\_\_\_\_





# Richfield Township

Section \_\_\_\_\_ 4

Corner NW

Date Established 12/5/2006

Marker Small RR Spike


32.56' NW to center USGS BM "V116 1947" (P) (1988)

42.78' SSW to "+" in wing of new bridge

37.27' WSW to "+" west end bridge wing

66.81' NE to "+" center of curb wall

52' ± to Damascus Twn. corner



Section \_\_\_\_\_ 4

Corner N¼

Date Established 12/5/2006

Marker Small RR Spike


40.93' E to S¼ Post. Sec. 33. Damascus Twn.

36.44' NW to center USGS Sta. "STONER-1947" (P)

50.58' NE to saw cut at SW corner concrete monument

70.33' SE to duplex W/side power pole (New)

43.47' SSW to "+" in 1" square bar in concrete (P) (Did not locate)



Section \_\_\_\_\_ 4

Corner W¼ NW


Date Established 7/13/1988

Marker No PK Found

7.25' NW to 5/8" iron pin 1' west of pavement

18.53' NE to 5/8" iron pin 1' east of pavement

102.13' SSE to center USGS Sta. "CRONINGER-1950" (P)



**Richfield Township**

Section \_\_\_\_\_ 4

Corner W<sup>1</sup>/<sub>4</sub>

Date Established 9/9/2020

Marker Small RR Spike

22.02' NE to 5/8" iron pin 1' east of pavement (New iron pin)

26.21' E to center USGS Sta. "LONG-1950"

22.04' SE to 5/8" iron pin 1' east of pavement

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

W <sup>1</sup> / <sub>4</sub>	

# Richfield Township

Section \_\_\_\_\_ 5

Corner   NW  

Date Established   12/5/2006  

Marker   Small RR Spike  

  57.52' E to SE corner. Sec. 31. Damascus Twn.  

  67.38' SE to center USGS Sta. "BARNES-1963"  

  59.79' SE to duplex NW/side power pole  

  37.42' SW to "+" west end concrete pipe (P)  

  96.46' ENE to duplex NW/side power pole  

\_\_\_\_\_

\_\_\_\_\_

Section \_\_\_\_\_ 5

Corner   N¼  

Date Established   12/5/2006  

Marker   Small RR Spike  

  58.62' E to S¼ Post. Sec. 32. Richfield Twn.  

  32.31' SSW to "+" SE bridge wing (P)  

  29.15' SW to "+" NW bridge wing (P)  

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Section \_\_\_\_\_ 5

Corner   W¼  

Date Established   12/5/2006  

Marker   Iron Pin - 5' West of Edge of Pavement  

  Set mag nails 8' NE and SE  

  33.85' E to "+" center of concrete headwall (P)  

  24.44' SE to 5/8" iron pin at east edge of pavement  

  11.81' W to "+" chiseled in west end CMP (P)  

  39.92' NE to 5/8" iron pin at east edge of pavement (New)  

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

NW	

	N¼

W¼	



# Richfield Township

Section \_\_\_\_\_ 6

Corner   NW  

Date Established  12/5/2006 

Marker   RR Spike  

 29.59' NE to duplex SE/side telephone pole 

 44.01' SE to duplex NE/side power pole 

 42.59' SW to duplex NW/side power pole 

 68.12' NW to south corner concrete block house foundation 

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Section \_\_\_\_\_ 6

Corner   N¼  

Date Established  12/5/2006 

Marker   Small RR Spike  

 57.18" E to S¼ Post. Sec. 31. Damascus Twp. 

 27.84' NNE to "+" west end concrete headwall (P) 

 66.38' ENE to "+" east end concrete headwall (P) 

 62.78' ESE to "+" east end concrete headwall (P) 

 17.61' S to west end concrete headwall (P) 

\_\_\_\_\_

\_\_\_\_\_

Section \_\_\_\_\_ 6

Corner   W¼  

Date Established  12/5/2006 

Marker   Iron Pin  

 83.56' NNW to duplex SW/side power pole 

 30.29' SW to 5/8" iron pin 2' west of west edge pavement 

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

NW	

	N¼

W¼	

# Richfield Township

Section 7

Corner NW

Date Established 11/5/2018

Marker Canned 5/8" Iron Pin

NOTE: Check 15' offset nails NE & SE along west EP-can shift due to ditch bank sliding.

62.74' NNW to duplex SW side power pole

72.95' NNW to sawed "X" in NW corner catch basin (P)

32.71' NW to sawed "X" south end conc. pipe (center of tile) (P)

4.59' ESE to duplex west side of GR post (2nd in from south side)

46.71' ESE to sawed "X" in NE side catch basin (P)

73.92' N to NE corner Sec. 12 Monroe Twn

Section 7

Corner N<sup>1</sup>/<sub>4</sub>

Date Established 12/5/2006

Marker Iron Pin

77.60' NW to spike NE/side power pole

34.43' NNE to center hole north end CMP (P)

21.79' SSE to center hole south end CMP (P)

35.48' SW to PK west PK west end CMP (P)

Section 7

Corner W<sup>1</sup>/<sub>4</sub>

Date Established 12/5/2006

Marker Iron Pin




68.43' NNW to duplex NE/side power pole

66.97' NNW to "+" west end concrete headwall

52.86' NNW to "+" east end concrete headwall (P)

62.98' NE to spike W/side power pole

80.07' N to E<sup>1</sup>/<sub>4</sub> Post. Sec. 12. Monroe Twn.



# Richfield Township

Section \_\_\_\_\_ 8

Corner   NW  

Date Established  12/5/2006 

Marker  RR Spike 

41.59' SW to "+" south end RCP (P)

62.28' SW to duplex SE/side power pole

54.23' NW to duplex SW/side power pole

47.47' NW to "+" north end RCP (P)

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Section \_\_\_\_\_ 8

Corner   N¼  

Date Established  12/5/2006 

Marker  Small RR Spike 

40.33' NW to duplex SW/side power pole

33.28' NNE to "+" north end RCP (P)

33.32' SSE to "+" south end RCP (P)

36.10' S to USGS Sta. "AUSTERMILLER-1947" (P) (1988)

22.57' SSW to "+" NE corner catch basin (P) (New)

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Section \_\_\_\_\_ 8

Corner   W¼  

Date Established  12/5/2006 

Marker  Iron Pin 

17.48' NW to "+" top south end concrete headwall (P)

38.06' W to center USGS Sta. "WILLIAM-1947" (P) (1988)

17.48' NW to "+" south end concrete headwall (P)

28.07' NE to "+" SE corner concrete headwall (P)

28.28' E to "+" W/side concrete anchor post

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

NW	

	N¼

W¼	

# Richfield Township

Section \_\_\_\_\_ 9

Corner   NW  

Date Established  12/6/2006 

Marker   RR Spike  

 37.73' NW to center hex bolt top 96" CMP (P) 

 36.83' NE to center USGS Sta. "SHIDLER-1947" (P) (1988) 

 56.53' NE to duplex W/side power pole 

 32.72' SE to "+" east end headwall (P) 

 38.56' SW to center hex bolt top 96" CMP (P) 

\_\_\_\_\_

\_\_\_\_\_

Section \_\_\_\_\_ 9

Corner   N¼  

Date Established  12/6/2009 

Marker   RR Spike  

 24.17' N to "+" west end concrete pipe (P) 

 33.99' NE to "+" east end concrete pipe (P) 

 41.34' SSE to center USGS Sta. "SPANGLER-1959" (P) 

 57.88' SE to duplex N/side power pole 

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Section \_\_\_\_\_ 9

Corner   W¼  

Date Established  9/9/2020 

Marker   Placed RR Spike over PK Nail  

 71.43' NW to duplex E/side power pole (New) 

 19.12' NE to 5/8" iron pin at east edge of pavement 

 20.44' SE to 5/8" iron pin at east edge of pavement 

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

NW	

	N¼

W¼	



# Richfield Township

Section 10

Corner NW

Date Established 12/6/2006

Marker Nail/Shiner

50.36' NNW to "+" north end CMP (P)


47.97' NE to shiner SW/side power pole

55.33' NE to center USGS Sta. "GILES-1950" (P) (1988)

54.05' SW to shiner NE/side power pole

41.00' SW to "+" NE corner catch basin (P)

35.34' SW to "+" south end CMP (P)



Section 10

Corner N¼

Date Established 12/6/2006

Marker Small RR Spike


29.85' S to "+" SE corner concrete box (P)

32.68' SW to "+" SW corner concrete box (P)

43.90' NW to "+" NW corner concrete box (P)

41.75' N to "+" NE corner concrete box (P)

48.34' SW to duplex NW/side power pole



Section 10

Corner W¼

Date Established 12/6/2006


Marker Nail/Shiner

38.12' NE to PK nail north end CMP (P)

28.79' ESE to PK nail south end CMP (P)

20.00' WSW to mag nail north end plastic pipe (P)

47.10' SW to mag nail south end plastic pipe (P)



# Richfield Township

Section 11

Corner NW

Date Established 12/6/2006

Marker Small RR Spike

57.68' NW to duplex S/side power pole

53.07' NNE to duplex W/side buried cable marker

59.65' ENE to center USGS BM "Y116-1947" (P) (1988)

40.05' SE to center USGS Sta. "LYTLE-1947" (P) (1988)

52.30' SW to duplex NW/side power pole

41.91' SW to "+" south end RCP (P)

48.95' SE to "+" east end RCP (P)

NW	

Section 11

Corner N¼

Date Established 12/6/2006

Marker Iron Pin & Top of Stone

53.35' NW to "+" SE corner catch basin (P)

43.95' SW to duplex E/side power pole

40.84' SW to "+" center concrete headwall (P)

21.18' N to PK nail 1' south of north edge of pavement (1988)

	N¼

Section 11

Corner W¼

Date Established 12/6/2006

Marker Small RR Spike

37.83' W to duplex N/side power pole

32.78' W to "+" south end block headwall (P)

31.75' E to center USGS Sta. "BRETZ-1947" (P) (1988)

72.34' SSW to "+" west end CMP (P)

38.06' NW to "+" north end headwall (P)

W¼	

# Richfield Township

Section \_\_\_\_\_ 12

Corner   NW  

Date Established  12/6/2006 

Marker  Small RR Spike 

 56.58' SW to duplex SE/side power pole 

 50.88' WSW to "+" west end concrete pipe (P) 

 68.39' NW to duplex E/side power pole 

 52.23' ESE to "+" in east end concrete pipe (P) 

 52.28' SE to duplex SW/side power pole 

\_\_\_\_\_

\_\_\_\_\_

Section \_\_\_\_\_ 12

Corner   N¼  

Date Established  12/6/2006 

Marker  Iron Pin 

 35.34' NW to 5/8" iron pin 3' north of pavement 

 51.32' NNE to duplex W/side power pole 

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Section \_\_\_\_\_ 12

Corner   NE  

Date Established  12/6/2006 

Marker  RR Spike 

 39.53' WSW to "+" NW end of headwall 

 40.27' NNE to duplex SE/side telephone pole 

 53.20' ESE to duplex N/side power pole 

 15.29' SE to "+" NW corner headwall 

 36.42' SSW to "+" south end of headwall 

 66.87' SW to duplex W/side power pole 

\_\_\_\_\_

\_\_\_\_\_

NW	

	N¼

	NE



**Richfield Township**

**Section** 12

**Corner** W<sup>1</sup>/<sub>4</sub>

**Date Established** 12/6/2006

**Marker** RR Spike


28.79' W to duplex in wood post

24.80' NE to 5/8" iron pin at east edge of pavement

24.30' SE to 5/8" iron pin at east edge of pavement

89.84' SSE to duplex W/side power pole

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



**Section** 12

**Corner** E<sup>1</sup>/<sub>4</sub>

**Date Established** 12/6/2006

**Marker** RR Spike

26.40' NW to 5/8" iron pin (New)


6.37' E to small hole in center of concrete monument (P) (1988)

9.52' SE to small hole in center of concrete monument (P) (1988)

30.27' SW to 5/8" iron pin (New)

12.80' E to 5/8" iron pin

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



# Richfield Township

Section 13

Corner NW

Date Established 12/6/2006

Marker Small RR Spike

40.52' NW to duplex NE/side brace pole

86.40' NNE to duplex W/side power pole

49.40' ESE to "+" NE end of headwall (P)

46.41' SE to "+" in headwall

35.54' SW to "+" in headwall

36.49' WSW to "+" NW end of headwall

65.82' SE to duplex NE/side power pole

NW	

Section 13

Corner N¼

Date Established 12/6/2006

Marker Iron Pin

86.28' ENE to duplex S/side power pole

58.48' SE to iron pin on south ditch bank

39.73' SW to iron pin on south ditch bank

	N¼

Section 13

Corner NE

Date Established 12/6/2006

Marker Iron Pin - 3" Below Surface

25.25' NE to "+" north end concrete pipe (P)

26.20' SE to "+" NE corner concrete slab (P)

44.34' SSE to "+" south end concrete pipe (P)

43.30' WSW to "+" west end concrete pipe

	NE

**Richfield Township**

Section 13

Corner W<sup>1</sup>/<sub>4</sub>

Date Established 12/6/2006


Marker Small RR Spike

47.45' SW to duplex SE/side power pole

46.60' NE to mag nail SW/side 12" tree

10.43' NW to 5/8" iron pin at west edge of pavement

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Section 13

Corner E<sup>1</sup>/<sub>4</sub>


Date Established 12/6/2006

Marker RR Spike

13.73' NW to center of concrete monument (P)

11.83' WSW to center of concrete monument (P)

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



# Richfield Township

Section \_\_\_\_\_ 14

Corner   NW  

Date Established   2/18/2006  

Marker   RR Spike  

  43.00' NW to duplex SE/side buried cable marker  

  34.15' SE to "+" east end CMP (P)  

  44.10' SSE to duplex NE/side power pole  

  67.41' SSW to duplex NW/side power pole  

  35.58' SW to "+" west end CMP (P)  

\_\_\_\_\_

\_\_\_\_\_

Section \_\_\_\_\_ 14

Corner   N¼  

Date Established   2/18/2006  

Marker   Re-set Iron Pin from PKs 10' NW & NE  

  25.12' NW to 5/8" iron pin 1' north of pavement  

  25.86' NE to 5/8" iron pin 1' north of pavement  

  22.12' SSE to "+" in west end concrete pipe (P)  

  59.48' SE to duplex SW/side power pole  

\_\_\_\_\_

\_\_\_\_\_

Section \_\_\_\_\_ 14

Corner   W¼  

Date Established   2/18/2006  

Marker   Small RR Spike  

  46.18' NW to duplex NE/side power pole  

  32.95' SE to PK nail NW/side power pole  

  49.94' SSE to "+" center west wall of catch basin (P)  

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

NW	

	N¼

W¼	

# Richfield Township

Section 15

Corner NW

Date Established 2/18/2006

Marker Nail/Shiner

37.61' NE to center USGS BM "H116 1947" (P)

36.03' SE to "+" east end concrete pipe (P)

27.42' SW to "+" west end concrete pipe (P)

48.27' SW to nail/shiner NE/side power pole

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Section 15

Corner N¼

Date Established 2/18/2006

Marker Iron Pin

PK Nails 10' NE & NW

34.92' SSE to PK nail east side of power pole

22.60' SSW to sawed "+" SE corner concrete box (P)

53.10' NNW to sawed "+" NE corner concrete box (P)

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Section 15

Corner W¼

Date Established 2/18/2006

Marker Nail/Shiner

25.10' W to "+" in concrete headwall (P)

32.11' NW to "+" in concrete headwall (P)

50.65' NW to shiner SE/side power pole (Leaning)




22.16' ESE to "+" east end concrete pipe (P)

42.76' WSW to center USGS Sta. "FULLER 1947" (P)

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



# Richfield Township

Section \_\_\_\_\_ 16

Corner   NW  

Date Established   2/18/2006  

Marker   RR Spike  

  34.83' WNW to SW corner bridge banister  

  16.14' NW to SE corner bridge banister  

  72.58' NNE to duplex W/side power pole (New)  

  69.07' ENE to duplex W/side power pole  

  15.94' SW to NE corner bridge banister  

  43.28' WSW to center USGS Sta. "RICHARD 2"  

NW	

Section \_\_\_\_\_ 16

Corner   N¼  

Date Established   2/18/2006  

Marker   RR Spike  

  41.63' WNW to PK nail west end CMP (P)  

  22.47' NW to map nail east end corrugated plastic (P)  

  49.31' NNE to "+" in concrete slab (1988)  

  14.37' NE to 5/8" iron pin at edge of pavement  

  11.94' SE to 5/8" iron pin at edge of pavement  

	N¼

Section \_\_\_\_\_ 16

Corner   W¼  

Date Established   2/18/2006  

Marker   Set small RR Spike over RR Spike  

  32.37' W to "+" in 4" aluminum pipe (P)  

  70.89' NNE to map nail SW/side 27" maple  

  19.43' NE to 5/8" iron pin 1' east of pavement  

  21.50' SE to 5/8" iron pin 1' east of pavement  

W¼	

**Richfield Township**


**Section** 17

**Corner** NW

**Date Established** 2/18/2006

**Marker** Small RR Spike

- 56.17' NW to duplex NE/side power pole
- 39.52' WSW to duplex NW/side power pole
- 46.42' SE to magnail in plastic pipe (P)
- 44.29' SW to "+" south end concrete pipe (P)
- 39.72' NW to "+" north end concrete pipe (P)




**Section** 17

**Corner** N¼

**Date Established** 2/18/2006

**Marker** Small RR Spike

- 49.54' WNW to mag nail SE/side 24' maple
- 30.53' NE to mag nail north end plastic pipe
- 34.71' SSE to mag nail south end plastic pipe
- 49.73' SE to mag nail east end plastic pipe




**Section** 17

**Corner** N¼ NE

**Date Established** 7/21/1988

**Marker** RR Spike

- 37.81' N to duplex W/side wood anchor post
- 17.41' SE to 5/8" iron pin at south edge of pavement
- 21.11' SW to 5/8" iron pin at south edge of pavement



**Richfield Township**

Section 17

Corner W<sup>1</sup>/<sub>4</sub>

Date Established 2/18/2006

Marker Stone - had moved 0.3' west from PKs 15' NE & SE

Set 5/8" Iron Pin from PKs. (Use Iron Pin, not Stone)

Ton of Iron Pin is 0.2' below ton of Stone

28.19' NE to 5/8" iron pin 3' east of pavement (P) (Bent)

28.88' SE to 5/8" iron pin 3' east of pavement (P) (Bent)

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

W <sup>1</sup> / <sub>4</sub>	



**Richfield Township**

**Section** \_\_\_\_\_ 18

**Corner** \_\_\_\_\_ NW \_\_\_\_\_

**Date Established** 2/18/2006

**Marker** \_\_\_\_\_ Iron Pin \_\_\_\_\_

Set new Mag Nails 10' NE & SE \_\_\_\_\_

58.42' NNW to "+" south end concrete pipe (P) \_\_\_\_\_

56.88' NE to spike SW/side power pole \_\_\_\_\_

53.92' SE to mag nail east end plastic pipe (P) \_\_\_\_\_

84.31' ENE to duplex S/side power pole \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**Section** \_\_\_\_\_ 18

**Corner** \_\_\_\_\_ N<sup>1</sup>/<sub>4</sub> \_\_\_\_\_

**Date Established** 2/18/2006

**Marker** \_\_\_\_\_ RR Spike \_\_\_\_\_

19.52' NW to 5/8" iron pin at north edge of pavement (New) \_\_\_\_\_

29.11' NNE to "+" north end concrete pipe (P) \_\_\_\_\_

33.01' ESE to 5/8" iron pin at south edge of pavement (New) \_\_\_\_\_

19.99' SSE to "+" south end concrete pipe (P) \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**Section** \_\_\_\_\_ 18

**Corner** \_\_\_\_\_ W<sup>1</sup>/<sub>4</sub> \_\_\_\_\_

**Date Established** 2/18/2006

**Marker** \_\_\_\_\_ Iron Pin \_\_\_\_\_

64.87' NNE to center USGS Sta "COUCH-1948" (P) (1988) \_\_\_\_\_

26.42' ENE to duplex S/side power pole \_\_\_\_\_

27.13' SE to 5/8" iron pin 1' east of edge of pavement (Bent) \_\_\_\_\_




30.08' E to iron pin (P) \_\_\_\_\_

69.01' NNW to mag nail west end plastic pipe \_\_\_\_\_

70.17' NNE to sawed "+" SW corner catch basin (P) \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



# Richfield Township

Section 19

Corner NW

Date Established 2/18/2006

Marker Small RR Spike

35.00' NW to "+" south end concrete pipe (P)

81.15' NNE to map nail S/side power pole (New)

60.26' ENE to center USGS BM "F117 1947" (P) (1988)

58.18' ENE to "+" NW corner catch basin (P)

23.65' SW to "+" north end concrete headwall (P)

84.40' ENE to duplex S/side power pole

NW	

Section 19

Corner N¼

Date Established 2/19/2006

Marker Small RR Spike

47.43' SW to "+" south end concrete pipe (P)

30.46' SSE to "+" in concrete base (P)

49.85' NW to "+" SE corner catch basin (P)

	N¼

Section 19

Corner W¼

Date Established 2/18/2006

Marker Small RR Spike

58.45' N to E¼ Post Sec 24 Monroe Twn (1979)

32.63' NNW to 5/8" iron pin at west edge of pavement

16.36' SSW to 5/8" iron pin at west edge of pavement

26.30' E to duplex S/side power pole

40.04' W to duplex N/side power pole

W¼	

# Richfield Township

Section 20

Corner NW

Date Established 2/19/2006

Marker RR Spike

43.93' NW to north end concrete nine (P)

46.07' NE to duplex NW/side telephone pole (New)

47.83' SW to "+" south end concrete nine (P)

46.80' NE to center USGS Sta. "SCHOOL 1950" (P) (1988)

(Left RR spike over monument for magnetic locators)

41.20' SE to PK nail in center concrete headwall

47.27' NW to duplex SE/side telephone pole

NW	

Section 20

Corner N¼

Date Established 2/19/2006

Marker RR Spike

29.36' N to duplex E/side power pole

34.94' NE to "+" SW corner catch basin (P)

34.05' SE to "+" south end concrete nine (P)

	N¼

Section 20

Corner W¼

Date Established 2/19/2006

Marker Iron Pin

35.43' E to USGS Sta "SIEGRED-1950" (P) (1988)

24.84' SW to PK nail west end CMP (P)

36.40' NE to iron pin 1' east of pavement

31.95' SE to iron pin 1' east of pavement

W¼	

**Richfield Township**

**Section** 21

**Corner** NW

**Date Established** 2/19/2006

**Marker** RR Spike

40.33' NE to PK nail SW/side telephone pole


39.01' SE to "+" NE corner catch basin (P)

43.40' SW to "+" south end 90" RCP (P)

47.25' NW to duplex SE/side power pole

41.93' NW to "+" north end concrete pipe (P)

40.85' NE to "+" SE corner catch basin (P)



**Section** 21

**Corner** N¼

**Date Established** 2/19/2006


**Marker** RR Spike

27.17' NW to "+" SW corner sloned riser

33.28' N to center Sta. "ALVAH 1947" (P)

14.50' S to mag nail south end plastic pipe (P)

75.23' WNW to duplex S/side power pole



**Section** 21

**Corner** N¼ NE

**Date Established** 7/21/1988

**Marker** RR Spike


21.69' NW to 5/8" iron pin at north edge pavement

51.13' N to duplex W/side 33" manle

35.06' NNE to duplex W/side power pole

30.01' N to property pin

31.76' S to duplex W/side power pole



**Richfield Township**

Section 21

Corner W<sup>1</sup>/<sub>4</sub>

Date Established 2/19/2006

Marker Small RR Spike

28.29' E to center Sta. "JOHN-1950" (P) (1988)

55.37' SE to duplex W/side power pole

33.11' SW to mag nail west end plastic pipe (P)

28.62' E to duplex S/side power pole

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

W <sup>1</sup> / <sub>4</sub>	

# Richfield Township

Section 22

Corner NW

Date Established 2/19/2006

Marker Nail/Shiner


41.73' SE to nail/shiner NW/side power pole

45.38' SW to nail/shiner NE/side power pole

45.47' SE to mag nail east end plastic pipe (P)

45.44' SW to mag nail west end plastic pipe (P)

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_



Section 22

Corner N<sup>1</sup>/<sub>4</sub> NW

Date Established 2/19/2006

Marker RR Spike


20.88' NW to 5/8" iron pin at north edge of pavement

23.35' N to "+" SW corner catch basin (P)

22.70' NE to 5/8" iron pin at north edge of pavement

26.83' NNE to duplex W/side telephone pole

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_



Section 22

Corner N<sup>1</sup>/<sub>4</sub>

Date Established 2/19/2006

Marker Small RR Spike

17.50' S to "+" in concrete wing


30.81' NE to duplex SE/side telephone pole

78.57' SE to duplex SW/side power pole

27.87' SSE to "+" south end CMP (P)

19.80' NNE to "+" north end CMP (P)

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_



**Richfield Township**

Section 22

Corner N<sup>1</sup>/<sub>4</sub> NE

Date Established 2/19/2006


Marker Small RR Spike

13.97' NE to iron pin 1' north of pavement

13.38' S to iron pin 1' south of pavement

51.96' SE to duplex NW/side power pole

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Section 22

Corner W<sup>1</sup>/<sub>4</sub>

Date Established 2/19/2006

Marker Nail/Shiner


33.19' NW to "+" south end metal pipe (P)

47.87' NNW to "+" north end metal pipe

92.59' SW to nail/shiner NE/side power pole

24.20' E to mag nail north end plastic pipe (P)

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



# Richfield Township

Section \_\_\_\_\_ 23

Corner   NW  

Date Established   2/19/2006  

Marker   Small RR Spike  

  50.35' NW to mag nail north end plastic pipe (P)  

  46.26' SW to mag nail south end plastic pipe (P)  


  40.86' SE to duplex NE/side power pole  

  68.37' SW to duplex NW/side power pole  

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



Section \_\_\_\_\_ 23

Corner   N¼ NW  

Date Established   2/19/2006  

Marker   Small RR Spike  

  27.54' N to bolt at base of concrete corner post  

  24.88' NNE to duplex SE/side telephone pole  


  18.97' SE to 5/8" iron pin at south edge of pavement  

  17.09' SW to 5/8" iron pin at south edge of pavement  

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



Section \_\_\_\_\_ 23

Corner   N¼  

Date Established   2/19/2006  

Marker   Small RR Spike  

  80.18' WNW to duplex S/side telephone pole  

  80.57' ENE to duplex S/side telephone pole  


  27.58' S to iron pipe in base of concrete anchor post  

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_





**Richfield Township**

Section 23

Corner N<sup>1</sup>/<sub>4</sub> NE

Date Established 2/19/2006

Marker Small RR Spike


39.56' WNW to duplex SE/side telephone pole

83.18' ESE to duplex NW/side power pole

19.79' SE to 5/8" iron pin at south edge of pavement

18.43' SW to 5/8" iron pin at south edge of pavement

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Section 23

Corner W<sup>1</sup>/<sub>4</sub>

Date Established 2/19/2006

Marker Iron Pin - 1' west of pavement


23.44' WNW to "+" east end CMP (P)

26.46' NE to 5/8" iron pin at east edge of pavement (New)

23.10' SE to 5/8" iron pin at east edge of pavement

32.27' SE to duplex SW/side power pole

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



# Richfield Township

Section \_\_\_\_\_ 24

Corner   NW  

Date Established   2/19/2006  

Marker   Small RR Spike  

  39.65' NW to duplex NE/side telephone pole  

  32.91' NW to "+" NE corner catch basin (P)  

  77.99' ENE to duplex N/side brace pole  

  38.16' SE to duplex SW/side telephone pole  

  35.60' SW to duplex SE/side power pole  

\_\_\_\_\_

\_\_\_\_\_

Section \_\_\_\_\_ 24

Corner   N¼  

Date Established   2/19/2006  

Marker   RR Spike  

  18.11' NW to 5/8" iron pin at north edge of pavement  

  102.19' ENE to duplex SE/side power pole  

  18.73' SSE to "+" NE corner catch basin (P)  

  9.51' SW to 5/8" iron pin at south edge of pavement  

\_\_\_\_\_

\_\_\_\_\_

Section \_\_\_\_\_ 24

Corner   NE  

Date Established   2/19/2006  

Marker   RR Spike  

  74.34' WNW to "+" SE corner catch basin (P)  

  57.10' NW to duplex NE/side power pole  

  23.10' SE to "+" east end concrete pipe  

  71.30' WSW to "+" NE corner catch basin (P)  

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

NW	

	N¼

	NE

**Richfield Township**

Section 24

Corner W<sup>1</sup>/<sub>4</sub>

Date Established 2/19/2006

Marker RR Spike


75.05' NNW to duplex NE/side power pole

31.72' NE to 5/8" iron pin 1' east of pavement

26.25' SE to 5/8" iron pin 1' east of pavement

69.59' SSE to duplex NE/side telephone pole

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Section 24

Corner E<sup>1</sup>/<sub>4</sub>

Date Established 2/19/2006


Marker Small RR Spike

17.69' NW to 5/8" iron pin at west edge 16' pavement

6.78' E to 5/8" iron pin at east edge 16' pavement

17.00' SW to 5/8" iron pin at west edge 16' pavement

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



**Richfield Township**

**Section** 25

**Corner** NW

**Date Established** 2/20/2006

**Marker** RR Spike

- 63.80' NNW to duplex SW/side power pole
- 54.15' NNW to "+" in center concrete headwall (P)
- 55.09' NNE to shiner S/side telephone pole
- 67.92' SSE to duplex SW/side telephone pole
- 58.35' SSW to duplex NW/side power pole

NW	

**Section** 25

**Corner** N¼

**Date Established** 2/20/2006

**Marker** Nail/Shiner

- 49.22' NW to "+" SE corner catch basin (P)
- 97.32' S to NW corner of concrete foundation
- 44.42' SW to "+" south end concrete pipe (P)
- 45.62' NNE to duplex E/side power pole

	N¼

**Section** 25

**Corner** NE

**Date Established** 2/20/2006

**Marker** Small RR Spike

- 46.78' NW to "+" NE corner catch basin (P)
- 74.63' NNE to "+" north end concrete pipe (P)
- 83.25' NNE to shiner SW/side telephone pole
- 32.32' SE to "+" NE corner catch basin (P)
- 90.90' SSE to shiner N/side power pole
- 62.38' SW to nail/shiner NE/side power pole

	NE

**Richfield Township**

Section 25

Corner W<sup>1</sup>/<sub>4</sub>

Date Established 2/20/2006

Marker Small RR Spike


22.19' NW to iron pin at edge of pavement

22.87' NE to iron pin at edge of pavement

41.15' SW to PK nail NE/side power pole

33.10' SW to mag nail south end plastic pipe

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Section 25

Corner E<sup>1</sup>/<sub>4</sub>

Date Established 2/20/2006

Marker Iron Pin - Found Stone 0.55' west of Iron Pin

Found PK's 12' NE and SE of Iron Pin

Ties are to Iron Pin (True Point)


44.49' NE to "+" south end concrete drainage structure (P)

73.89' SW to duplex SE/side power pole (P)

45.95' SE to duplex NE/side power pole (P)

21.05' NE to mag nail in plastic pipe (P)

\_\_\_\_\_  
\_\_\_\_\_



# Richfield Township

Section 26

Corner NW

Date Established 2/20/2006

Marker Nail/Shiner

52.35' NW to center USGS BM "A-117 1947" (1988)

48.78' NW to duplex SW/side brace pole

34.62' SE to "+" in center headwall

43.73' SE to "+" south end concrete headwall

51.81' SW to duplex NW/side power pole

49.58' NW to "+" NW corner catch basin

33.34' SW to "+" west end concrete pole (P)

NW	

Section 26

Corner N<sup>1</sup>/<sub>4</sub>

Date Established 5/21/2014

Marker Small RR Spike

37.81' NE to "x" in SW corner conc. catch basin

46.49' S to map nail in 24" maple tree

64.34' SW to duplex SE/side power pole

	N <sup>1</sup> / <sub>4</sub>

Section 26

Corner W<sup>1</sup>/<sub>4</sub>

Date Established 2/20/2006

Marker Small RR Spike

25.19' NW to "+" east end concrete headwall (P)

36.57' SW to duplex N/side power pole

23.39' SW to "+" south end concrete headwall (P)

27.31' SE to "+" east end CMP (P)

W <sup>1</sup> / <sub>4</sub>	

**Richfield Township**

Section 26

Corner CENTER

Date Established 2/20/2006

Marker Iron Pin


38.52' N to "+" in concrete slab

21.89' N to duplex W/side power pole (New)

44.94' SE to mag nail in plastic pipe (P)

18.13' S to mag nail in plastic pipe (P)

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



# Richfield Township

Section 27

Corner NW

Date Established 2/20/2006

Marker Nail/Shiner

57.92' NW to "+" north end concrete pipe (P)

50.22' NE to "+" SW corner "Traffic" man hole

47.40' SW to "+" SE corner "Traffic" man hole (P)

66.06' SW to "+" south end concrete pipe (P)

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

NW	

Section 27

Corner N<sup>1</sup>/<sub>4</sub>

Date Established 2/28/2006

Marker Iron Pin - Reset

36.18' NW to 5/8" iron pin at north edge pavement (P)

37.68' NE to 5/8" iron pin at north edge pavement (P)

20.52' SE to 5/8" iron pin on ditch bank (P)

28.84' SW to 5/8" iron pin on ditch bank (P)

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

	N <sup>1</sup> / <sub>4</sub>

Section 27

Corner W<sup>1</sup>/<sub>4</sub>

Date Established 2/20/2006

Marker Nail/Shiner

22.88' NE to SE corner of north banister

55.55' SSW to "+" east end concrete pipe (P)

16.95' WSW to NE corner of south banister

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

W <sup>1</sup> / <sub>4</sub>	



# Richfield Township

Section \_\_\_\_\_ 28

Corner   NW  

Date Established   2/20/2006  

Marker   Nail/Shiner  

  52.37' NW to shiner SE/side telephone pole  

  34.46' NW to "+" north end concrete headwall (P)  

  54.11' NE to "+" USGS BM "C-117 1947" (P)  

  68.95' ENE to shiner SW/side telephone pole  

  57.01' SSE to shiner NW/side power pole  

  33.33' SW to "+" in concrete headwall  

NW	

Section \_\_\_\_\_ 28

Corner   N¼  

Date Established   2/20/2006  

Marker   Nail/Shiner  

  39.28' NW to "+" west end concrete pipe (P)  

  27.36' NNW to "+" east end concrete pipe (P)  

  42.20' N to center Sta. "BENEIN 1947" (P)  

  64.38' SW to duplex SE/side power pole  

	N¼

Section \_\_\_\_\_ 28

Corner   W¼  

Date Established   2/20/2006  

Marker   Iron Pin  

  45.22' SSE to duplex NE/side power pole (P) (New)  

  21.62' SSW to "+" in concrete wing (P)  

  8.44' SW to "+" in concrete wing (P)  

W¼	

# Richfield Township

Section 29

Corner NW

Date Established 2/20/2006

Marker Nail/Shiner

53.00 NW to shiner SE/side telephone pole

55.93' NE to center USGS BM "B-117 1948"

28.35' WSW to "+" west end concrete parant

50.03' SE to shiner NE/side power pole

36.68' NW to "+" north end concrete headwall (P)

49.68' SE to "+" east end concrete pipe (P)

NW	

Section 29

Corner N¼

Date Established 2/20/2006

Marker Nail/Shiner

39.65' NE to "+" west end concrete headwall (P)

48.30' ESE to "+" east end concrete headwall (P)

37.19' ESE to "+" west end concrete headwall (P)

52.11' SW to duplex NW/side power pole

47.13' S to center Sta. "IMBROCK 1947"

	N¼

Section 29

Corner W¼

Date Established 2/20/2006

Marker Iron Pin

10" below edge of pavement at west edge of pavement

32.92' NE to 5/8" iron pin 3' east of pavement

23.74' SE to 5/8" iron pin 3' east of pavement

W¼	

# Richfield Township

Section \_\_\_\_\_ 30

Corner   NW  

Date Established   2/20/2006  

Marker   Nail/Shiner  

  31.54' NNW to "+" in concrete curb of banister  

  51.50' NNE to center USGS BM "E 117 1947" (P) (1988)  

  44.28' SE to "+" east end concrete headwall (P)  

  54.42' SE to shiner N/side power pole  

  20.66' SW to "+" in concrete curb of banister  

  35.22' NNE to "+" in north wing of bridge  

  47.57' NE to "+" in NE corner catch basin (P)  

NW	

Section \_\_\_\_\_ 30

Corner   N¼  

Date Established   2/20/2006  

Marker   Nail/Shiner  

  35.68' NNW to "+" NW corner catch basin (P)  

  57.71' SE to duplex NW/side power pole  

  25.59' SSW to "+" south end RCP (P)  

  30.53' NE to near corner metal mail box post  

	N¼

Section \_\_\_\_\_ 30

Corner   W¼  

Date Established   2/20/2006  

Marker   RR Spike at west edge of pavement  

  30.90' ESE to duplex N/side power pole  

  37.94' SE to "+" NW corner catch basin (P)  

  28.65' SW to "+" west end 8" concrete pipe (P)  

W¼	

# Richfield Township

Section 31

Corner NW

Date Established 2/28/2006


Marker Small RR Spike

25.87' WNW to "+" south end of RCP (P)

79.83' NNE to PK nail SW/side power pole

40.47' SE to PK nail east end plastic pipe (P)

25.59' SW to PK nail in plastic pipe at ditch bank (P)



Section 31

Corner OTHER

Date Established 2/28/2006


Marker Iron Pin

28.09' N to "+" SE corner catch basin (P)

32.01' NE to 5/8" iron pin 1' north of pavement (P)

37.47' E to iron pin at N¼ Post

57.12' E to map nail in plastic tile (P)



Section 31

Corner N¼

Date Established 2/28/2006


Marker Iron Pin

44.28' WNW to "+" SE corner catch basin (P)

33.83' NW to 5/8" iron pin 1' north of pavement (P)

37.47' W to iron pin

19.88' E to map nail in plastic tile (P)



**Richfield Township**

Section 31

Corner W<sup>1</sup>/<sub>4</sub>

Date Established 2/28/2006


Marker Small RR Spike

21.40' N to E<sup>1</sup>/<sub>4</sub> Post. Sec. 36. Monroe Twp.

22.71' NE to PK nail W/side power pole

66.82' SSE to "+" NW corner catch basin

35.06' SW to mag nail in plastic tile (P)



Section 31

Corner SW

Date Established 8/30/2006

Marker Small RR Spike

40.18' SE to duplex SW/side power pole

42.35' SW to duplex NW/side power pole


43.22' NW to duplex SW/side power pole

56.63' NE to duplex SE/side power pole

43.51' SE to "+" NW corner catch basin (P)

31.28' SW to "+" south end RCP (P)

41.05' NW to "+" north end RCP (P)



Section 31

Corner S<sup>1</sup>/<sub>4</sub> (1905 Su)

Date Established 8/30/2006

Marker Small RR Spike


37.00' ENE to duplex SE/side telephone pole

45.75' SE to "+" north side iron corner post

51.35' SW to duplex NW/side power pole

39.87' E to S<sup>1</sup>/<sub>4</sub> Stone (1907 Survey- Vol. 3. Pg. 134)

44.82' ENE to 5/8" iron pin at north edge of pavement



**Richfield Township**

**Section** 31

**Corner** S<sup>1</sup>/<sub>4</sub> (1907 Su

**Date Established** 8/30/2006

**Marker** RR Spike

28.84' NW to duplex SE/side telephone pole


11.59' NE to 5/8" iron pin at edge of pavement

33.38' S to "+" north side iron corner post

85.02' SW to duplex NW/side power pole

39.87' W to S<sup>1</sup>/<sub>4</sub> Stone (1905 Survey - Vol. 3, Pg. 112)

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



# Richfield Township

Section 32

Corner NW

Date Established 2/28/2006

Marker Small RR Spike

51.43' NW to "+" in north end RCP (P)

39.14' NE to PK nail SW/side power pole

38.99' SE to mag nail in plastic tile (P)

40.67' SW to "+" south end RCP (P)

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

NW	

Section 32

Corner N¼

Date Established 2/28/2006

Marker Iron Pine

25.07' NW to 5/8" iron pin 1' north of pavement

27.90' N to center of iron pine (P)

26.81' NE to 5/8" iron pin 1' north of pavement

46.18' NE to duplex SE/side power pole

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

	N¼

Section 32

Corner W¼

Date Established 2/28/2006

Marker Small RR Spike

29.10' E to nail/shiner S/side wood corner post

45.58' SE to "+" north end agriculture structure (P)

19.36' SW to mag nail west end plastic tile (P)

87.22' S to PK nail NW/side power pole

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

W¼	

**Richfield Township**

Section 32

Corner SW

Date Established 8/30/2006

Marker RR Spike

31.71' S to duplex west side power pole


27.11' SW to "+" concrete headwall (P)

43.02' NW to "+" north end RCP (P)

54.92' NE to "+" SE corner catch basin

32.63' E to NW corner. Sec. 5. Bartlow Twp.

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Section 32

Corner S¼

Date Established 8/30/2006

Marker RR Spike

25.02' NW to PK nail west end CMP (P)


24.84' N to "+" on high point of witness stone

18.75' NNE to PK nail east end CMP (P)

70.48' ESE to duplex north side power pole

26.53' E to N¼ post Sec. 5. Bartlow Twp.

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_





# Richfield Township

Section 33

Corner NW

Date Established 2/28/2006


Marker Small RR Spike

22.19' NW to SE corner of north banister

36.84' NE to duplex S/side power pole

33.97' SE to "+" east end concrete pipe (P)

18.27' SW to "+" south end SE wingwall (P)



Section 33

Corner OTHER

Date Established 2/28/2006

Marker RR Spike

108.40' E to N¼ Post. Sec. 33 (1979)


18.47' NW to 5/8" iron pin at north edge pavement

18.30' NE to 5/8" iron pin at north edge pavement

13.64' ESE to 5/8" iron pin at south edge pavement

35.48' SE to duplex E/side wood post

33.65' SW to duplex NW/side wood post



Section 33

Corner N¼

Date Established 2/28/2006


Marker Small RR Spike

18.72' NE to 1" iron pipe 1' north of pavement

12.97' ESE to 5/8" iron pin 1' south of pavement

9.20' WSW to 5/8" iron pin 1' south of pavement

30.00' N to capped iron pin (P)



**Richfield Township**

Section 33

Corner W<sup>1</sup>/<sub>4</sub>


Date Established 2/28/2006

Marker Small RR Spike

15.47' NW to 5/8" iron pin 1' west of pavement

13.01' NE to 5/8" iron pin 1' east of pavement

77.92' SSE to duplex W/side power pole (New)



Section 33

Corner SW

Date Established 8/30/2006

Marker RR Spike

40.45' WNW to "+" east end concrete banister

73.32' NE to duplex south side power pole. NEW


57.50' ESE to "+" east end conc. pipe (P)

55.05' ESE to duplex SW/side power pole

19.92' E to NW corner. Sec. 5. Bartlow Twp.

60.42' ENE to mag nail north end CMP (P)

51.08' SW to duplex west side of east post of church sign



Section 33

Corner S<sup>1</sup>/<sub>4</sub>

Date Established 8/30/2006


Marker RR Spike

9.75' NW to 5/8" iron pin 0.5' north of pavement

24.77' NE to 5/8" iron pin 0.5' north of pavement

60.78' ESE to duplex N/side of power pole

17.36' E to N<sup>1</sup>/<sub>4</sub> Post. Sec. 4. Bartlow Twp.



# Richfield Township

Section \_\_\_\_\_ 34

Corner   NW  

Date Established   2/28/2006  

Marker   Nail/Shiner  

  43.96' NW to shiner SE/side power pole  

  51.37' NE to shiner SW/side walnut tree  

  34.72' SE to "+" east end RCP (P)  

  28.85' SW to "+" west end RCP (P)  

  40.14' NE to "+" SW corner catch basin (P)  

\_\_\_\_\_

\_\_\_\_\_

Section \_\_\_\_\_ 34

Corner   N¼  

Date Established   2/28/2006  

Marker   Small RR Spike  

  22.37' NE to iron pin  

  22.05' NW to iron pin  

  75.37' SW to PK nail NE/side power pole  

  47.59' S to "+" east end agriculture inlet (P)  

\_\_\_\_\_

\_\_\_\_\_

Section \_\_\_\_\_ 34

Corner   W¼  

Date Established   2/28/2006  

Marker   Monument Box  

  Center punched box from straddles  

  38.04' WNW to "+" north end concrete wing (P)  

  45.52' ENE to "+" north end concrete wing (P)  




  50.55' SE to "+" south end concrete wing (P)  

  43.13' SW to "+" south end concrete wing (P)  

  82.18' NNE to duplex SE/side power pole  

\_\_\_\_\_

\_\_\_\_\_



**Richfield Township**

Section 34

Corner SW

Date Established 8/30/2006

Marker Placed Small RR Spike - No point found.

Re-established corner from witness ties.

29.70' NW to "+" SE corner metal frame of catch basin grate (P)

58.73' NW to nail/shiner SE/side of power pole


87.18' ENE to shiner west side of telephone pole

72.94' ESE to duplex north side of power pole

35.47' SW to "+" SW corner catch basin (P)

17.72' E to NW corner Sec. 3, Bartlow Twp.

45.87' SSW to duplex east side of power pole



Section 34

Corner S¼

Date Established 8/30/2006

Marker RR Spike


16.61' E to N¼ Post. Sec. 3, Bartlow Twp.

34.42' N to duplex W/side power pole

28.45' SSW to duplex E/side power pole

53.65' ENE to duplex SE/side power pole

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



**Richfield Township**

**Section** \_\_\_\_\_ 35

**Corner** \_\_\_\_\_ NW

**Date Established** 8/12/2005


**Marker** \_\_\_\_\_ Small RR Spike

\_\_\_\_\_ 40.32' SE to sawed "+" east end RCP

\_\_\_\_\_ 38.63' SW to sawed "+" west end RCP

\_\_\_\_\_ 38.45' NE to duplex SE/side power pole

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



**Section** \_\_\_\_\_ 35

**Corner** \_\_\_\_\_ N<sup>1</sup>/<sub>4</sub>

**Date Established** 2/28/2006


**Marker** \_\_\_\_\_ Iron Pin

\_\_\_\_\_ 32.80' N to near face 4" iron pipe

\_\_\_\_\_ 25.52' S to duplex W/side 12" oak tree

\_\_\_\_\_ 54.95' NE to duplex SE/side power pole

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



**Section** \_\_\_\_\_ 35

**Corner** \_\_\_\_\_ W<sup>1</sup>/<sub>4</sub>

**Date Established** 2/28/2006

**Marker** \_\_\_\_\_ Small RR Spike


\_\_\_\_\_ 15.45' NNW to 5/8" iron pin 0.5' west of pavement

\_\_\_\_\_ 17.47' E to 5/8" iron pin 1' east of pavement

\_\_\_\_\_ 17.12' SSW to 5/8" iron pin 1' west of pavement

\_\_\_\_\_ 28.01' E to duplex S/side power pole

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



**Richfield Township**

Section 35

Corner SW

Date Established 8/30/2006

Marker RR Spike

17.16' E to NW corner. Sec. 2, Bartlow Twp.

84.42' ENE to duplex SW/side cable marker

52.52' SE to duplex N/side power pole (NEW)

31.22' SSW to duplex E/side brace pole

27.11' NNW to 5/8" iron pin 0.5' NW of edge of pavement radius

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Section 35

Corner S<sup>1</sup>/<sub>4</sub>

Date Established 5/31/2012

Marker Small RR Spike

45.77' ESE to "+" in SW wingwall

128.86' ENE to "+" in NE wingwall

111.46' NE to "+" in northerly corner of bridge



\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



**Richfield Township**

**Section** \_\_\_\_\_ 36

**Corner** \_\_\_\_\_ NW \_\_\_\_\_

**Date Established** 2/28/2006

**Marker** \_\_\_\_\_ Small RR Spike \_\_\_\_\_

38.51' NW to duplex NE/side power pole

45.67' NW to mas nail north end plastic tile (P)

40.80' NE to duplex SE/side telephone pole

45.58' SW to mas nail south end plastic tile (P)

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**Section** \_\_\_\_\_ 36

**Corner** \_\_\_\_\_ N¼ \_\_\_\_\_

**Date Established** 2/28/2006

**Marker** \_\_\_\_\_ Small RR Spike \_\_\_\_\_

30.13' NNW to "+" north end RCP (P)

16.93' NE to 5/8" iron pin at north edge of pavement

15.64' SE to 5/8" iron pin at south edge of pavement

26.40' SSW to "+" south end RCP (P)

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**Section** \_\_\_\_\_ 36

**Corner** \_\_\_\_\_ NE \_\_\_\_\_

**Date Established** 2/28/2006

**Marker** \_\_\_\_\_ Small RR Spike \_\_\_\_\_

38.90' NW to duplex NE/side power pole

46.71' NW to "+" north end RCP (P)

50.09' NE to "+" east end RCP (P)

36.65' SE to nail/shiner N/side buried cable marker

52.61' SW to "+" south end RCP (P)

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

NW	

	N¼

	NE

**Richfield Township**

Section 36

Corner W<sup>1</sup>/<sub>4</sub>


Date Established 2/28/2006

Marker Small RR Spike

62.95' NNW to duplex NE/side power pole

43.81' SE to "+" NE corner catch basin (P) (New)

75.14' NE to mag nail S/side hickory tree




Section 36

Corner E<sup>1</sup>/<sub>4</sub>

Date Established 2/28/2006

Marker Iron Pin washed out by erosion

Found PK's 12' NE and SE



Section 36

Corner SW

Date Established 2/28/2006

Marker Small RR Spike

40.10' NW to duplex SW/side power pole

31.37' NW to "+" north end 66" CMP (P)


103.83' NE to SW corner brick veneer house

46.60' SE to duplex W/side sign post

30.44' SW to PK south end 66" CMP

39.13' SW to PK NE/side power pole

10.56' E to NW corner. Sec. 1. Bartlow Twn.





**Richfield Township**

Section 36

Corner S<sup>1</sup>/<sub>4</sub>

Date Established 12/8/2006

Marker RR Spike - 3" below surface


5.28' E to N<sup>1</sup>/<sub>4</sub> Post. Sec. 1. Bartlow Twp.

68.60' WNW to duplex NE/side power pole

18.67' NW to 5/8" iron pin 6' north of pavement

9.80' SW to iron pin 6' south of edge of pavement

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Section 36

Corner SE

Date Established 0/26/2006

Marker Small RR Spike

41.73' NW to "+" north end RCP (P)

49.71' NE to duplex SE/side power pole

69.54' SE to duplex SW/side power pole

42.13' SW to south end RCP (P)

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

