

Richfield Township

Section _____ 1

Corner NW

Date Established 12/4/2006

Marker RR Spike

49.64' WNW to duplex S/side buried cable marker

54.22' ESE to "+" east end concrete pipe (P)

43.25' WSW to "+" east end RCP (P)

38.93' SW to duplex E/side power pole

NW	

Section _____ 1

Corner N¹/₄

Date Established 12/4/2006

Marker Small RR Spike

68.28' WNW to "+" center east wing catch basin (P)

18.27' NNW to "+" east end concrete headwall (P) (Leaning North)

16.60' SW to "+" south end cast iron pipe (P)

30.28' S to duplex W/side wood corner post

	N ¹ / ₄

Section _____ 1

Corner NE

Date Established _____

Marker Spike

Bridge being rehabed

	NE

Richfield Township

Section _____ 1

Corner W¹/₄

Date Established 12/4/2006

Marker RR Spike

55.56' SE to mag nail in plastic pipe

53.62' SSW to duplex NW/side power pole

21.96' W to mag nail in plastic pipe

44.90' SSW to mag nail in plastic pipe

W ¹ / ₄	

Richfield Township

Section 2

Corner NW

Date Established 12/5/2006

Marker Small RR Spike

 66.40' ENE to center USGS Bench Mark (P) (1988)


 38.38' SE to "+" east end concrete pipe (P)

 49.77' SE to duplex SW/side power pole (New)

 27.35' SW to "+" west end concrete pipe (P)

 32.34' E to Damascus Twn. Corner

 51.47' N to duplex SE/side power pole



Section 2

Corner N¼ NW


Date Established 7/13/1988

Marker RR Spike

 35.05' NW to duplex NE/side buried cable marker

 17.03' NE to 5/8" iron pin 3' north of pavement

 11.79' ESE to 5/8" iron pin 3' south of pavement



Section 2

Corner N¼

Date Established 12/5/2006


Marker RR Spike

 11.91' E to S¼ Post Sec 35 Damascus Twn

 28.10' NE to "+" west end concrete headwall (P)

 17.22' SE to "+" west end stone headwall (P)

 36.42' SSE to duplex NW/side power pole



Richfield Township

Section 2

Corner W¹/₄ NW

Date Established 7/13/1988


Marker RR Spike

30.84' NW to PK nail in aluminum pipe (P)

15.11' NE to 5/8" iron pin 1' east of pavement

14.81' SE to 5/8" iron pin 1' east of pavement

36.37' SW to PK nail in aluminum pipe (P)



Section 2

Corner W¹/₄

Date Established 12/5/2006

Marker Small RR Spike

54.30' SW to "+" north end CMP (P)


34.39' WNW to "+" north end concrete block headwall (P) (New "+")

14.56' NE to 5/8" iron pin 1' east of pavement (7/13/88)

11.76' SE to 5/8" iron pin 1' east of pavement (7/13/88)


54.26' SSW to PK nail north end CMP (P)

34.99' WSW to "+" south end concrete block headwall (P)




Richfield Township

Section _____ 3
Corner _____ NW
Date Established _____ 12/5/2006
Marker _____ State Monument Box on Surface




Section _____ 3
Corner _____ N¼
Date Established _____ 12/5/2006
Marker _____ Small RR Spike

30.87' E to S¼ Post. Sec. 34. Damascus Twp.
18.41' NW to 5/8" iron pin 3' north of pavement (1988)
38.86' NNE to "+" in large stone (15"x15"x15") (P)
33.16' SSE to duplex W/side power pole
39.36' NNE to duplex W/side power pole



Section _____ 3
Corner _____ W¼
Date Established _____ 5/21/2014
Marker _____ Small RR Spike

50.30' W to mag nail in west end corrugated plastic pipe
33.45' NE to "x" in SE corner conc. catch basin
56.74' NE to nail/shiner in SW side power pole



Richfield Township

Section _____ 4

Corner NW

Date Established 12/5/2006

Marker Small RR Spike


32.56' NW to center USGS BM "V116 1947" (P) (1988)

42.78' SSW to "+" in wing of new bridge

37.27' WSW to "+" west end bridge wing

66.81' NE to "+" center of curb wall

52' ± to Damascus Twn. corner



Section _____ 4

Corner N¼

Date Established 12/5/2006

Marker Small RR Spike


40.93' E to S¼ Post. Sec. 33. Damascus Twn.

36.44' NW to center USGS Sta. "STONER-1947" (P)

50.58' NE to saw cut at SW corner concrete monument

70.33' SE to duplex W/side power pole (New)

43.47' SSW to "+" in 1" square bar in concrete (P) (Did not locate)



Section _____ 4

Corner W¼ NW


Date Established 7/13/1988

Marker No PK Found

7.25' NW to 5/8" iron pin 1' west of pavement

18.53' NE to 5/8" iron pin 1' east of pavement

102.13' SSE to center USGS Sta. "CRONINGER-1950" (P)



Richfield Township

Section _____ 4

Corner W¹/₄

Date Established 12/5/2006

Marker Small RR Spike

21.94' NE to 5/8" iron pin 1' east of pavement (New iron pin)

26.10' E to center USGS Sta. "LONG-1950"

21.90' SE to 5/8" iron pin 1' east of pavement

W ¹ / ₄	

Richfield Township

Section 5

Corner NW

Date Established 12/5/2006

Marker Small RR Spike

57.52' E to SE corner. Sec. 31. Damascus Twn.

67.38' SE to center USGS Sta. "BARNES-1963"

59.79' SE to duplex NW/side power pole

37.42' SW to "+" west end concrete pipe (P)

96.46' ENE to duplex NW/side power pole

NW	

Section 5

Corner N¼

Date Established 12/5/2006

Marker Small RR Spike

58.62' E to S¼ Post. Sec. 32. Richfield Twn.

32.31' SSW to "+" SE bridge wing (P)

29.15' SW to "+" NW bridge wing (P)

	N¼

Section 5

Corner W¼

Date Established 12/5/2006

Marker Iron Pin - 5' West of Edge of Pavement

Set mag nails 8' NE and SE

33.85' E to "+" center of concrete headwall (P)

24.44' SE to 5/8" iron pin at east edge of pavement

11.81' W to "+" chiseled in west end CMP (P)

39.92' NE to 5/8" iron pin at east edge of pavement (New)

W¼	

Richfield Township

Section _____ 6

Corner NW

Date Established 12/5/2006

Marker RR Spike

 29.59' NE to duplex SE/side telephone pole

 44.01' SE to duplex NE/side power pole

 42.59' SW to duplex NW/side power pole

 68.12' NW to south corner concrete block house foundation

Section _____ 6

Corner N¼

Date Established 12/5/2006

Marker Small RR Spike

 57.18" E to S¼ Post. Sec. 31. Damascus Twp.

 27.84' NNE to "+" west end concrete headwall (P)

 66.38' ENE to "+" east end concrete headwall (P)

 62.78' ESE to "+" east end concrete headwall (P)

 17.61' S to west end concrete headwall (P)

Section _____ 6

Corner W¼

Date Established 12/5/2006

Marker Iron Pin

 83.56' NNW to duplex SW/side power pole

 30.29' SW to 5/8" iron pin 2' west of west edge pavement

NW	

	N¼

W¼	

Richfield Township

Section 7

Corner NW

Date Established 11/5/2018

Marker Canned 5/8" Iron Pin

NOTE: Check 15' offset nails NE & SE along west EP-can shift due to ditch bank sliding.

62.74' NNW to duplex SW side power pole

72.95' NNW to sawed "X" in NW corner catch basin (P)

32.71' NW to sawed "X" south end conc. pipe (center of tile) (P)

4.59' ESE to duplex west side of GR post (2nd in from south side)

46.71' ESE to sawed "X" in NE side catch basin (P)

73.92' N to NE corner Sec. 12 Monroe Twn

Section 7

Corner N¹/₄

Date Established 12/5/2006

Marker Iron Pin

77.60' NW to spike NE/side power pole

34.43' NNE to center hole north end CMP (P)

21.79' SSE to center hole south end CMP (P)

35.48' SW to PK west PK west end CMP (P)

Section 7

Corner W¹/₄

Date Established 12/5/2006

Marker Iron Pin




68.43' NNW to duplex NE/side power pole

66.97' NNW to "+" west end concrete headwall

52.86' NNW to "+" east end concrete headwall (P)

62.98' NE to spike W/side power pole

80.07' N to E¹/₄ Post. Sec. 12. Monroe Twn.



Richfield Township

Section _____ 8

Corner NW

Date Established 12/5/2006

Marker RR Spike

 41.59' SW to "+" south end RCP (P)

 62.28' SW to duplex SE/side power pole

 54.23' NW to duplex SW/side power pole

 47.47' NW to "+" north end RCP (P)

Section _____ 8

Corner N¼

Date Established 12/5/2006

Marker Small RR Spike

 40.33' NW to duplex SW/side power pole

 33.28' NNE to "+" north end RCP (P)

 33.32' SSE to "+" south end RCP (P)

 36.10' S to USGS Sta. "AUSTERMILLER-1947" (P) (1988)

 22.57' SSW to "+" NE corner catch basin (P) (New)

Section _____ 8

Corner W¼

Date Established 12/5/2006

Marker Iron Pin

 17.48' NW to "+" top south end concrete headwall (P)

 38.06' W to center USGS Sta. "WILLIAM-1947" (P) (1988)

 17.48' NW to "+" south end concrete headwall (P)

 28.07' NE to "+" SE corner concrete headwall (P)

 28.28' E to "+" W/side concrete anchor post

NW	

	N¼

W¼	

Richfield Township

Section _____ 9

Corner NW

Date Established 12/6/2006

Marker RR Spike

 37.73' NW to center hex bolt top 96" CMP (P)

 36.83' NE to center USGS Sta. "SHIDLER-1947" (P) (1988)

 56.53' NE to duplex W/side power pole

 32.72' SE to "+" east end headwall (P)

 38.56' SW to center hex bolt top 96" CMP (P)

Section _____ 9

Corner N¼

Date Established 12/6/2009

Marker RR Spike

 24.17' N to "+" west end concrete pipe (P)

 33.99' NE to "+" east end concrete pipe (P)

 41.34' SSE to center USGS Sta. "SPANGLER-1959" (P)

 57.88' SE to duplex N/side power pole

Section _____ 9

Corner W¼

Date Established 12/6/2006

Marker PK Nail on Surface

 71.43' NW to duplex E/side power pole (New)

 19.12' NE to 5/8" iron pin at east edge of pavement

 20.44' SE to 5/8" iron pin at east edge of pavement

NW	

	N¼

W¼	

Richfield Township

Section _____ 9

Corner _____ W¹/₄ SW

Date Established 7/14/1988


Marker _____ Canned Iron Pin

_____ 31.30' NE to 5/8" iron pin 1' east of pavement

_____ 26.90' E to duplex S/side power pole

_____ 26.91' ESE to center USGS Sta. "FLORENCE-1950" (P)

_____ 16.37' SW to PK nail west end CMP (P)



Richfield Township

Section 10

Corner NW

Date Established 12/6/2006

Marker Nail/Shiner

50.36' NNW to "+" north end CMP (P)


47.97' NE to shiner SW/side power pole

55.33' NE to center USGS Sta. "GILES-1950" (P) (1988)

54.05' SW to shiner NE/side power pole

41.00' SW to "+" NE corner catch basin (P)

35.34' SW to "+" south end CMP (P)



Section 10

Corner N¼

Date Established 12/6/2006

Marker Small RR Spike


29.85' S to "+" SE corner concrete box (P)

32.68' SW to "+" SW corner concrete box (P)

43.90' NW to "+" NW corner concrete box (P)

41.75' N to "+" NE corner concrete box (P)

48.34' SW to duplex NW/side power pole



Section 10

Corner W¼

Date Established 12/6/2006


Marker Nail/Shiner

38.12' NE to PK nail north end CMP (P)

28.79' ESE to PK nail south end CMP (P)

20.00' WSW to mag nail north end plastic pipe (P)

47.10' SW to mag nail south end plastic pipe (P)



Richfield Township

Section 11

Corner NW

Date Established 12/6/2006

Marker Small RR Spike

57.68' NW to duplex S/side power pole

53.07' NNE to duplex W/side buried cable marker

59.65' ENE to center USGS BM "Y116-1947" (P) (1988)

40.05' SE to center USGS Sta. "LYTLE-1947" (P) (1988)

52.30' SW to duplex NW/side power pole

41.91' SW to "+" south end RCP (P)

48.95' SE to "+" east end RCP (P)

NW	

Section 11

Corner N¼

Date Established 12/6/2006

Marker Iron Pin & Top of Stone

53.35' NW to "+" SE corner catch basin (P)

43.95' SW to duplex E/side power pole

40.84' SW to "+" center concrete headwall (P)

21.18' N to PK nail 1' south of north edge of pavement (1988)

	N¼

Section 11

Corner W¼

Date Established 12/6/2006

Marker Small RR Spike

37.83' W to duplex N/side power pole

32.78' W to "+" south end block headwall (P)

31.75' E to center USGS Sta. "BRETZ-1947" (P) (1988)

72.34' SSW to "+" west end CMP (P)

38.06' NW to "+" north end headwall (P)

W¼	

Richfield Township

Section 12

Corner NW

Date Established 12/6/2006

Marker Small RR Spike

56.58' SW to duplex SE/side power pole

50.88' WSW to "+" west end concrete pipe (P)

68.39' NW to duplex E/side power pole

52.23' ESE to "+" in east end concrete pipe (P)

52.28' SE to duplex SW/side power pole

Section 12

Corner N¼

Date Established 12/6/2006

Marker Iron Pin

35.34' NW to 5/8" iron pin 3' north of pavement

51.32' NNE to duplex W/side power pole

Section 12

Corner NE

Date Established 12/6/2006

Marker RR Spike

39.53' WSW to "+" NW end of headwall

40.27' NNE to duplex SE/side telephone pole

53.20' ESE to duplex N/side power pole

15.29' SE to "+" NW corner headwall

36.42' SSW to "+" south end of headwall

66.87' SW to duplex W/side power pole

NW	

	N¼

	NE

Richfield Township

Section 12

Corner W¹/₄

Date Established 12/6/2006


Marker RR Spike

28.79' W to duplex in wood post

24.80' NE to 5/8" iron pin at east edge of pavement

24.30' SE to 5/8" iron pin at east edge of pavement

89.84' SSE to duplex W/side power pole



Section 12

Corner E¹/₄

Date Established 12/6/2006

Marker RR Spike


26.40' NW to 5/8" iron pin (New)

6.37' E to small hole in center of concrete monument (P) (1988)

9.52' SE to small hole in center of concrete monument (P) (1988)

30.27' SW to 5/8" iron pin (New)

12.80' E to 5/8" iron pin



Richfield Township

Section 13

Corner NW

Date Established 12/6/2006

Marker Small RR Spike

40.52' NW to duplex NE/side brace pole

86.40' NNE to duplex W/side power pole

49.40' ESE to "+" NE end of headwall (P)

46.41' SE to "+" in headwall

35.54' SW to "+" in headwall

36.49' WSW to "+" NW end of headwall

65.82' SE to duplex NE/side power pole

NW	

Section 13

Corner N¼

Date Established 12/6/2006

Marker Iron Pin

86.28' ENE to duplex S/side power pole

58.48' SE to iron pin on south ditch bank

39.73' SW to iron pin on south ditch bank

	N¼

Section 13

Corner NE

Date Established 12/6/2006

Marker Iron Pin - 3" Below Surface

25.25' NE to "+" north end concrete pipe (P)

26.20' SE to "+" NE corner concrete slab (P)

44.34' SSE to "+" south end concrete pipe (P)

43.30' WSW to "+" west end concrete pipe

	NE

Richfield Township

Section 13

Corner W¹/₄


Date Established 12/6/2006

Marker Small RR Spike

47.45' SW to duplex SE/side power pole

46.60' NE to mag nail SW/side 12" tree

10.43' NW to 5/8" iron pin at west edge of pavement



Section 13


Corner E¹/₄

Date Established 12/6/2006

Marker RR Spike

13.73' NW to center of concrete monument (P)

11.83' WSW to center of concrete monument (P)



Richfield Township

Section _____ 14

Corner NW

Date Established 2/18/2006

Marker RR Spike

 43.00' NW to duplex SE/side buried cable marker

 34.15' SE to "+" east end CMP (P)

 44.10' SSE to duplex NE/side power pole

 67.41' SSW to duplex NW/side power pole

 35.58' SW to "+" west end CMP (P)

Section _____ 14

Corner N¼

Date Established 2/18/2006

Marker Re-set Iron Pin from PKs 10' NW & NE

 25.12' NW to 5/8" iron pin 1' north of pavement

 25.86' NE to 5/8" iron pin 1' north of pavement

 22.12' SSE to "+" in west end concrete pipe (P)

 59.48' SE to duplex SW/side power pole

Section _____ 14

Corner W¼




Date Established 2/18/2006

Marker Small RR Spike

 46.18' NW to duplex NE/side power pole

 32.95' SE to PK nail NW/side power pole

 49.94' SSE to "+" center west wall of catch basin (P)



Richfield Township

Section _____ 15

Corner NW

Date Established 2/18/2006

Marker Nail/Shiner

 37.61' NE to center USGS BM "H116 1947" (P)

 36.03' SE to "+" east end concrete pipe (P)

 27.42' SW to "+" west end concrete pipe (P)

 48.27' SW to nail/shiner NE/side power pole

Section _____ 15

Corner N¼

Date Established 2/18/2006

Marker Iron Pin

 PK Nails 10' NE & NW

 34.92' SSE to PK nail east side of power pole

 22.60' SSW to sawed "+" SE corner concrete box (P)

 53.10' NNW to sawed "+" NE corner concrete box (P)

Section _____ 15

Corner W¼

Date Established 2/18/2006

Marker Nail/Shiner




 25.10' W to "+" in concrete headwall (P)

 32.11' NW to "+" in concrete headwall (P)

 50.65' NW to shiner SE/side power pole (Leaning)

 22.16' ESE to "+" east end concrete pipe (P)

 42.76' WSW to center USGS Sta. "FULLER 1947" (P)



Richfield Township

Section _____ 16

Corner NW

Date Established 2/18/2006

Marker RR Spike

 34.83' WNW to SW corner bridge banister

 16.14' NW to SE corner bridge banister

 72.58' NNE to duplex W/side power pole (New)

 69.07' ENE to duplex W/side power pole

 15.94' SW to NE corner bridge banister

 43.28' WSW to center USGS Sta. "RICHARD 2"

NW	

Section _____ 16

Corner N¼

Date Established 2/18/2006

Marker RR Spike

 41.63' WNW to PK nail west end CMP (P)

 22.47' NW to mag nail east end corrugated plastic (P)

 49.31' NNE to "+" in concrete slab (1988)

 14.37' NE to 5/8" iron pin at edge of pavement

 11.94' SE to 5/8" iron pin at edge of pavement

	N¼

Section _____ 16

Corner W¼

Date Established 2/18/2006

Marker Set small RR Spike over RR Spike

 32.37' W to "+" in 4" aluminum pipe (P)

 70.89' NNE to mag nail SW/side 27" maple

 19.43' NE to 5/8" iron pin 1' east of pavement

 21.50' SE to 5/8" iron pin 1' east of pavement

W¼	

Richfield Township

Section 17

Corner NW

Date Established 2/18/2006

Marker Small RR Spike


56.17' NW to duplex NE/side power pole

39.52' WSW to duplex NW/side power pole

46.42' SE to magnail in plastic pipe (P)

44.29' SW to "+" south end concrete pipe (P)

39.72' NW to "+" north end concrete pipe (P)



Section 17

Corner N¼

Date Established 2/18/2006


Marker Small RR Spike

49.54' WNW to mag nail SE/side 24' maple

30.53' NE to mag nail north end plastic pipe

34.71' SSE to mag nail south end plastic pipe

49.73' SE to mag nail east end plastic pipe



Section 17

Corner N¼ NE


Date Established 7/21/1988

Marker RR Spike

37.81' N to duplex W/side wood anchor post

17.41' SE to 5/8" iron pin at south edge of pavement

21.11' SW to 5/8" iron pin at south edge of pavement



Richfield Township

Section 17

Corner W¹/₄

Date Established 2/18/2006

Marker Stone - had moved 0.3' west from PKs 15' NE & SE

Set 5/8" Iron Pin from PKs. (Use Iron Pin, not Stone)

Ton of Iron Pin is 0.2' below ton of Stone

28.19' NE to 5/8" iron pin 3' east of pavement (P) (Bent)

28.88' SE to 5/8" iron pin 3' east of pavement (P) (Bent)

W ¹ / ₄	

Richfield Township

Section 18

Corner NW

Date Established 2/18/2006

Marker Iron Pin


Set new Mag Nails 10' NE & SE

58.42' NNW to "+" south end concrete pipe (P)

56.88' NE to spike SW/side power pole

53.92' SE to mag nail east end plastic pipe (P)

84.31' ENE to duplex S/side power pole



Section 18

Corner N¼

Date Established 2/18/2006


Marker RR Spike

19.52' NW to 5/8" iron pin at north edge of pavement (New)

29.11' NNE to "+" north end concrete pipe (P)

33.01' ESE to 5/8" iron pin at south edge of pavement (New)

19.99' SSE to "+" south end concrete pipe (P)



Section 18

Corner W¼

Date Established 2/18/2006

Marker Iron Pin

64.87' NNE to center USGS Sta "COUCH-1948" (P) (1988)


26.42' ENE to duplex S/side power pole

27.13' SE to 5/8" iron pin 1' east of edge of pavement (Bent)

30.08' E to iron pin (P)

69.01' NNW to mag nail west end plastic pipe

70.17' NNE to sawed "+" SW corner catch basin (P)



Richfield Township

Section _____ 19

Corner NW

Date Established 2/18/2006

Marker Small RR Spike

 35.00' NW to "+" south end concrete pipe (P)

 81.15' NNE to map nail S/side power pole (New)

 60.26' ENE to center USGS BM "F117 1947" (P) (1988)

 58.18' ENE to "+" NW corner catch basin (P)

 23.65' SW to "+" north end concrete headwall (P)

 84.40' ENE to duplex S/side power pole

NW	

Section _____ 19

Corner N¼

Date Established 2/19/2006

Marker Small RR Spike

 47.43' SW to "+" south end concrete pipe (P)

 30.46' SSE to "+" in concrete base (P)

 49.85' NW to "+" SE corner catch basin (P)

	N¼

Section _____ 19

Corner W¼

Date Established 2/18/2006

Marker Small RR Spike

 58.45' N to E¼ Post Sec 24 Monroe Twn (1979)

 32.63' NNW to 5/8" iron pin at west edge of pavement

 16.36' SSW to 5/8" iron pin at west edge of pavement

 26.30' E to duplex S/side power pole

 40.04' W to duplex N/side power pole

W¼	

Richfield Township

Section _____ 20

Corner _____ NW

Date Established 2/19/2006

Marker _____ RR Spike

_____ 43.93' NW to north end concrete pipe (P)

_____ 46.07' NE to duplex NW/side telephone pole (New)

_____ 47.83' SW to "+" south end concrete pipe (P)

_____ 46.80' NE to center USGS Sta. "SCHOOL 1950" (P) (1988)

_____ (Left RR spike over monument for magnetic locators)

_____ 41.20' SE to PK nail in center concrete headwall

_____ 47.27' NW to duplex SE/side telephone pole

NW	

Section _____ 20

Corner _____ N¼

Date Established 2/19/2006

Marker _____ RR Spike

_____ 29.36' N to duplex E/side power pole

_____ 34.94' NE to "+" SW corner catch basin (P)

_____ 34.05' SE to "+" south end concrete pipe (P)

	N¼

Section _____ 20

Corner _____ W¼

Date Established 2/19/2006

Marker _____ Iron Pin

_____ 35.43' E to USGS Sta "SIEGRED-1950" (P) (1988)

_____ 24.84' SW to PK nail west end CMP (P)

_____ 36.40' NE to iron pin 1' east of pavement

_____ 31.95' SE to iron pin 1' east of pavement

W¼	

Richfield Township

Section 21

Corner NW

Date Established 2/19/2006

Marker RR Spike

40.33' NE to PK nail SW/side telephone pole


39.01' SE to "+" NE corner catch basin (P)

43.40' SW to "+" south end 90" RCP (P)

47.25' NW to duplex SE/side power pole

41.93' NW to "+" north end concrete pipe (P)

40.85' NE to "+" SE corner catch basin (P)



Section 21

Corner N¼

Date Established 2/19/2006


Marker RR Spike

27.17' NW to "+" SW corner sloned riser

33.28' N to center Sta. "ALVAH 1947" (P)

14.50' S to mag nail south end plastic pipe (P)

75.23' WNW to duplex S/side power pole



Section 21

Corner N¼ NE

Date Established 7/21/1988

Marker RR Spike


21.69' NW to 5/8" iron pin at north edge pavement

51.13' N to duplex W/side 33" manle

35.06' NNE to duplex W/side power pole

30.01' N to property pin

31.76' S to duplex W/side power pole



Richfield Township

Section 21

Corner W¹/₄

Date Established 2/19/2006

Marker Small RR Spike

28.29' E to center Sta. "JOHN-1950" (P) (1988)

55.37' SE to duplex W/side power pole

33.11' SW to mag nail west end plastic pipe (P)

28.62' E to duplex S/side power pole

W ¹ / ₄	

Richfield Township

Section _____ 22

Corner NW

Date Established 2/19/2006

Marker Nail/Shiner

 41.73' SE to nail/shiner NW/side power pole

 45.38' SW to nail/shiner NE/side power pole

 45.47' SE to mag nail east end plastic pipe (P)

 45.44' SW to mag nail west end plastic pipe (P)

Section _____ 22

Corner N¹/₄ NW

Date Established 2/19/2006

Marker RR Spike

 20.88' NW to 5/8" iron pin at north edge of pavement

 23.35' N to "+" SW corner catch basin (P)

 22.70' NE to 5/8" iron pin at north edge of pavement

 26.83' NNE to duplex W/side telephone pole

Section _____ 22

Corner N¹/₄

Date Established 2/19/2006

Marker Small RR Spike




 17.50' S to "+" in concrete wing

 30.81' NE to duplex SE/side telephone pole

 78.57' SE to duplex SW/side power pole

 27.87' SSE to "+" south end CMP (P)

 19.80' NNE to "+" north end CMP (P)



Richfield Township

Section 22

Corner N¹/₄ NE


Date Established 2/19/2006

Marker Small RR Spike

13.97' NE to iron pin 1' north of pavement

13.38' S to iron pin 1' south of pavement

51.96' SE to duplex NW/side power pole



Section 22

Corner W¹/₄

Date Established 2/19/2006


Marker Nail/Shiner

33.19' NW to "+" south end metal pipe (P)

47.87' NNW to "+" north end metal pipe

92.59' SW to nail/shiner NE/side power pole

24.20' E to mag nail north end plastic pipe (P)



Richfield Township

Section _____ 23

Corner NW

Date Established 2/19/2006


Marker Small RR Spike

 50.35' NW to mag nail north end plastic pipe (P)

 46.26' SW to mag nail south end plastic pipe (P)

 40.86' SE to duplex NE/side power pole

 68.37' SW to duplex NW/side power pole



Section _____ 23

Corner N¼ NW

Date Established 2/19/2006


Marker Small RR Spike

 27.54' N to bolt at base of concrete corner post

 24.88' NNE to duplex SE/side telephone pole

 18.97' SE to 5/8" iron pin at south edge of pavement

 17.09' SW to 5/8" iron pin at south edge of pavement



Section _____ 23

Corner N¼


Date Established 2/19/2006

Marker Small RR Spike

 80.18' WNW to duplex S/side telephone pole

 80.57' ENE to duplex S/side telephone pole

 27.58' S to iron pipe in base of concrete anchor post



Richfield Township

Section 23

Corner N¹/₄ NE

Date Established 2/19/2006


Marker Small RR Spike

39.56' WNW to duplex SE/side telephone pole

83.18' ESE to duplex NW/side power pole

19.79' SE to 5/8" iron pin at south edge of pavement

18.43' SW to 5/8" iron pin at south edge of pavement



Section 23

Corner W¹/₄

Date Established 2/19/2006


Marker Iron Pin - 1' west of pavement

23.44' WNW to "+" east end CMP (P)

26.46' NE to 5/8" iron pin at east edge of pavement (New)

23.10' SE to 5/8" iron pin at east edge of pavement

32.27' SE to duplex SW/side power pole



Richfield Township

Section _____ 24

Corner _____ NW _____

Date Established 2/19/2006

Marker _____ Small RR Spike _____

39.65' NW to duplex NE/side telephone pole

32.91' NW to "+" NE corner catch basin (P)

77.99' ENE to duplex N/side brace pole

38.16' SE to duplex SW/side telephone pole

35.60' SW to duplex SE/side power pole

Section _____ 24

Corner _____ N¹/₄ _____

Date Established 2/19/2006

Marker _____ RR Spike _____

18.11' NW to 5/8" iron pin at north edge of pavement

102.19' ENE to duplex SE/side power pole

18.73' SSE to "+" NE corner catch basin (P)

9.51' SW to 5/8" iron pin at south edge of pavement

Section _____ 24

Corner _____ NE _____

Date Established 2/19/2006

Marker _____ RR Spike _____

74.34' WNW to "+" SE corner catch basin (P)

57.10' NW to duplex NE/side power pole

23.10' SE to "+" east end concrete pipe

71.30' WSW to "+" NE corner catch basin (P)

NW	

	N ¹ / ₄

	NE

Richfield Township

Section 24

Corner W¹/₄

Date Established 2/19/2006


Marker RR Spike

75.05' NNW to duplex NE/side power pole

31.72' NE to 5/8" iron pin 1' east of pavement

26.25' SE to 5/8" iron pin 1' east of pavement

69.59' SSE to duplex NE/side telephone pole



Section 24

Corner E¹/₄


Date Established 2/19/2006

Marker Small RR Spike

17.69' NW to 5/8" iron pin at west edge 16' pavement

6.78' E to 5/8" iron pin at east edge 16' pavement

17.00' SW to 5/8" iron pin at west edge 16' pavement



Richfield Township

Section 25

Corner NW

Date Established 2/20/2006

Marker RR Spike

- 63.80' NNW to duplex SW/side power pole
- 54.15' NNW to "+" in center concrete headwall (P)
- 55.09' NNE to shiner S/side telephone pole
- 67.92' SSE to duplex SW/side telephone pole
- 58.35' SSW to duplex NW/side power pole

NW	

Section 25

Corner N¼

Date Established 2/20/2006

Marker Nail/Shiner

- 49.22' NW to "+" SE corner catch basin (P)
- 97.32' S to NW corner of concrete foundation
- 44.42' SW to "+" south end concrete pipe (P)
- 45.62' NNE to duplex E/side power pole

	N¼

Section 25

Corner NE

Date Established 2/20/2006

Marker Small RR Spike

- 46.78' NW to "+" NE corner catch basin (P)
- 74.63' NNE to "+" north end concrete pipe (P)
- 83.25' NNE to shiner SW/side telephone pole
- 32.32' SE to "+" NE corner catch basin (P)
- 90.90' SSE to shiner N/side power pole
- 62.38' SW to nail/shiner NE/side power pole

	NE

Richfield Township

Section 25

Corner W¹/₄

Date Established 2/20/2006


Marker Small RR Spike

22.19' NW to iron pin at edge of pavement

22.87' NE to iron pin at edge of pavement

41.15' SW to PK nail NE/side power pole

33.10' SW to mag nail south end plastic pipe



Section 25

Corner E¹/₄

Date Established 2/20/2006

Marker Iron Pin - Found Stone 0.55' west of Iron Pin

Found PK's 12' NE and SE of Iron Pin


Ties are to Iron Pin (True Point)

44.49' NE to "+" south end concrete drainage structure (P)

73.89' SW to duplex SE/side power pole (P)

45.95' SE to duplex NE/side power pole (P)

21.05' NE to mag nail in plastic pipe (P)



Richfield Township

Section 26

Corner NW

Date Established 2/20/2006

Marker Nail/Shiner

52.35' NW to center USGS BM "A-117 1947" (1988)

48.78' NW to duplex SW/side brace pole

34.62' SE to "+" in center headwall

43.73' SE to "+" south end concrete headwall

51.81' SW to duplex NW/side power pole

49.58' NW to "+" NW corner catch basin

33.34' SW to "+" west end concrete pole (P)

NW	

Section 26

Corner N¼

Date Established 5/21/2014

Marker Small RR Spike

37.81' NE to "x" in SW corner conc. catch basin

46.49' S to map nail in 24" maple tree

64.34' SW to duplex SE/side power pole

	N¼

Section 26

Corner W¼

Date Established 2/20/2006

Marker Small RR Spike

25.19' NW to "+" east end concrete headwall (P)

36.57' SW to duplex N/side power pole

23.39' SW to "+" south end concrete headwall (P)

27.31' SE to "+" east end CMP (P)

W¼	

Richfield Township

Section 26

Corner CENTER

Date Established 2/20/2006


Marker Iron Pin

38.52' N to "+" in concrete slab

21.89' N to duplex W/side power pole (New)

44.94' SE to mag nail in plastic pipe (P)

18.13' S to mag nail in plastic pipe (P)



Richfield Township

Section 27

Corner NW

Date Established 2/20/2006


Marker Nail/Shiner

57.92' NW to "+" north end concrete pipe (P)

50.22' NE to "+" SW corner "Traffic" man hole

47.40' SW to "+" SE corner "Traffic" man hole (P)

66.06' SW to "+" south end concrete pipe (P)



Section 27

Corner N¼

Date Established 2/28/2006


Marker Iron Pin - Reset

36.18' NW to 5/8" iron pin at north edge pavement (P)

37.68' NE to 5/8" iron pin at north edge pavement (P)

20.52' SE to 5/8" iron pin on ditch bank (P)

28.84' SW to 5/8" iron pin on ditch bank (P)



Section 27

Corner W¼


Date Established 2/20/2006

Marker Nail/Shiner

22.88' NE to SE corner of north banister

55.55' SSW to "+" east end concrete pipe (P)

16.95' WSW to NE corner of south banister



Richfield Township

Section _____ 28

Corner NW

Date Established 2/20/2006

Marker Nail/Shiner

 52.37' NW to shiner SE/side telephone pole

 34.46' NW to "+" north end concrete headwall (P)

 54.11' NE to "+" USGS BM "C-117 1947" (P)

 68.95' ENE to shiner SW/side telephone pole

 57.01' SSE to shiner NW/side power pole

 33.33' SW to "+" in concrete headwall

NW	

Section _____ 28

Corner N¼

Date Established 2/20/2006

Marker Nail/Shiner

 39.28' NW to "+" west end concrete pipe (P)

 27.36' NNW to "+" east end concrete pipe (P)

 42.20' N to center Sta. "BENEIN 1947" (P)

 64.38' SW to duplex SE/side power pole

	N¼

Section _____ 28

Corner W¼

Date Established 2/20/2006

Marker Iron Pin

 45.22' SSE to duplex NE/side power pole (P) (New)

 21.62' SSW to "+" in concrete wing (P)

 8.44' SW to "+" in concrete wing (P)

W¼	

Richfield Township

Section _____ 29

Corner NW

Date Established 2/20/2006

Marker Nail/Shiner

 53.00 NW to shiner SE/side telephone pole

 55.93' NE to center USGS BM "B-117 1948"

 28.35' WSW to "+" west end concrete parant

 50.03' SE to shiner NE/side power pole

 36.68' NW to "+" north end concrete headwall (P)

 49.68' SE to "+" east end concrete pipe (P)

NW	

Section _____ 29

Corner N¼

Date Established 2/20/2006

Marker Nail/Shiner

 39.65' NE to "+" west end concrete headwall (P)

 48.30' ESE to "+" east end concrete headwall (P)

 37.19' ESE to "+" west end concrete headwall (P)

 52.11' SW to duplex NW/side power pole

 47.13' S to center Sta. "IMBROCK 1947"

	N¼

Section _____ 29

Corner W¼

Date Established 2/20/2006

Marker Iron Pin

 10" below edge of pavement at west edge of pavement

 32.92' NE to 5/8" iron pin 3' east of pavement

 23.74' SE to 5/8" iron pin 3' east of pavement

W¼	

Richfield Township

Section 30

Corner NW

Date Established 2/20/2006

Marker Nail/Shiner

31.54' NNW to "+" in concrete curb of banister

51.50' NNE to center USGS BM "E 117 1947" (P) (1988)

44.28' SE to "+" east end concrete headwall (P)

54.42' SE to shiner N/side power pole

20.66' SW to "+" in concrete curb of banister

35.22' NNE to "+" in north wing of bridge

47.57' NE to "+" in NE corner catch basin (P)

NW	

Section 30

Corner N¹/₄

Date Established 2/20/2006

Marker Nail/Shiner

35.68' NNW to "+" NW corner catch basin (P)

57.71' SE to duplex NW/side power pole

25.59' SSW to "+" south end RCP (P)

30.53' NE to near corner metal mail box post

	N ¹ / ₄

Section 30

Corner W¹/₄

Date Established 2/20/2006

Marker RR Spike at west edge of pavement

30.90' ESE to duplex N/side power pole

37.94' SE to "+" NW corner catch basin (P)

28.65' SW to "+" west end 8" concrete pipe (P)

W ¹ / ₄	

Richfield Township

Section 31

Corner NW

Date Established 2/28/2006


Marker Small RR Spike

25.87' WNW to "+" south end of RCP (P)

79.83' NNE to PK nail SW/side power pole

40.47' SE to PK nail east end plastic pipe (P)

25.59' SW to PK nail in plastic pipe at ditch bank (P)



Section 31

Corner OTHER

Date Established 2/28/2006


Marker Iron Pin

28.09' N to "+" SE corner catch basin (P)

32.01' NE to 5/8" iron pin 1' north of pavement (P)

37.47' E to iron pin at N¼ Post

57.12' E to map nail in plastic tile (P)



Section 31

Corner N¼

Date Established 2/28/2006


Marker Iron Pin

44.28' WNW to "+" SE corner catch basin (P)

33.83' NW to 5/8" iron pin 1' north of pavement (P)

37.47' W to iron pin

19.88' E to map nail in plastic tile (P)



Richfield Township

Section 31

Corner W¹/₄

Date Established 2/28/2006


Marker Small RR Spike

21.40' N to E¹/₄ Post. Sec. 36. Monroe Twp.

22.71' NE to PK nail W/side power pole

66.82' SSE to "+" NW corner catch basin

35.06' SW to mag nail in plastic tile (P)



Section 31

Corner SW

Date Established 8/30/2006

Marker Small RR Spike

40.18' SE to duplex SW/side power pole

42.35' SW to duplex NW/side power pole


43.22' NW to duplex SW/side power pole

56.63' NE to duplex SE/side power pole

43.51' SE to "+" NW corner catch basin (P)

31.28' SW to "+" south end RCP (P)

41.05' NW to "+" north end RCP (P)



Section 31

Corner S¹/₄ (1905 Su)

Date Established 8/30/2006

Marker Small RR Spike


37.00' ENE to duplex SE/side telephone pole

45.75' SE to "+" north side iron corner post

51.35' SW to duplex NW/side power pole

39.87' E to S¹/₄ Stone (1907 Survey- Vol. 3. Pg. 134)

44.82' ENE to 5/8" iron pin at north edge of pavement



Richfield Township

Section 31

Corner S¹/₄ (1907 Su

Date Established 8/30/2006

Marker RR Spike


28.84' NW to duplex SE/side telephone pole

11.59' NE to 5/8" iron pin at edge of pavement

33.38' S to "+" north side iron corner post

85.02' SW to duplex NW/side power pole

39.87' W to S¹/₄ Stone (1905 Survey - Vol. 3, Pg. 112)



Richfield Township

Section _____ 32

Corner NW

Date Established 2/28/2006

Marker Small RR Spike

 51.43' NW to "+" in north end RCP (P)

 39.14' NE to PK nail SW/side power pole

 38.99' SE to mag nail in plastic tile (P)

 40.67' SW to "+" south end RCP (P)

NW	

Section _____ 32

Corner N¼

Date Established 2/28/2006

Marker Iron Pine

 25.07' NW to 5/8" iron pin 1' north of pavement

 27.90' N to center of iron pine (P)

 26.81' NE to 5/8" iron pin 1' north of pavement

 46.18' NE to duplex SE/side power pole

	N¼

Section _____ 32

Corner W¼

Date Established 2/28/2006

Marker Small RR Spike

 29.10' E to nail/shiner S/side wood corner post

 45.58' SE to "+" north end agriculture structure (P)

 19.36' SW to mag nail west end plastic tile (P)

 87.22' S to PK nail NW/side power pole

W¼	

Richfield Township

Section 32

Corner SW

Date Established 8/30/2006

Marker RR Spike


31.71' S to duplex west side power pole

27.11' SW to "+" concrete headwall (P)

43.02' NW to "+" north end RCP (P)

54.92' NE to "+" SE corner catch basin

32.63' E to NW corner Sec. 5, Bartlow Twp.



Section 32

Corner S¼

Date Established 8/30/2006

Marker RR Spike


25.02' NW to PK nail west end CMP (P)

24.84' N to "+" on high point of witness stone

18.75' NNE to PK nail east end CMP (P)

70.48' ESE to duplex north side power pole

26.53' E to N¼ post Sec. 5, Bartlow Twp.



Richfield Township

Section _____ 33

Corner NW

Date Established 2/28/2006


Marker Small RR Spike

 22.19' NW to SE corner of north banister

 36.84' NE to duplex S/side power pole

 33.97' SE to "+" east end concrete pipe (P)

 18.27' SW to "+" south end SE wingwall (P)



Section _____ 33

Corner OTHER

Date Established 2/28/2006

Marker RR Spike

 108.40' E to N¼ Post. Sec. 33 (1979)


 18.47' NW to 5/8" iron pin at north edge pavement

 18.30' NE to 5/8" iron pin at north edge pavement

 13.64' ESE to 5/8" iron pin at south edge pavement

 35.48' SE to duplex E/side wood post

 33.65' SW to duplex NW/side wood post



Section _____ 33

Corner N¼

Date Established 2/28/2006


Marker Small RR Spike

 18.72' NE to 1" iron pipe 1' north of pavement

 12.97' ESE to 5/8" iron pin 1' south of pavement

 9.20' WSW to 5/8" iron pin 1' south of pavement

 30.00' N to capped iron pin (P)



Richfield Township

Section 33

Corner W¹/₄


Date Established 2/28/2006

Marker Small RR Spike

15.47' NW to 5/8" iron pin 1' west of pavement

13.01' NE to 5/8" iron pin 1' east of pavement

77.92' SSE to duplex W/side power pole (New)



Section 33

Corner SW

Date Established 8/30/2006

Marker RR Spike

40.45' WNW to "+" east end concrete banister

73.32' NE to duplex south side power pole. NEW


57.50' ESE to "+" east end conc. pipe (P)

55.05' ESE to duplex SW/side power pole

19.92' E to NW corner. Sec. 5. Bartlow Twp.

60.42' ENE to mag nail north end CMP (P)

51.08' SW to duplex west side of east post of church sign



Section 33

Corner S¹/₄

Date Established 8/30/2006


Marker RR Spike

9.75' NW to 5/8" iron pin 0.5' north of pavement

24.77' NE to 5/8" iron pin 0.5' north of pavement

60.78' ESE to duplex N/side of power pole

17.36' E to N¹/₄ Post. Sec. 4. Bartlow Twp.



Richfield Township

Section _____ 34

Corner NW

Date Established 2/28/2006

Marker Nail/Shiner

 43.96' NW to shiner SE/side power pole

 51.37' NE to shiner SW/side walnut tree

 34.72' SE to "+" east end RCP (P)

 28.85' SW to "+" west end RCP (P)

 40.14' NE to "+" SW corner catch basin (P)

Section _____ 34

Corner N¼

Date Established 2/28/2006

Marker Small RR Spike

 22.37' NE to iron pin

 22.05' NW to iron pin

 75.37' SW to PK nail NE/side power pole

 47.59' S to "+" east end agriculture inlet (P)

Section _____ 34

Corner W¼

Date Established 2/28/2006

Marker Monument Box

 Center punched box from straddles

 38.04' WNW to "+" north end concrete wing (P)

 45.52' ENE to "+" north end concrete wing (P)

 50.55' SE to "+" south end concrete wing (P)

 43.13' SW to "+" south end concrete wing (P)

 82.18' NNE to duplex SE/side power pole

NW	

	N¼

W¼	

Richfield Township

Section 34

Corner SW

Date Established 8/30/2006

Marker Placed Small RR Spike - No point found.

Re-established corner from witness ties.

29.70' NW to "+" SE corner metal frame of catch basin grate (P)

58.73' NW to nail/shiner SE/side of power pole


87.18' ENE to shiner west side of telephone pole

72.94' ESE to duplex north side of power pole

35.47' SW to "+" SW corner catch basin (P)

17.72' E to NW corner Sec. 3, Bartlow Twp.

45.87' SSW to duplex east side of power pole



Section 34

Corner S¹/₄

Date Established 8/30/2006


Marker RR Spike

16.61' E to N¹/₄ Post. Sec. 3, Bartlow Twp.

34.42' N to duplex W/side power pole

28.45' SSW to duplex E/side power pole

53.65' ENE to duplex SE/side power pole



Richfield Township

Section _____ 35

Corner _____ NW _____


Date Established 8/12/2005

Marker _____ Small RR Spike _____

40.32' SE to sawed "+" east end RCP

38.63' SW to sawed "+" west end RCP

38.45' NE to duplex SE/side power pole



Section _____ 35

Corner _____ N¹/₄ _____


Date Established 2/28/2006

Marker _____ Iron Pin _____

32.80' N to near face 4" iron pipe

25.52' S to duplex W/side 12" oak tree

54.95' NE to duplex SE/side power pole



Section _____ 35

Corner _____ W¹/₄ _____

Date Established 2/28/2006


Marker _____ Small RR Spike _____

15.45' NNW to 5/8" iron pin 0.5' west of pavement

17.47' E to 5/8" iron pin 1' east of pavement

17.12' SSW to 5/8" iron pin 1' west of pavement

28.01' E to duplex S/side power pole



Richfield Township

Section 35

Corner SW

Date Established 8/30/2006

Marker RR Spike


17.16' E to NW corner. Sec. 2, Bartlow Twp.

84.42' ENE to duplex SW/side cable marker

52.52' SE to duplex N/side power pole (NEW)

31.22' SSW to duplex E/side brace pole

27.11' NNW to 5/8" iron pin 0.5' NW of edge of pavement radius



Section 35

Corner S¹/₄


Date Established 5/31/2012

Marker Small RR Spike

45.77' ESE to "+" in SW wingwall

128.86' ENE to "+" in NE wingwall

111.46' NE to "+" in northerly corner of bridge



Richfield Township

Section _____ 36

Corner _____ NW _____

Date Established 2/28/2006

Marker _____ Small RR Spike _____

38.51' NW to duplex NE/side power pole

45.67' NW to mas nail north end plastic tile (P)

40.80' NE to duplex SE/side telephone pole

45.58' SW to mas nail south end plastic tile (P)

Section _____ 36

Corner _____ N¹/₄ _____

Date Established 2/28/2006

Marker _____ Small RR Spike _____

30.13' NNW to "+" north end RCP (P)

16.93' NE to 5/8" iron pin at north edge of pavement

15.64' SE to 5/8" iron pin at south edge of pavement

26.40' SSW to "+" south end RCP (P)

Section _____ 36

Corner _____ NE _____

Date Established 2/28/2006

Marker _____ Small RR Spike _____

38.90' NW to duplex NE/side power pole

46.71' NW to "+" north end RCP (P)

50.09' NE to "+" east end RCP (P)

36.65' SE to nail/shiner N/side buried cable marker

52.61' SW to "+" south end RCP (P)

NW	

	N ¹ / ₄

	NE

Richfield Township

Section 36

Corner W¹/₄


Date Established 2/28/2006

Marker Small RR Spike

62.95' NNW to duplex NE/side power pole

43.81' SE to "+" NE corner catch basin (P) (New)

75.14' NE to mag nail S/side hickory tree




Section 36

Corner E¹/₄

Date Established 2/28/2006

Marker Iron Pin washed out by erosion

Found PK's 12' NE and SE



Section 36

Corner SW

Date Established 2/28/2006

Marker Small RR Spike

40.10' NW to duplex SW/side power pole

31.37' NW to "+" north end 66" CMP (P)


103.83' NE to SW corner brick veneer house

46.60' SE to duplex W/side sign post

30.44' SW to PK south end 66" CMP

39.13' SW to PK NE/side power pole

10.56' E to NW corner. Sec. 1. Bartlow Twn.



Richfield Township

Section 36

Corner S¹/₄

Date Established 12/8/2006


Marker RR Spike - 3" below surface

5.28' E to N¹/₄ Post. Sec. 1. Bartlow Twp.

68.60' WNW to duplex NE/side power pole

18.67' NW to 5/8" iron pin 6' north of pavement

9.80' SW to iron pin 6' south of edge of pavement



Section 36

Corner SE

Date Established 0/26/2006

Marker Small RR Spike

41.73' NW to "+" north end RCP (P)

49.71' NE to duplex SE/side power pole

69.54' SE to duplex SW/side power pole

42.13' SW to south end RCP (P)

