Section 1	NW	
Date Established 10/26/2006		
Corner NW		
Marker Small RR Spike		
48.90' WNW to duplex SW/side power pole		
38.96' WNW to "+" cut north end 66" CMP		
40.04' SE to duplex W/side sign post	.	
38.22' SW to PK south end 66" CMP		
10.56' W to SW corner. Sec. 36. Richfield Twp.		•
48.01' SW to PK nail NE/side power pole		
97.75' NNE to SW corner brick veneer house (No field check)		
Section 1		N <sup>1</sup> / <sub>4</sub>
Date Established 10/26/2006		
Corner <u>N<sup>1</sup>/<sub>4</sub></u>		
Marker Small RR Spike		
73.57' WNW to duplex N/side power pole		
5.28' W to S <sup>1</sup> / <sub>4</sub> post, Sec. 36, Richfield Twp.	-	
20.86' NW to 5/8" iron pin 6' north of edge of pavement		
13.50' SW to 5/8" iron pin 6' south of edge of pavement		
Section 1		NE
Date Established10/26/2006		
Corner NE		
Marker Small RR Spike	_	
41.73' NW to "+" north end RCP (P)		
49.71' NE to duplex SE/side power pole		
69.54' SE to duplex SW/side power pole	_	
42.13' SW to south end RCP (P)		

Tuesday, July 13, 2021 Page 1 of 57

Section 1		
<b>Date Established</b> 10/26/2006_		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker PK Nail - Found iron pin 5.5' west of west edge of pavement	W <sup>1</sup> / <sub>4</sub>	
11.90' SW to "+" west end 21" RCP (P)		
53.72' NE to duplex NW/side power pole (P)		
13.52' NW to "+" south end RCP (P)		
34.75' NNW to "+" north end RCP (P)		
Section 1		
Date Established 10/26/2006		
Corner E <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin - Adjusted to 10' off PK's		E1/2
NOTE: Ties are to iron pin, not stone. Stone is moving to west		
36.20' NE to "+" SE corner catch basin top (P)		
13.35' SW to PK nail west end 10" CMP (P)		
28.53' NW to "+" in witness stone on west ditch bank (P)		

Tuesday, July 13, 2021 Page 2 of 57

Section 2	NW	
Date Established 8/30/2006		
Corner NW		
Marker RR Spike		
68.30' ENE to duplex SW/side cable marker	_	
39.28' SE to duplex north side power pole	_	
40.08' SW to duplex east side brace pole	_	
35.65' NW to 5/8" iron pin 0.5' west of edge of pavement radius	_	
17.16' W to SW corner, Sec. 35. Richfield Twp.	-	
Section 2	-	N <sup>1</sup> / <sub>4</sub>
Date Established 5/31/2012		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
27.10' ESE to "+" in SW wingwall		
108.46' ENE to "+" in NE wingwall		
92.67' NE to "+" in northerly corner of bridge	_	
	_	
	- - -	
Section 2		T
Date Established 10/26/2006		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin	W <sup>1</sup> / <sub>4</sub>	
NOTE: Reset iron pin to 10' from PKs. Ties to iron pin, not stone.	_	
5.23' NW to "+" south end concrete headwall	_	
9.70' NW to "+" north end concrete headwall (P)	_	
27.14' ENE to "+" SW corner catch basin (P)	_	
33.85' E to duplex S/side power pole	-	
	_	

Tuesday, July 13, 2021 Page 3 of 57

Section 3	NW
Date Established 8/30/2006	
Corner NW	
Marker Nail & Shiner	
68.19' NW to nail/shiner SE/side power pole 47.09' SW to "+" SW corner catch basin (P) 70.54' ENE to shiner west side telephone pole 58.49' SE to duplex north side power pole 58.05' SW to duplex east side power pole 17.72' W to SW corner. Sec. 34. Richfield Twp.	
43.51' NW to chiseled "+" SE corner catch basin frame (P)	
Section         3           Date Established         8/30/2006           Corner         N½	N <sup>1</sup> / <sub>4</sub>
Marker RR Spike	
38.47' NW to duplex west side power pole 35.24' SW to duplex east side power pole 16.61' W to S¹/4 Post, Sec. 34, Richfield Twp. 41.10' NE to duplex SE/side power pole	
Section 3	
Date Established 10/26/2006	
Corner W <sup>1</sup> / <sub>4</sub>	
Marker Iron Pin	W <sup>1</sup> / <sub>4</sub>
Iron Pin is 1' west of west edge of pavement  66.15' NE to nail/shiner SW/side telephone pole  44.36' SE to "+" NW corner catch basin (P)	

Tuesday, July 13, 2021 Page 4 of 57

Section 4	NW
Date Established 8/30/2006	
Corner NW	
Marker RR Spike	
59.44' WNW to "+" top edge end concrete bridge rail	
40.52' SE to duplex SW/side power pole	
19.92' W to SW corner. Sec. 33. Richfield Twp.	
41.89' ENE to mag nail north end CMP (P)	
69.74' N to duplex south side power pole (NEW)	
66.03' SW to duplex west side of east post of church sign	
40.64' SE to "+" east end RCP (P)	
Section 4	N <sup>1</sup> / <sub>4</sub>
Date Established 8/30/2006	
Corner N <sup>1</sup> / <sub>4</sub>	
Marker RR Spike	
46.43' SE to duplex north side power pole	
17.36' W to S <sup>1</sup> / <sub>4</sub> Post, Sec. 33, Richfield Twp.	
9.34' NE to 5/8" iron pin at north edge of pavement	
25.12' WNW to 5/8" iron pin at north edge of pavement	
Section 4	
Date Established 10/26/2006	
Corner W <sup>1</sup> / <sub>4</sub>	
Marker Iron Pin	W <sup>1</sup> / <sub>4</sub>
Iron Pin is 0.5' west of west edge of pavement	
22.91' SW to "+" south end 48" RCP (P)	
28.21' NW to "+" north end 48" RCP (P)	
39.55' ESE to "+" east end 42" RCP (P)	

Tuesday, July 13, 2021 Page 5 of 57

Section 4	
Date Established 5/4/1982	
Corner W1/4 SW	
Marker 3/4" Rod	
48.67' W to "+" in concrete headwall	
18.49' W to PK nail east end 18" CMP (P)	< w1/4SW
107.18' NNW to duplex E/side telephone pole	
27.30' ESE to duplex N/side power pole	

Tuesday, July 13, 2021 Page 6 of 57

Section 5	NW	
Date Established 8/30/2006		
Corner NW		
Marker RR Spike		
45.39' SW to duplex west side power pole		
55.92' WSW to "+" concrete headwall (P)		
65.41' WNW to "+" north end RCP (P)		
48.83' NNE to "+" SE corner catch basin (P)		
32.63' W to SW corner, Sec. 32. Richfield Twp.		
Section 5	N½	ı
Date Established 8/30/2006		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
36.51' NNW to "+" on high point of witness stone (P)		
47.84' SE to duplex north side power pole		
26.53' W to S <sup>1</sup> / <sub>4</sub> Post, Sec. 32, Richfield Twp.		
46.90' WNW to PK nail west end buried CMP (P)		
29.96' NW to PK nail east end buried CMP (P)		
Section 5		
Date Established10/26/2006		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike	W1/4	
64.17' WNW to mag nail west end plastic drive pipe		
41.94' SW to "+" west end RCP (P)		
40.22' SE to "+" east end RCP (P)		
	LL	

Tuesday, July 13, 2021 Page 7 of 57

Section 6	NW	
Date Established 8/30/2006		
Corner NW		
Marker Small RR Spike		
40.18' SE to duplex SW/side power pole		
42.35' SW to duplex NW/side power pole		
43.22' NW to duplex SW/side power pole		
56.63' NE to duplex SE/side power pole		
43.51' SE to "+" NW corner catch basin (P)		
31.28' SW to "+" south end RCP (P)		
41.05' NW to "+" north end RCP (P)		
Section 6	N	1/4
<b>Date Established</b> <u>8/30/2006</u>		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
15.65' NE to 5/8" iron pin at north edge of pavement		
32.36' W to S <sup>1</sup> / <sub>4</sub> Post, Sec. 31, Richfield Twp.		
26.27' NNW to duplex SE/side telephone pole		
32.46' S to near face iron anchor post		
78.22' WSW to duplex north side power pole		
7.51' E to RR Spike (See "E1", Sec. 31, Richfield Twp.)		
Section 6		
<b>Date Established</b>		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker RR Spike	W1/4	
26.74' NW to "+" in top south end concrete pipe		
25.60' E to PK in power pole		
59.72' NNW to "+" north end RCP (P)		
84.80' N to Iron Pin, E <sup>1</sup> / <sub>4</sub> Sec. 1, Marion Twp.		
37.95' N to small RR Spike C/L Road F2		

Tuesday, July 13, 2021 Page 8 of 57

Section 6		
Date Established		
Corner CENTER		
Marker Iron Pin		(
Iron Pin is 10½' north of north edge of pavement  8.37' NNW to "+" west end conncrete headwall (P) (Ag. Inlet)  8.80' NNE to "+" east end of concrete headwall (P) (Ag. Inlet)  36.63' S to PK nail south end 12" CMP	CEN	TER
Section 6		
Date Established 10/26/2006		
Corner W1/4 SW		
Marker RR Spike - 5" Below Surface		
RR Spike is 1' east of west edge of pavement (P)  13.18' SW to "+" top plastic pipe (P)  35.59' SE to duplex SW/side power pole  42.29' ESE to "+" NE corner concrete slab	<b>&lt;</b> W⅓SW	

Tuesday, July 13, 2021 Page 9 of 57

Section 7	NW	
Date Established 10/26/2006		
Corner NW		
Marker RR Spike - 6" below surface at west edge of pavement		
61.62' NE to mag nail S/side maple tree		
22.67' SW to punched hole on south end of 72" CMP (P)		
88.98' NNE to duplex SE/side guard rail post		
52.12' SE to PK NW/side power pole (11/7/74 tie) (No field check)	- <u>L</u>	
	-	
Section 7		N <sup>1</sup> ⁄ <sub>4</sub>
Date Established 10/26/2006		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
24.67' NNE to "+" top center west wall catch basin		
19.80' ESE to PK in corrugated plastic pipe (P)		
30.18' S to near face steel post		
34.34' SW to PK north end 24" CMP (P)	_	
	-	
Section 7		
Date Established 10/26/2006		
Corner _W <sup>1</sup> / <sub>4</sub>		
Marker RR Spike	W1⁄4	
RR Spike - 15" west of west edge of pavement and 6" below surface	_	
131.95' NE to duplex SE/side power pole		
96.05' SE to duplex NE/side power pole	_	
17.05' SW to PK nail west end 12" CMP (P)	_	
34.55' NE to "+" west side concrete post	_	
	_	

Tuesday, July 13, 2021 Page 10 of 57

Section 8	NW	
Date Established 11/3/2006		
Corner NW		
Marker Small RR Spike		
49.70' NE to "+" SE wing of Bridge 6-5.00		
41.99' NNW to "+" in SW wingwall of Bridge 6-5.00		
61.00' WNW to "+" in NE wingwall of Bridge F-13.00		
Section 8	N1/4	
Date Established 11/3/2006		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
19.44' NW to 5/8" iron pin		
22.48' NE to 5/8" iron pin		
Section 8		
Date Established 11/3/2006		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin	W1⁄4	
13.04' WSW to mag nail west end 24" CMP (P)		
85.13' SSE to duplex W/side power pole		
34.48' E to "+" north end concrete headwall (P)		
37.60' SE to PK (crushed) south end 12" CMP (P)		

Tuesday, July 13, 2021 Page 11 of 57

Section 9	NW	
Date Established 11/3/2006		
Corner NW		
Marker Small RR Spike		
23.90' NW to "+" in concrete headwall		
44.42' NE to duplex SE/side power pole (New)		
29.01' SE to "+" in concrete headwall		
20.01' SW to "+" in concrete headwall		
Section 9		N <sup>1</sup> / <sub>4</sub>
Date Established11/3/2006_		
Corner <u>N<sup>1</sup>/<sub>4</sub></u>		
Marker Small RR Spike		
40.25' NNW to near face well casing		
29.61' N to duplex E/side power pole		
28.90' SE to "+" in top of large rock (P)		
17.36' SW to 5/8" iron pin 3' south of south edge of pavement		
	_	
Section 9		
Date Established 11/3/2006		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker RR Spike	W1/4	
82.78' NNE to duplex W/side power pole		
25.98' SE to "+" in concrete (P)		
29.66' SW to "+" east end 15" concrete pipe (P)		

Tuesday, July 13, 2021 Page 12 of 57

Section 10	NW	
Date Established 11/3/2006		
Corner NW		
Marker Nail/Shiner		
79.48' NW to "+" 72" RCP (P)		
52.05' NE to duplex NW/side power pole		
38.48' SE to "+" east end concrete headwall		
40.92' SE to nail/shiner NW/side power pole		
83.40' W to "+" 72" RCP (P)		
Section 10	N <sup>1</sup> / <sub>4</sub>	
Date Established11/3/2006		
Corner <u>N<sup>1</sup>/<sub>4</sub></u>		
Marker Stone Leaning North		
130.75' WNW to duplex S/side power pole (Did not check)		
126.64' ENE to duplex S/side power pole (Did not check)		
11.25' NW to 5/8" iron pin on ditch bank (Mark to Mark)		
11.95' NE to 5/8" iron pin on ditch bank (Mark to Mark)		
17.5' N to south edge of pavement		
Section 10		
Date Established11/3/2006		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Nail/Shiner	W1/4	
26.05' WNW to "+" west end 12" concrete pipe (P)		
26.78' ENE to "+" east end 12" concrete pipe (P)		

Tuesday, July 13, 2021 Page 13 of 57

Section 10			
Date Established 5/12/1982			
Corner <u>CENTER</u>			
Marker Found stone beside woo	od post		
		CEN	TER

Tuesday, July 13, 2021 Page 14 of 57

Section 11	NW
Date Established 11/3/2006	
Corner NW	
Marker Small RR Spike	
43.69' NW to duplex SW/side power pole	
46.64' NNW to "+" north end 84" CMP (P)	
50.24' NE to PK nail NW/side underground cable marker	
31.63' ESE to center of bench mark tablet	
32.84' SW to "+" south end 84" CMP (P)	
Section 11	N¼NWNW
Date Established 5/13/1982	
Corner OTHER	
Marker RR Spike	
29.38' NNE to duplex E/side power pole	
17.11' S to"+" NE corner concrete box culvert (P)	
22.05' SW to "+" NW corner concrete box culvert (P)	
Section 11	N14NW
Date Established 5/12/1982	
Corner N1/4 NW	
Marker RR Spike	
141.44' WNW to duplex S/side power pole	
128.83' ENE to duplex S/side power pole	

Tuesday, July 13, 2021 Page 15 of 57

Section 11	N <sup>1</sup> / <sub>4</sub>
Date Established 11/3/2006	
Corner N <sup>1</sup> / <sub>4</sub>	
Marker Iron Pin	
31	
34.60' N to "+" north end 72" RCP (P)	
93.61' ENE to duplex S/side power pole	
23.97' S to "+" south end 72" RCP (P)	
32.94' WSW to PK west end 24' CMP (P) (No Field Check)	
Section <u>11</u>	
Date Established5/12/1982	10/1/01/07
Corner W <sup>1</sup> / <sub>4</sub> NW	W14NW
Marker Iron Pin	
30.44' E to duplex SW/side wood anchor post (P)	
105.56' SSE to nail/shiner E/side power pole	
82.45' WSW to NE corner concrete block building foundation	
Section <u>11</u>	
Date Established11/3/2006	
Corner W <sup>1</sup> / <sub>4</sub>	
Marker Iron Pin - 2' west of west edge of pavement	W <sup>1</sup> / <sub>4</sub>
31.75' NE to iron pin on east edge of pavement	
30.49' SE to iron pin on east edge of pavement	
66.50' SSW to PK nail west end 12" CMP (P)	
33.60' SW to PK nail east end 10" plastic (P)	

Tuesday, July 13, 2021 Page 16 of 57

Section 12	NW	
Date Established 11/3/2006		
Corner NW		
Marker Small RR Spike		
35.01' NW to "+" north end 48" RCP (P)		
54.38' NE to duplex SE/side power pole		
59.89' SE to duplex SW/side power pole		
34.29' SW to "+" south end 48" RCP (P)		
<b>Section</b> 12		N <sup>1</sup> ⁄ <sub>4</sub>
Date Established11/3/2006		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
81.45' NE to duplex S/side power pole		
23.63' SE to duplex E/side guard rail post		
19.24' NNW to "+" top center concrete headwall		
20.53' SSW to "+" top center concrete headwall		
30.66' SW to duplex W/side guard rail post		,
22.89' NW to duplex SW/side guard rail post		
Section 12		NE.
Date Established11/3/2006		
Corner NE		
Marker Small RR Spike		
44.85' SW to "+" south end RCP (P)		
34.17' NW to PK SE/side power pole		
43.60' NW to "+" north end RCP (P)		
44.49' NE to "+" east end RCP (P)		
33.29' N to NW corner, Sec. 7, Jackson Twp., Wood Co.		

Tuesday, July 13, 2021 Page 17 of 57

1/4
E½

Tuesday, July 13, 2021 Page 18 of 57

Section 13	NW	
Date Established11/3/2006		
Corner NW		
Marker Small RR Spike		
95.43' WNW to duplex S/side power pole		
43.73' NE to PK nail SW/side power pole		
67.54' ESE to duplex SW/side telephone pole		
32.68' SW to "+" SW corner concrete catch basin (P)		
Section <u>13</u>	N¼NW	
Date Established 5/24/1982		
Corner N1/4 NW		
Marker RR Spike		
12.39' NW to 5/8" iron pin at north edge of pavement		
14.86' NE to 5/8" iron pin at north edge of pavement		
Section 13		1/4
Date Established 12/8/2009		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
30.32' NNE to mag nail north end 48" N12 plastic pipe (P)		
31.02' SSE to mag nail south end 48" N12 plastic pipe (P)		
89.75' ESE to PK nail west end 36" CMP (P)		

Tuesday, July 13, 2021 Page 19 of 57

Section 13		NE
<b>Date Established</b> 11/3/2006_		
Corner NE		
Marker RR Spike		
46.21' NNE to duplex NW/side telephone pole		
59.37' ENE to duplex SE/side telephone pole		
31.55' SE to duplex NE/side telephone pole		
52.72' SW to duplex NW/side power pole		
34.85' NW to copper wire in concrete monument (P)		
17.22' N to RR spike at Wood Co. corner		
Section 13		
Date Established 3/18/1982		
Corner W1/4 NW	₩¼NW	
Marker RR Spike		
43.71' W to iron pin on west ditch bank		
37.85' NNE to duplex SW root 21" maple		
72.30' NE to SW corner block porch foundation		
24.10' ESE to duplex SW/side power pole		
35.54' SE to iron pin (P)		
Section 13		
<b>Date Established</b> 11/3/2006_		
Corner W1/4		
Marker RR Spike	W <sup>1</sup> / <sub>4</sub>	
27.42' SE to duplex SW/side power pole		
27.81' SE to "+" SW corner catch basin (P)		
31.73' NW to south end concrete headwall (P)		
108.24' NNE to duplex W/side power pole		
78.04' W to NE corner house foundation		

Tuesday, July 13, 2021 Page 20 of 57

Section 13		
Date Established 11/3/2006		
Corner <u>E<sup>1</sup>/<sub>4</sub></u>		
Marker Small RR Spike		E1/2
8.43' NW to iron pin in center concrete monument(P)		
6.61' SW to iron pin in center concrete monument (P)		
Section 13		
Date Established3/18/1982		
Corner W <sup>1</sup> / <sub>4</sub> SW		
Marker RR Spike		
34.40' W to duplex S/side power pole 17.07' WNW to near face house foundation		
32.39' NE to duplex NW/side power pole	< W⅓SW	
71.70' WSW to NE corner porch foundation		
86.94' SW to SE corner block house foundation		
SOLD I STATE OF SELECTION TO COMPANIENT STATE OF SELECTION TO COMP		
Section 13		
Date Established 11/3/2006		
Corner OTHER		
Marker PK Nail		
40.80' WSW to "+" north rim of manhole		
56.02' E to SW corner concrete block house foundation		
39.94' ESE to duplex SW/side power pole		
75.42' SE to duplex W/side brace pole	N. R/W, North St.	
65.65' SW to duplex E/side light pole		

Tuesday, July 13, 2021 Page 21 of 57

Section 14	NW	
Date Established 11/6/2006		
Corner NW		
Marker Small RR Spike		
51.59' ESE to mag nail in corrugated plastic pipe (P)		
31.41' SSW to "+" south end concrete headwall (P)		
29.29' WSW to "+" at bend in concrete headwall (P)		
40.58' NW to chiseled "+" north end 54" RCP		
Section 14	N <sup>1</sup> / <sub>4</sub>	
Date Established11/6/2006		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
26.50' NE to duplex W/side power pole		
37.72' NW to duplex SW/side power pole		
23.09' SW to "+" corner concrete wingwall		
<b>Section</b> 14		
Date Established 11/6/2006		
Corner <u>W<sup>1</sup>/<sub>4</sub></u>		
Marker Small RR Spike	W1/4	
52.57' NW to "+" north end RCP (P)		
11.56' E to 5/8" iron pin 1' east of edge of pavement		
42.21' SE to "+" south end RCP (P)		

Tuesday, July 13, 2021 Page 22 of 57

Section 14		
Date Established 11/6/2	2006	
Corner <u>CENTER</u>		
Marker Small RR Spike		*
19.83' NW to 5/8" iron pin 2	" west of pavement	 ENTER
18.98' SW to 5/8" iron pin 2	' west of pavement	
43.04' WSW to duplex S/sid	le power pole	

Tuesday, July 13, 2021 Page 23 of 57

Section 15	NW
Date Established 11/6/2006	
Corner NW	
Marker Nail/Shiner	
58.15' NW to "+" NE corner catch basin (P)	
40.48' NE to nail/shiner SW/side power pole	
82.88' SE to duplex SW/side telephone pole	
58.35' SE to right of wav monument	
68.98' SE to duplex NE/side power pole	
Section 15	N¹¼
Date Established11/6/2006	
Corner N <sup>1</sup> / <sub>4</sub>	
Marker Small RR Spike	-
18.42' NNW to PK nail E/side power pole	_
80.08' ESE to duplex NE/side telephone pole	_
51.03' S to PK nail W/side wood post	-
73.58' WSW to duplex NW/side telephone pole	
Section <u>15</u>	
Date Established 11/6/2006	
Corner W <sup>1</sup> / <sub>4</sub>	
Marker Nail/Shiner	W <sup>1</sup> / <sub>4</sub>
30.93' NE to duplex SW/side underground cable marker (loose)	
27.22' SE to "+" in center east wall catch basin (P)	
28.53' SW to "+" in center concrete headwall (P)	_
15.87' NW to "+" in steel guard rail post	

Tuesday, July 13, 2021 Page 24 of 57

Section 15	
Date Established 11/6/2006	
Corner <u>CENTER</u>	
Marker Iron Pin	
24.66' N to "+" S/side metal post	CENTER
17.61' SE to mag nail east end corrugated plastic pipe	e (P)
21.77' SW to mag nail east end corrugated plastic pir	pe (P)

Tuesday, July 13, 2021 Page 25 of 57

Section 16	NW	
Date Established 11/6/2006		
Corner NW		
Marker Nail/Shiner		
49.19' NW to "+" in angle point of concrete headwall (P)		
44.64' NE to duplex SE/side power pole		
43.82' SW to "+" north corner catch basin (P)		
	_	
Section 16		1/4
Date Established11/6/2006		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Nail/Shiner		
54.58' NW to duplex SW/side power pole		
19.85' N to "+" SW corner catch basin (P)		
75.20' NNE to SW corner house foundation		
83.50' NE to SE corner porch foundation		
34.68' SSW to duplex E/side telephone pole		
Section 16		
Date Established 11/6/2006		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike	W1⁄4	
70.05' NE to duplex W/side power pole		
15.98' SSW to 5/8" iron pin 2' west of edge of pavement		
22.44' SE to 5/8" iron pin 2' east of edge of pavement		
	L	J

Tuesday, July 13, 2021 Page 26 of 57

N <sup>1</sup> / <sub>4</sub>
N <sup>1</sup> / <sub>4</sub>
11/4

Tuesday, July 13, 2021 Page 27 of 57

Section 18	NW
Date Established 11/6/2006	
Corner NW	
Marker Small RR Spike	
41.11' NW to nail/shiner NE/side 18" maple	
58.56' NE to "+" in NW cap bolt fire hydrant	
29.72' SE to nail/shiner NW/side power pole	
84.05' N to NE corner Sec. 13. Marion Twp.	
Section 18	N <sup>1</sup> / <sub>4</sub>
Date Established 11/6/2006	
Corner N <sup>1</sup> / <sub>4</sub>	
Marker PK Nail	
28.91' N to duplex W/side power pole	
20.38' N to PK nail west end 8" CMP (P)	
39.77' NE to PK nail east end 8" CMP (P)	
72.00' ESE to duplex NE/side telephone pole	
36.37' S to duplex W/side power pole	
Section 18	
Date Established	
Corner W <sup>1</sup> / <sub>4</sub>	
Marker Capped Iron Pin	W¼
GPS Shot #1533	

Tuesday, July 13, 2021 Page 28 of 57

Section 19	NW	
Date Established 11/6/2006		
Corner NW		
Marker Iron Pin - 1' west of edge of pavement		
28.92' NW to "+" south end 96" CMP arch (P)		
8.29' NW to duplex NE/side power pole		
79.55' N to NE corner Sec. 24. Marion Twp.		
63.32' SE to duplex SW/side power pole	_	
75.88' NNW to duplex S/side wood guard rail post	_	
Section 19	_	N <sup>1</sup> / <sub>4</sub>
Date Established11/6/2006		
Corner _N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
96.13' ENE to duplex S/side power pole		
11.30' S to "+" in concrete headwall (P) (Not at end)		
92.49' WSW to duplex NW/side power pole		
33.00' SW to "+" south end concrete headwall (P)	_	
	_	
	_	
Section 19		
Date Established 11/6/2006		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike	W <sup>1</sup> / <sub>4</sub>	
52.20' SE to NW corner concrete block catch basin	_	
45.50' SW to PK nail in corrugated plastic pipe		
55.54' NNW to duplex E/side power pole	_	
68.52' N to E <sup>1</sup> / <sub>4</sub> Post, Sec. 24, Marion Twp. (No Field Check)		
	_	

Tuesday, July 13, 2021 Page 29 of 57

Section 19		
Date Established <u>11/6/2006</u>		
Corner <u>CENTER</u>		
Marker Iron Pin		·
22.04' NW to 5/8" iron pin	CEN	ΓER
24.30' NE to 5/8" iron pin (bent)		
25.24' SW to "+" north face RR iron post		
29.00' W to PK nail north end 12" CMP (P)		

Tuesday, July 13, 2021 Page 30 of 57

Date Established         11/6/2006           Corner NW         NW           Marker Small RR Spike         38.88' SE to "+" east end RCP           40.11' SE to duplex E/side telephone pole         45.07' SW to PK nail NW/side power pole           31.34' SW to "+" west end RCP (P)         N¼           Section         20           Date Established         11/6/2006           Corner N¼         N¼	
Marker Small RR Spike  38.88' SE to "+" east end RCP  40.11' SE to duplex E/side telephone pole  45.07' SW to PK nail NW/side power pole  31.34' SW to "+" west end RCP (P)  Section 20  Date Established 11/6/2006	
38.88' SE to "+" east end RCP  40.11' SE to duplex E/side telephone pole  45.07' SW to PK nail NW/side power pole  31.34' SW to "+" west end RCP (P)  Section 20  Date Established 11/6/2006	
40.11' SE to duplex E/side telephone pole 45.07' SW to PK nail NW/side power pole 31.34' SW to "+" west end RCP (P)  Section 20	
40.11' SE to duplex E/side telephone pole 45.07' SW to PK nail NW/side power pole 31.34' SW to "+" west end RCP (P)  Section 20	
31.34' SW to "+" west end RCP (P)  Section 20  Date Established 11/6/2006	
Section 20 N1/4  Date Established 11/6/2006	
Date Established 11/6/2006	
Date Established 11/6/2006	
Corner N1/.	
Marker Iron Pin	
34.09' NW to duplex SW/side power pole	
79.35' ENE to duplex NW/side underground cable marker	
Section 20	
Date Established 11/6/2006	
Corner W <sup>1</sup> / <sub>4</sub>	
Marker Small RR Spike W1/4	
Stone is 7.5' west of east edge 12' pavement	
28.39' W to "+" west end RCP (P)	
28.60' E to "+" east end RCP (P)	
62.49' SE to duplex W/side telephone pole	
34.49' NW to duplex NE/side power pole	
42.54' SW to "+" south end RCP (P)	

Tuesday, July 13, 2021 Page 31 of 57

Section 21	NW	
Date Established 11/6/2006		
Corner NW		
Marker RR Spike		
36.74' NE to duplex SE/side power pole		
32.00' ESE to hole punched in east end 60" CSP (P)		
38.17' SE to duplex E/side power pole		
27.13' SW to hole punched in west end 60" CSP (P)		
Section 21		N <sup>1</sup> / <sub>4</sub>
Date Established 11/6/2006		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
30.95' NW to duplex E/side power pole		
71.34' NE to duplex NW/side 24" pine		
42.40' SW to PK nail west end 21" CMP		
	_	
Section 21		
Date Established 11/6/2006		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker RR Spike	W½	
38.47' ENE to "+" north end concrete headwall (P)		
37.42' E to "+" south end concrete headwall (P)		
45.45' SW to mag nail SE/side maple		
17.93' NW to mag nail west end CMP (P)		

Tuesday, July 13, 2021 Page 32 of 57

Section 22	NW
Date Established 11/6/2006	
Corner NW	
Marker Nail/Shiner	
68.37' WSW to mag nail west end corrugated plastic pipe (P)	
48.08' SW to "+" south end RCP (P)	
50.80' NW to "+" north end RCP (P)	
79.71' NNW to duplex W/side power pole	
Section 22	N <sup>1</sup> / <sub>4</sub>
Date Established 11/6/2006	
Corner N <sup>1</sup> / <sub>4</sub>	
Marker Nail/Shiner	
101.98' N to SW corner block house foundation	
128.95' NE to SE corner block foundation	
Section 22	
Date Established11/6/2006	
Corner W <sup>1</sup> / <sub>4</sub>	
Marker Nail/Shiner	W1⁄4
28.18' ENE to "+" north end concrete headwall (P)	
25.95' E to "+" south end concrete headwall (P)	
9.00' SW to 5/8" iron pin 2' west of pavement	
24.73' NW to mag nail in corrugated plastic pipe	

Tuesday, July 13, 2021 Page 33 of 57

Section 23	NW
Date Established <u>11/8/2006</u>	
Corner NW	
Marker Nail/Shiner	
42.72' NW to nail/shiner SE/side power pole	
34.03' NW to "+" north end 60" RCP (P)	
44.81' NE to nail/shiner SW/side power pole	
26.37' SW to "+" south end 60" RCP (P)	
42.11' SW to nail/shiner NE/side power pole	
37.10' SE to nail/shiner SE/side power pole	
Section 23	
Date Established11/8/2006	
Corner W <sup>1</sup> / <sub>4</sub>	
Marker RR Spike	W1⁄4
60.75' NNW to "+" south end concrete headwal	ll (P)
61.23' NNE to "+" SW corner catch basin	
57.92' NNE to duplex W/side power pole	

Tuesday, July 13, 2021 Page 34 of 57

	N <sup>1</sup> ⁄ <sub>4</sub>
Date Established 11/8/2006	
Corner N <sup>1</sup> / <sub>4</sub>	
Marker Small RR Spike	
55.40' ESE to small PK nail NW/side power pole	
63.75' WSW to duplex N/side power pole	
87.60' NNW to SW corner brick house	
20.37' ESE to "+" S/side manhole rim	
Section 24	NE
Date Established 11/8/2006	
Corner NE	
Marker Small RR Spike	
32.00' NW to "+" north end CMP arch (P)	
28.55' SW to "+" south end CMP arch (P)	
36.18' SW to duplex NW/side power pole	
74.70' WSW to duplex NW/side power pole	
Section 24	
Date Established 8/31/2006	E½NE
Corner E <sup>1</sup> / <sub>4</sub> NE	
Marker Small RR Spike	
6.22' NW to iron pin on west ditch bank (New)	
5.18' SW to iron pin on west ditch bank (New)	
27.82' NE to iron pin 2' east of edge of pavement	
26.30' SE to iron pin 2' east of edge of pavement	

Tuesday, July 13, 2021 Page 35 of 57

Section 24		
Date Established 11/8/2006		
Corner W1/4		
Marker RR Spike	W <sup>1</sup> / <sub>4</sub>	
74.85' NE to SW corner house foundation 25.45' NE to "+" east rim of manhole 24.82' SW to "+" south rim of manhole 87.25' SW to NE corner brick house foundation (No Field Check) 34.94' SE to duplex SW/side power pole		
29.95' SW to duplex NW/side power pole		
Section 24  Date Established 11/8/2006  Corner CENTER  Marker RR Spike		
43.49' NW to duplex S/side wood gate post 32.37' SE to duplex NE/side power pole 32.32' SW to duplex NW/side power pole 57.57' SSW to duplex NW/side power pole 27.19' NE to duplex SE/side power pole	CEN	TER
Section 24  Date Established 8/31/2006		
Corner E <sup>1</sup> / <sub>4</sub> Marker Iron Pin - 8" below edge of berm		E1/4
49.53' NNW to "+" north end RCP (P) 60.78' NE to nail/shiner SW/side power pole 35.82' E to duplex N/side telephone pole 7.01' SW to "+" south end RCP (P)		
17.68' W to nail/shiner E/side telephone pole 34.31' E to nail/shiner NW/side power pole		

Tuesday, July 13, 2021 Page 36 of 57

Section 25	NW	
Date Established 8/31/2006		
Corner NW		
Marker RR Spike		
60.00' WNW to duplex S/side telephone pole (No Field Check) 51.29' SW to duplex NW/side power pole 19.67' SW to "+" corner headwall 107.03' WNW to duplex N/side cable marker 69.54' NW to "+" north end RCP		
Section   25     Date Established   11/8/2006     Corner   N <sup>1</sup> / <sub>4</sub>		N <sup>1</sup> / <sub>4</sub>
Marker RR Spike		
31.46' SW to "+" south end RCP (P)  37.52' SW to small PK nail NE/side power pole  43.74' NW to "+" north end RCP (P)  42.56' SE to mag nail east end corrugated plastic pipe (P)		
Section 25  Date Established 8/30/2006  Corner NE  Markey DD C 1		NE
Marker RR Spike		
42.38' SW to "+" south end RCP (P) 50.32' NW to "+" north end RCP (P) 46.39' NW to GPS Monument (P) 26.42' NE to duplex NW/side power pole		
32.52' SE to duplex W/side power pole		I
37.87' SW to duplex N/side power pole		
33.50' N to SW corner, Sec. 30. Jackson Twp Wood County		

Tuesday, July 13, 2021 Page 37 of 57

Section 25	
Date Established 8/30/2006	
Corner _W <sup>1</sup> / <sub>4</sub>	
Marker RR Spike	W1⁄4
33.42' NE to duplex SE/side power pole	
47.42' SE to mag nail east end 24" CMP (P)	
26.32' SW to "+" south end RCP (P)	
33.95' NW to "+" north end RCP (P)	
35.85' NW to duplex SW/side (P)	
Section 25	
Date Established 11/8/2006	
Corner CENTER	
Marker Small RR Spike	
Set concrete nails 6' north and east 29.52' NW to duplex E/side power pole 26.29' NW to "+" north end RCP (P) 41.16' SE to "+" SE corner catch basin (P)	CENTER
25.80' SW to "+" south end RCP (P)	
32.64' SW to "+" east end RCP (P)	
Section 25	
Date Established 8/30/2006	
Corner E <sup>1</sup> / <sub>4</sub>	
Marker Small RR Spike	E½
41.02' NW to "+" north end RCP (P) 53.20' NE to PK nail SW/side telephone pole 31.37' SE to duplex NE/side power pole 56.91' NE to "+" NE corner catch basin (P)	
35.44' SW to "+" south end RCP (P)	
26.77' N to Wood Co. corner	

Tuesday, July 13, 2021 Page 38 of 57

Section 26	NW
Date Established 11/8/2006	
Corner NW	
Marker Small RR Spike	
72.60' WNW to duplex SW/side power pole 32.15' SE to dupex SW/side power pole 37.01' SW to duplex NW/side power pole 56.22' WSW to "+" west end concrete pipe (P)	
Section 26	
Date Established 11/8/2006	
Corner W1/4	
Marker Small RR Spike	W1⁄4
17.30' NE to 5/8" iron pin at east edge of pavement 20.01' NW to 5/8" iron pin at west edge of pavement 57.48' SE to duplex W/side power pole	

Tuesday, July 13, 2021 Page 39 of 57

Section 27	NW
Date Established 11/8/2006	
Corner NW	
Marker Nail/Shiner	
36.85' NE to nail/shiner SW/side power pole	
47.47' SE to nail/shiner W/side telephone pole	
39.89' SW "+" south end CMP (P) (12" from end)	
34.63' NW to "+" north end CMP (P)	
Section 27	N <sup>1</sup> ⁄ <sub>4</sub>
Date Established 11/8/2006	
Corner N <sup>1</sup> / <sub>4</sub>	
Marker Capped Iron Pin	
82.15' WNW to duplex S/side power pole	
131.95' ENE to duplex S/side power pole	
90.18' ESE to duplex SW/side power pole (7/14/82)	
24.20' N to duplex W/side wood post	
Section 27	
Date Established11/8/2006	
Corner W <sup>1</sup> / <sub>4</sub>	
Marker Nail/Shiner	W1⁄4
92.93' NE to NW corner block house foundation	
74.23' NE to SW corner block house foundation	
27.06' SW to mag nail south end corrugated plastic pipe (P) (1' from end	
27.82' NW to mag nail south end corrugated plastic pipe (P) (1' from en	

Tuesday, July 13, 2021 Page 40 of 57

Section 28	NW	
Date Established 11/8/2006		
Corner NW		
Marker RR Spike		
33.61' NE to PK nail NW/side power pole		
51.89' SSE to PK nail W/side telephone pole		
23.92' SW to hole punched in south end 60" CMP (P)		
31.90' NW to hole punched in north end 60" CMP (P)		
23.14' NNW to PK nail E/side brace pole		
<b>Section</b> 28	N <sup>1</sup> ⁄ <sub>4</sub>	
Date Established 11/8/2006		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike - 4" below edge of pavement		
25.19' NW to 5/8" iron pin on north edge of pavement		
28.05' NE to duplex W/side power pole		
Section 28		
Date Established 11/8/2006		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Removed loose RR Spike	W1⁄4	
Set 5/8" Iron Pin from PK's 6' NW and SW. Iron Pin is 1.5' west of pave		
146.44' NNE to duplex W/side power pole		
22.70' E to duplex W/side wood post		
132.48' SSE to duplex W/side power pole		

Tuesday, July 13, 2021 Page 41 of 57

Section 29	NW	
Date Established 11/8/2006		
Corner NW		
Marker RR Spike		
29.31' ESE to "+" NE bridge wing (P)		
27.90' SE to "+" face of east bridge rail		
33.23' SSW to "+" in SW bridge wing (P)		
22.01' WSW to "+" NW bridge wing (P)		
16.53' SW to USGS benchmark tablet		
36.92' NW to duplex SW/side power pole		
Section 29	N <sup>1</sup> /4	
Date Established11/8/2006		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
28.29' NW to "+" in west end of concrete headwall (P)		
23.73' NNE to "+" in east end of concrete headwall (P)		
16.40' SSE to "+" in east end of concrete headwall (P)		
22.54' SW to "+" in west end of concrete headwall (P)		
	_	
Section 29		
Date Established11/8/2006		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin	W1⁄4	
Surveyor's Note: I.P. is moving with ditch bank to west.		
Check north-south alignment		
43.15' SE to duplex NE/side power pole		
16.18' SW to PK nail west end 12" CMP (P)		
28.93' NW to 5/8" iron pin 4' east of pavement		

Tuesday, July 13, 2021 Page 42 of 57

Section 30	NW	
Date Established 11/9/2006		
Corner NW		
Marker Small RR Spike		
58.23' N to NE corner, Sec. 25, Marion Twp. (8/21/82)		
66.44' NW to "+" chiseled in south end of CMP arch (P)		
124.26' N to duplex E/side power pole		
58.13' SE to mag nail east end corrugated plastic pipe (P)		
41.25' SSW to duplex E/side power pole		
8.03' NW to duplex E/side guard rail post (Loose)		
Section 30	N <sup>1</sup> /	<b>/</b> 4
Date Established10/1/2014		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
33.86' N to "+" in 2" steel post (leaning)		
17.74' S to "+" in west end 48" RCP		
81.36' ESE to "+" 2' west of east end 48" RCP		
Section 30		
Date Established11/9/2006	<b> </b>	
Corner W1/4 NW	W <sup>1</sup> / <sub>4</sub> NW	
Marker RR Spike		
61.27' NNW to "+" SW bridge wing (P)		
55.51' NNW to "+" SE bridge wing (P)		
82.51' NNW to duplex E/side power pole		
73.05' SSE to "+" NW corner concrete block catch basin (P)		
64.72' SSW to mag nail west end corrugated plastic pipe (P)		

Tuesday, July 13, 2021 Page 43 of 57

Section 30	
Date Established 11/8/2006	
Corner W1/4	
Marker Small RR Spike	W <sup>1</sup> / <sub>4</sub>
68.63' N to E¼ post, Sec. 25, Marion Twp. 52.87' SSE to "+" NW corner catch basin (P) 19.58' SSW to duplex NW/side power pole 46.47' SSW to mag nail in corrugated plastic pipe (P)	-
<b>Section</b> 30	
Date Established 12/4/2006	
Corner OTHER	
Marker RR Spike - 2" Below Surface	
46.93' SSE to "+" NW corner concrete slope riser on catch basin (P) 21.75' SSW to duplex E/side power pole	10.835 ch.

Tuesday, July 13, 2021 Page 44 of 57

Section 31	NW	
Date Established 11/9/2006		
Corner NW		
Marker Iron Pin - 4' west of pavement		
23.33' NNW to PK - S/side power pole		
80.86' N to center of cornerstone NE corner, Sec. 36. Marion Twp. (7/8/		
17.03' W to "+" in south end CMP (P)		
88.35' NW to mag nail SE/side power pole		
Section 31		N <sup>1</sup> / <sub>4</sub>
Date Established 11/9/2006		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
29.23' SSE to duplex E/side power pole		
22.23' S to PK nail north end 15" CSP (P)  18.50' S to mag nail west end corrugated plastic pipe (P)		
69.45' ESE to mag nail east end corrugated plastic pipe (P)		
Section <u>31</u>		N¼NE
Date Established 11/9/2006		
Corner N <sup>1</sup> / <sub>4</sub> NE		
Marker Small RR Spike		
39.16' SE to 5/8" iron pin on south ditch bank		
28.16' S to 5/8" iron pin on south ditch bank		
67.47' WSW to duplex SE/side power pole		
		•

Tuesday, July 13, 2021 Page 45 of 57

Section 31	
Date Established 11/9/2006	
Corner <u>W<sup>1</sup>/<sub>4</sub></u>	
Marker Small RR Spike	W1⁄4
72.69' NNW to duplex E/side power pole	
133.98' SSW to duplex E/side power pole	
40.70' N to E <sup>1</sup> / <sub>4</sub> post. Sec. 36. Marion Twp.	
11.00' SW to 5/8" iron pin 2' west of pavement	
23.15' SE to 5/8" iron pin 2' west of pavement	
Section 31	
Date Established11/9/2006	
Corner SW	
Marker RR Spike at east edge of pavement	
Set new PK's 6' SW and NW	
55.72' NNW to shiner SE/side power pole	
77.23' WNW to SE corner house foundation	
76.48' SSE to "+" in bridge wing	sw
16.60' E to center of GIS monument (P)	
Section <u>31</u>	
Date Established 11/9/2006	
Corner <u>S<sup>1</sup>/4</u>	
Marker Iron Pin	
Iron Pin is 3' north of the south edge of stone road	
32.53' ENE to "+" in NW bridge wing (P)	
55.86' ESE to "+" in SW bridge wing (P)	
13.68' SSW to "+" NE corner catch basin (P)	S1/4

Tuesday, July 13, 2021 Page 46 of 57

Section 32	NW	
Date Established 11/9/2006		
Corner NW		
Marker Small RR Spike		
47.74' NW to "+" north end RCP (P)		
42.83' NE to duplex SE/side buried cable marker		
44.84' SE to duplex NE/side power pole		
49.30' SW to "+" south end RCP (P)		
Section 32	N <sup>1</sup> ⁄ <sub>4</sub>	
Date Established11/9/2006		
Corner <u>N<sup>1</sup>/<sub>4</sub></u>		
Marker Small RR Spike		
14.00' NW to 5/8" iron pin 2' north of pavement		
16.94' SW to 5/8" iron pin 2' south of pavement		
32.49' SSE to mag nail south end CSP (P)		
33.82' NNE to mag nail north end CSP (P)		
Section 32		
Date Established 11/9/2006		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike	W <sup>1</sup> / <sub>4</sub>	
45.26' NE to duplex S/side power pole		
63.58' SE to duplex SW/side 12" tree		
28.16' SE to "+" W/side metal mailbox post		
44.98' NW to "+" west end metal pipe (P)		

Tuesday, July 13, 2021 Page 47 of 57

Section 32	
Date Established11/9/2006	
Corner SW	
Marker RR Spike	
33.70' NW to "+" north end RCP (P) 77.84' ENE to duplex S/side telephone pole 107.85' ESE to duplex SW/side telephone pole 83.50' SSE to duplex NE/side brace poel	SW
23.14' SW to "+" south end RCP (P)	
36.01' NW to duplex S/side power pole	
Section 32 Date Established 11/9/2006	
Corner S <sup>1</sup> / <sub>4</sub>	
Marker RR Spike	
83.92' WNW to duplex S/side power pole 14.19' NW to "+" west end concrete headwall (P) 11.35' NNW to "+" east end concrete headwall (P) 21.23' SSW to "+" east end concrete headwall (P)	S1⁄4
22.87' SW to "+" west end concrete headwall (P)	

Tuesday, July 13, 2021 Page 48 of 57

Section 33	NW	
Date Established 11/9/2006		
Corner NW		
Marker Small RR Spike		
55.65' SE to mag nail east end corrugated plastic pipe (P)		
49.04' SW to mag nail west end corrugated plastic pipe (P)		
32.97' NW to 5/8" iron pin 2' north of pavement		
36.99' NE to 5/8" iron pin 2' north of pavement		
Section 33	N <sup>1</sup> / <sub>2</sub>	, 1
Date Established11/9/2006_		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin		
28.72' N to duplex W/side wood post		
7.60' S to "+" south end 12" CIP (P)		
19.83' S to PK nail north end 18" CMP (P)		
69.45' W to mag nail south end corrugated plastic pipe (P)		
Section 33		
Date Established 11/9/2006		
Corner W1/4		
Marker RR Spike	W½	
55.16' SE to mag nail east end aluminum pipe (P)		
58.60' SW to "+" in top ag. inlet (P)		
20.45' W to mag nail west end CMP (P)		

Tuesday, July 13, 2021 Page 49 of 57

Section 33	
Date Established 11/9/2006	
Corner SW	
Marker RR Spike	
64.77' WSW to "+" east end concrete headwall (P)	
65.38' WNW to "+" east end concrete headwall (P)	
70.10' ESE to "+" west end concrete headwall (P)	
88.95' ENE to duplex S/side power pole	SW
Section 33	
Date Established 11/13/2006	
Corner <u>S<sup>1</sup>/4</u>	
Marker Drove 5/8" Iron Pin - Set concrete nails 6' N and W	
Found small PK on surface. No RR Spike found. Removed PK nail.	
66.44' WNW to duplex NE/side power pole	
29.91' NE to "+" west end concrete headwall (P)	
46.43' SE to "+" west end concrete headwall (P)	S1/4
38.95' ENE to "+" north end RCP (P)	

Tuesday, July 13, 2021 Page 50 of 57

Section 34	NW	
Date Established 10/16/2015		
Corner NW		
Marker RR Spike	-	
39.18' NE to duplex on NW side of power pole	-	
52.61' NW to "+" in RCP (P)	-	
47.31' SW to "+" in RCP (P)	-	
Section 34		N <sup>1</sup> / <sub>4</sub>
Date Established 11/13/2006		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike	-	
20.27' N to PK nail W/side power pole	_	
21.36' N to duplex E/side wood post	_	
34.26' SW to "+" SE bridge wing	-	
18.72' SW to "+" NE bridge wing		
40.70' SW to "+" NW bridge wing		
57.96' SW to duplex NW/side power pole		
Section 34		
Date Established 9/28/2017		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Mag Nail over RR Spike (* = ties to wrong point)	W1/4	
30.42' SE to "x" in NE corner catch basin		
28.11' SE to Mag Nail in south end corr. plastic pipe		
31.00' E to H. Behrman property pin		
35.64' NE to Mag Nail in north end corr. plastic pipe		
31.69' SE to + NE cor. CB:35.85' NE mag nail corr. pl. 2' from N/end *		
28.04' SW to mag nail west end corrugated plastic pipe at ground line*		
29.25' SE to mag nail in corrugated plastic pipe 2' from south end (P)*		

Tuesday, July 13, 2021 Page 51 of 57

Section	34		
Date Establish	ed <u>11/13/2006</u>		
Corner SW			
Marker Nai	/Shiner		
25.16' NW to	"+" east end banister	_	
97.10' WNW	to nail/shiner SE/side power pole	_	
61.40' NW to	nail/shiner SE/side power pole		
73.80' ENE to	"+" SE corner catch basin (P)	sw	
40.55' SE to "	+" NE corner catch basin (P)		
22.80' SW to	"+" north face concrete banister		
29.41' SW to	"+" west end RCP (P)		
Section	34		
Date Establish	ed <u>11/13/2006</u>		
Corner S1/4			
Marker Iron	Pin and PK's 6' NE & NW		
24.53' NW to	5/8" iron pin on north edge of pavement	_	
26.60' NE to 5	5/8" iron pin on north edge of pavement	_	
82.84' E to irc	n pin at N <sup>1</sup> / <sub>4</sub> post, Sec. 3, Van Buren Twp., Putnam Co. (8	_	
53.27' ESE to	"+" west end RCP (P)		61/4

Tuesday, July 13, 2021 Page 52 of 57

Section 35	NW	
Date Established 11/13/2006		
Corner NW		
Marker RR Spike		
27.26' NE to duplex SW/side power pole		
60.31' ESE to duplex SW/side power pole		
17.98' SE to "+" east end concrete headwall		
76.93' SSE to duplex W/side power pole	_	
34.25' SW to "+" south end concrete headwall	_	
Section 35	_	N <sup>1</sup> / <sub>4</sub>
		IN 74
Date Established 5/17/2013		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike set - no stone found		
28.00' SE to mag nail north side of power pole		
16.45' SSW to chiseled "x" south end RCP		
29.48' NNW to chiseled "x" north end RCP		
19.97' NE to iron pin along road		
	_	
	_	
Section 35		
Date Established 11/13/2006		
Corner _W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike	W <sup>1</sup> / <sub>4</sub>	
46.13' NE to mag nail NW/side 18" maple		
77.20' NE to SW corner block house foundation		
53.00' SSE to duplex W/side power pole		
31.54' W to mag nail S/side 12" hickory	[	
	_	

Tuesday, July 13, 2021 Page 53 of 57

Section 35	
Date Established 11/13/2006	
Corner SW	
Marker RR Spike	
53.72' NW to "+" in north end RCP (P)	
79.61' ENE to duplex S/side telephone pole	
34.16' SE to "+" in concrete headwall (P)	
43.80' SE to duplex W/side power pole (P)	SW
22.15' SW to "+" in concrete headwall (P)	
Section 35	
<b>Date Established</b> 11/13/2006	
Corner S <sup>1</sup> / <sub>4</sub>	
Marker Small RR Spike	
22.69' NW to 5/8" iron pin at north edge of pavement	
54.20' NE to 5/8" iron pin at north edge of pavement	
15.29' SW to 5/8" iron pin 2' south of pavement	
	S1/4
	<u> </u>

Tuesday, July 13, 2021 Page 54 of 57

Section 36	NW	
Date Established 8/31/2006		
Corner NW		
Marker Small RR Spike		
38.06' NW to PK nail north end CMP (P)		
37.69' SE to duplex NE/side underground cable post		
38.77' SW to PK nail south end CMP (P)		
48.20' SW to duplex NW/side power pole		
46.48' SE to "+" south corner catch basin (P)		
Section 36		N <sup>1</sup> / <sub>4</sub>
Date Established 8/31/2006		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
<u> </u>		
22.74' S to "+" south end RCP (P)		
33.67' N to "+" north end RCP (P)		
11.93' S to duplex W/side mail box post		
44.06' ESE to mag nail east end plastic pipe (P)		
35.37' ENE to duplex NW/side buried cable marker (No Field C	check)	
28.90' SE to duplex SW/side buried cable marker (No Field Che	eck)	
Section 36		NE.
Date Established 8/31/2006		
Corner NE		
Marker Small RR Spike		
39.49' E to "+" W/side round catch basin (P)		
39.07' SW to duplex NW/side power pole		
39.12' NW to "+" north end concrete pipe		
31.38' SW to "+" south end CMP (P)		
44.99' NW to duplex SW/side brace pole		

Tuesday, July 13, 2021 Page 55 of 57

Section 36		
Date Established 8/31/2006		
Corner <u>W<sup>1</sup>/<sub>4</sub></u>		
Marker Small RR Spike	W1/4	
31.15' W to duplex N/side power pole		
14.95' W to PK nail west end 8" CMP (P)		
24.27' ESE to "+" SE corner catch basin (P)		
23.18' NE to iron pin 3' east of edge of pavement		
Section 36		
Date Established 8/31/2006		
Corner <u>E<sup>1</sup>/<sub>4</sub></u>		
Marker RR Spike		E1/2
26.04' W to PK nail east end 8" CMP (P)		
9.88' NW to iron pin 0.5' west of edge of pavement		
25.85' NE to "+" SE corner catch basin (P)		
19.24' SW to "+" west end RCP (P)		
4.96' N to Wood Co. corner		
Section 36		
Date Established 8/31/2006		
Corner SW		
Marker Small RR Spike		
44.46' NW to duplex NE/side power pole		
38.93' NW to "+" north end concrete pipe		
16.88' SSW to "+" east end concrete headwall		
34.62' SW to "+" west end concrete headwall	SW	

Tuesday, July 13, 2021 Page 56 of 57

Section	36	
<b>Date Establis</b>	shed <u>8/31/2006</u>	
Corner S1/4		
Marker RF	R Spike	
	duplex NW/side power pole	
73.34' SE to	duplex SW/side power pole	
21.50' NW to	o iron pin at north edge of pavement	
2645.27' E to	o SE corner Sec. 36. Bartlow Twp. (8/18/82)	S1/4
Section	36	
<b>Date Establis</b>	shed <u>8/31/2006</u>	
Corner <u>SE</u>		
Marker RF	R Spike	
39.69' NE to	duplex NW/side power pole	
39.31' SW to	o "+" west end RCP (P)	
32.03' SE to	"+" east end RCP (P)	
36.75' SSE to	to Hancock Co. Monument (P)	SE

Tuesday, July 13, 2021 Page 57 of 57