| Section | 8 | N½ SR 110 |
|-----------|--|-------------------|
| Corner | N½ | 10/4 |
| Date | 7/27/2010 | Twp. Rd. 5A |
| Marker | Nail/Shiner | |
| 29.62' NE | E to chiseled "+" in north end concrete pipe (P) | |
| 23.29' SE | to chiseled "+" in south end concrete pipe (P) | |
| 69.00' SV | V to mag nail NW/side walnut tree | |
| 63.12' SE | to mag nail N/side walnut tree | |
| Section | 8 | SR 110 |
| Corner | CENTER | JSK 110 |
| Date | 7/27/2010 | Twp. Rd. 5A |
| Marker | RR Spike | |
| 49.48' SV | V to duplex E/side power pole | CENTER |
| 10.61' NE | E to 5/8" iron pin 18" east of EP | |
| 10.08' SE | E to 5/8" iron pin 18" east of EP | |
| | | |

Tuesday, July 13, 2021 Page 1 of 52


| | 9 | NW | |
|--|---|------|--|
| Corner | NW | INVV | |
| Date | 7/27/2010 | | |
| Marker | Nail/Shiner | | |
| 35.21' NN | NW to duplex E/side pedestal post (loose) | | |
| 27.64' S t | to nail/shiner N/side power pole | | |
| 34.08' SV | V to near face MTEL plastic riser | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 9 | | |
| | 9 N1/ | N1/4 | |
| Corner | N½ | N¹¼ | |
| Section Corner Date | | N½ | |
| Corner | N½ | N¹¼ | |
| Corner Date Marker | N½ 7/27/2010 | N1/4 | |
| Corner Date Marker 71.80' NE | N½ 7/27/2010 Nail/Shiner | N½ | |
| Corner Date Marker 71.80' NE 35.31' SE | N ¹ / ₄ 7/27/2010 Nail/Shiner to "+" NW corner concrete slab (P) | N½ | |
| Corner Date Marker 71.80' NE 35.31' SE | N½ 7/27/2010 Nail/Shiner E to "+" NW corner concrete slab (P) E to mag nail W/side wood anchor post | N1/4 | |

Tuesday, July 13, 2021 Page 2 of 52


| Section | 10 |
|-------------|--|
| Corner | N ¹ / ₄ |
| Date | 3/26/2018 |
| Marker | Stone - 3" wide x 8" long x 24"+ in depth. |
| Top of Sto | ne protrudes 6"± above ground line. |
| 1" IP on N | side of stone for locating purposes only |
| Witness p | ost placed on N side of stone. Old ties are gone. |
| Stone had | slid on bank and was moved back to recorded |
| distance o | f 46.03' on line between old location of stone and |
| ODOT Nai | l/shiner on SR 65. |
| "X" was cut | t into high point of stone |

| C/L SR 65 | 46.03' |
|-----------|--------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

| Section | 10 |
|-------------|---|
| Corner | N¼ NE |
| Date | 3/10/2021 |
| Marker | Stone w/iron pipe on North side. Witness Post 1' north of stone |
| 94.60' S to | mag nail in pavement of SR 65 |
| Ties to sto | ne: 12.18' SW to PK nail NW/side 8" Locust |
| 27.13' S to | PK nail north side 24" Locust |
| 13.55' SW | to PK nail north side 24" Locust |
| Refer to S | tate Ties for Highway points. |
| | |



| Corner OTHER Date 11/8/2017 Marker PK Nail on Centerline of 3A 28.07' NW to duplex east side of GR post 37.25' SE to duplex SW/side power pole 42.31' SW to SSE bolt on lower flange of fire hydrant that is leaning to the north 2.24' ESE to SR 65 PI (See State Ties) 66.41' W to point 1/4 mi. from section line | Section | 10 |
|---|-------------|---|
| Marker PK Nail on Centerline of 3A 28.07' NW to duplex east side of GR post 37.25' SE to duplex SW/side power pole 42.31' SW to SSE bolt on lower flange of fire hydrant that is leaning to the north 2.24' ESE to SR 65 PI (See State Ties) | Corner | OTHER |
| 28.07' NW to duplex east side of GR post 37.25' SE to duplex SW/side power pole 42.31' SW to SSE bolt on lower flange of fire hydrant that is leaning to the north 2.24' ESE to SR 65 PI (See State Ties) | Date | 11/8/2017 |
| 37.25' SE to duplex SW/side power pole 42.31' SW to SSE bolt on lower flange of fire hydrant that is leaning to the north 2.24' ESE to SR 65 PI (See State Ties) | Marker | PK Nail on Centerline of 3A |
| 42.31' SW to SSE bolt on lower flange of fire hydrant that is leaning to the north 2.24' ESE to SR 65 PI (See State Ties) | 28.07' NW | / to duplex east side of GR post |
| that is leaning to the north 2.24' ESE to SR 65 PI (See State Ties) | 37.25' SE | to duplex SW/side power pole |
| 2.24' ESE to SR 65 PI (See State Ties) | 42.31' SW | / to SSE bolt on lower flange of fire hydrant |
| | that is lea | ning to the north |
| 66.41' W to point 1/4 mi, from section line | 2.24' ESE | to SR 65 PI (See State Ties) |
| 1 1 | 66.41' W | to point 1/4 mi. from section line |



Tuesday, July 13, 2021 Page 3 of 52

| Section | 10 | | |
|-------------|---|-------|-----------|
| Corner | W ¹ / ₄ | | |
| Date | 7/27/2010 | | |
| | Nail/Shiner | | |
| Marker | | W½ | |
| | E to sawed "+" in NW corner catch basin (P) | | |
| | V to sawed "+" in NE corner of catch basin (P) to mag nail S/side pine tree | | |
| 40.44 ** | to may nail orside pine tree | | |
| | | | |
| | | | • |
| | | | |
| | | | |
| | | | |
| Section | 10 | | |
| Corner | CENTER | | |
| | 9/28/1993 | | |
| Date | | | |
| Marker | Iron Pin | | * |
| | to 30d spike S/side 8" tree | | CENTER |
| Refer to 0 | Old Ties for additional information. | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | 10 | | |
| Section | | 2 | AL SR 65 |
| Corner | N¼ SE | (3.5) | V-50/30 |
| Date | 7/24/2010 | | 85 |
| Marker | Iron Pin over Stone | | C/L RD 3A |
| 61.66' E 1 | to RR Spike in c/l Road 3A | | x |
| See Old | Ties for N¼ SE. | | |
| | | | |
| | | | |
| | | | |
| | | | |

Tuesday, July 13, 2021 Page 4 of 52

| Section | 10 | · |
|-----------|-----------------------------------|---|
| Corner | OTHER | |
| Date | 7/27/2010 | |
| Marker | RR Spike | |
| 26.05' ES | SE to mag nail N/side 15" tree | - |
| 27.78' NV | W to mag nail in plastic pipe (P) | |
| 27.48' SV | W to mag nail in plastic pipe (P) | |
| | | |
| | | |



Tuesday, July 13, 2021 Page 5 of 52

65.35' SE to mag nail east end 12" N12 drive pipe (P)

| Section | 11 | | |
|---|---|----|--|
| section | | NW | |
| Corner | NW | | |
| Date | 10/10/2018 | | |
| Marker | Stone | | |
| Ties are g | gone | | |
| Metal she | ed is gone | | |
| Point app | ears to lie under edge of concrete slab/railing | | |
| covered v | vith a pile of wood | | |
| Surveys Vol. 12, Pg. 138; Vol. 13, Pg. 247; | | | |
| Vol. 18, F | g. 130, call out NW corner. | | |
| | | | |

| | | - | |
|------------|---|-------------------------------|--|
| Section | 11 | N ¹ / ₄ | |
| Corner | N1/4 | IN /4 | |
| Date | 10/2/2018 | | |
| Marker | Stone - Found flush with ground, cut "X" in high pt. of stone | | |
| 7.40' N to | nail/shiner S/side power pole (Not Plumbed) | | |
| 7.69' N to | nail/shiner E/side power pole (Not Plumbed) | | |
| 49.00' NE | to SW corner brick veneer garage | | |
| 22.10' S t | o ODOT nail/shiner C/L SR 65 | | |
| 54.74' S t | o nail/shiner N/side power pole (Not Plumbed) | | |
| 59.00' NV | V to nail/shiner E/side leaning light pole (Not P) | | |

Tuesday, July 13, 2021 Page 6 of 52

| Section | 12 | | Ī |
|--|---|--------|------|
| Corner | W¹⁄₄ | | |
| Date | 7/27/2010 | | |
| Marker | Small RR Spike | W1⁄4 | |
| 25.41' W | SW to mag nail S/side 24" tree | 11,7,1 | |
| 39.01' SV | V to PK nail NE/side power pole | | |
| 36.40' NE | to duplex NE/side power pole | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 12 | | T |
| Section Corner | 12 E½ | | |
| | | | |
| Corner | E1/4 | | E1/2 |
| Corner Date Marker | E¼ 7/27/2010 | | E½ |
| Corner Date Marker 32.25' SV | E½ 7/27/2010 RR Spike | | E1/2 |
| Corner Date Marker 32.25' SV 41.10' NV | E1/4 7/27/2010 RR Spike V to sawed "+" south end CIP (P) | | E½ |
| Corner Date Marker 32.25' SV 41.10' NV | 7/27/2010 RR Spike V to sawed "+" south end CIP (P) V to duplex NE/side power pole | | E1/2 |

Tuesday, July 13, 2021 Page 7 of 52

| NE |
|----|
| |
| |
| |
| |
| |
| |
| |
| |
| _ |

Tuesday, July 13, 2021 Page 8 of 52

| Section | 13 | | |
|--|--|------|-----|
| Corner | W1/4 | | |
| Date | 7/26/2010 | | |
| Marker | Small RR Spike | W1⁄4 | |
| 64.09' NN | NW to mag nail west end plastic pipe (P) | | |
| 52.14' SS | SW to "+" south end CMP (P) | | |
| 16.79' W | to north end CMP (P) | | |
| 65.28' NN | NE to SE corner CB (P) | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 13 | | |
| Section Corner | 13 E1⁄4 | | |
| | | | |
| Corner | E1⁄4 | | |
| Corner Date Marker | E1⁄4 7/26/2010 | | E1/ |
| Corner Date Marker 29.79' ES | E1/4 7/26/2010 RR Spike | | E½ |
| Corner Date Marker 29.79' ES 44.14' SE | E1/4 7/26/2010 RR Spike SE to "+" north end 12" RCP (P) | | E½ |
| Corner Date Marker 29.79' ES 44.14' SE | E1/4 7/26/2010 RR Spike SE to "+" north end 12" RCP (P) E to "+" south end 12" RCP (P) | | E½ |

Tuesday, July 13, 2021 Page 9 of 52

| Castian | 14 | |
|----------|--|------|
| Section | NW | NW |
| Corner | | |
| Date | 7/26/2010 | |
| Marker | Small RR Spike | |
| | to duplex E/side power pole (P) | |
| | to mag nail NW/side maple tree | |
| 51.62 50 | V to duplex NW/side power pole (P) | |
| | | |
| | | |
| | | |
| | | |
| | | |
| Section | 14 | |
| Corner | N¼ NW | N¼NW |
| Date | 9/30/1992 | |
| Marker | RR Spike | |
| | to iron pin and witness post (P) | |
| | V to 5/8" iron pin at north edge of pavement | |
| | E to 5/8" iron pin at north edge of pavement | |
| | | |
| - | | |
| | | |
| | | |
| | | |
| | | |
| Section | 14 | N11/ |
| Corner | N1⁄4 | N1⁄4 |
| Date | 7/26/2010 | |
| Marker | Iron Pin | |
| | to 5/8" iron pin at south edge of pavement | |
| | V to 5/8" iron pin at north edge of pavement | |
| | EE to mag nail east end plastic pipe (P) | |
| | | |
| | | |
| | | |

Tuesday, July 13, 2021 Page 10 of 52

| Section | 15 | | 1 |
|-----------|--|------|------------|
| Corner | NW | NW | |
| Date | 7/26/2010 | | |
| Marker | Nail/Shiner | | |
| | V to punch hole in NNE flange bolt of fire hydrant | | |
| | to nail/shiner NE/side power pole | | |
| - | V to nail/shiner E/side brace pole | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 15 | | hu/AIE A |
| Corner | N¼ NE | | N¼NE |
| | 9/26/2016 | | |
| Date | | | C/L RD. 3A |
| Marker | Stone just below surface | | <u> </u> |
| | in on south side of stone (locating purposes only) | | Y |
| | IE to duplex south side of power pole | | |
| - | to duplex in SE root of 12" hickory tree | | |
| | o railroad spike in intersection of roads Q & 3A | | |
| 61.38' NE | to 5/8" rebar on west side of pavement | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 15 | | |
| Corner | W1⁄4 | | |
| Date | 7/26/2010 | | |
| Marker | Nail/Shiner | W1⁄4 | |
| 39.14' SV | V to "+" south end aluminum CMP | | |
| | to"+" north end aluminum CMP | | |
| | W to duplex NW/side power pole | | |
| | o mag nail east rim meter pit (P) | | |
| 100 20' N | NE to duplex W/side pedestal post (1992 tie) | | |

Tuesday, July 13, 2021 Page 11 of 52

| | <u>, </u> | | |
|-----------|--|------|--|
| Section | 16 | NW | |
| Corner | NW | | |
| Date | 7/27/2010 | | |
| Marker | Small RR Spike | | |
| 20.18' NV | V to 5/8" iron pin on north edge of pavement | | |
| 19.58' NE | to 5/8" iron pin on north edge of pavement | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 16 | | |
| Corner | N¼ | N¼ | |
| Date | 7/26/2010 | | |
| Marker | Small RR Spike | | |
| | | | |
| | V to 5/8" iron pin at north edge of pavement E to 5/8" iron pin at north edge of pavement | | |
| | o capped iron pin | | |
| _ | to mag nail NE/side 8" willow tree | | |
| - | - | | |
| | | | |
| | | | |
| | | | |
| - | | | |
| Section | 16 | | |
| Corner | W1/4 | | |
| Date | 10/27/2017 | | |
| Marker | Stone with Iron Pipe beside it. | W1⁄4 | |
| Placed st | eel witness post west of stone. | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

Tuesday, July 13, 2021 Page 12 of 52

| | • | | |
|-----------|--|-------------------------------|-------------|
| Section | 17 | N¹⁄4 | Twp. Rd. Q |
| Corner | N½ | 11/4 | |
| Date | 7/27/2010 | | |
| Marker | RR Spike | | |
| 30.02' SE | to duplex S/side cable marker post (leaning south) | Twp. Rd. P3 | |
| | V to duplex NE/side power pole | | |
| 27.51' SV | V to mag nail north end plastic pipe | | Twp. Rd. 5A |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 17 | | |
| Corner | W1⁄4 | | |
| Date | 7/27/2010 | | |
| Marker | Small RR Spike | W ¹ / ₄ | |
| 49.74' EN | IE to sawed "+" in west bridge abutment | | |
| | E to sawed "+" in west bridge abutment | | |
| | to duplex W/side telephone pole | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| - | | | |
| Section | 17 | | Twp. Rd. Q |
| Corner | CENTER | | |
| Date | 7/27/2010 | | |
| Marker | RR Spike | | |
| 47.43' NV | V to SE corner brick house | Twp. Rd. P3 | CENTER |
| 28.51' NE | to near face MTEL plastic riser | | |
| 33.45' SV | V to sawed "+" in SE corner catch basin | | Twp. Rd. 5A |
| 39.37' SV | V to duplex NW/side power pole | | |
| | | | |
| | | | |

Tuesday, July 13, 2021 Page 13 of 52

| Section | 18 | NW | |
|------------|---|----|----------|
| Corner | NW | | |
| Date | 6/29/2010 | | |
| Marker | RR Spike | | |
| 49.23' NE | to suplex NW/side power pole | | |
| 19.88' E t | to 5/8" iron pin (P) | | |
| 164.20' S | to NE corner, Sec. 13, Harrison Twp. | | |
| 58.62' EN | IE to duplex S/side 24" maple | | |
| | | | |
| Section | 18 | | |
| Corner | N¼ NE | | |
| | 6/29/2010 | | |
| Date | | | |
| Marker | Small RR Spike | | |
| | to 5/8" iron pin at east edge of pavement | | |
| | to 5/8" iron pin at east edge of pavement | | |
| 19.63' W | to duplex S/side power pole | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 18 | | <u> </u> |
| Corner | OTHER | | X |
| Date | 6/29/2010 | | |
| Marker | Small RR Spike | | |
| 21.07' E t | to mag nail W/side 30" oak | | |
| 13.83' SV | V to ½" iron pin at west edge of pavement | | |
| 14.10' NV | V to 5/8" iron pin at west edge of pavement | | |
| | | | |
| | | | |
| | | | |

Tuesday, July 13, 2021 Page 14 of 52

| <u> </u> | 18 | | |
|------------|---|------|--------------|
| Section | | | |
| Corner | W½ | | |
| Date | 6/29/2010 | | |
| Marker | Small RR Spike | W1⁄4 | |
| 29.87' NE | to PK in power pole | | |
| 63.68' EN | E to duplex NW/side marker post | | |
| 16.26' NV | V to 5/8" iron pin at west edge of pavement | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | 18 | | |
| | | | |
| Corner | CENTER | | |
| Date | 6/29/2010 | | |
| Marker | Small RR Spike | | \ |
| 19.16' N t | o "+" in concrete corner post (P) | | CENTER |
| b- | o duplex E/side power pole | | |
| 21.54' NE | to 5/8" iron pin at north edge of pavement | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Castian | 18 | | |
| Section | | | |
| Corner | N¼ SE | | |
| Date | 6/29/2010 | | |
| Marker | Small RR Spike | | \downarrow |
| 86.11' S t | o duplex E/side power pole | | N¹¼SE |
| | to duplex NE/side power pole | | |
| 29.61' WS | SW to "+" NE corner catch basin (P) | | |
| | | | |
| B | | | |
| | | | |

Tuesday, July 13, 2021 Page 15 of 52

| Section | 19 | |
|-----------|--|------|
| Corner | NW | NW |
| Date | 6/29/2010 | |
| Marker | Small RR Spike | |
| | NW to "+" SE corner catch basin (P) | |
| | W to "+" east corner catch basin (P) | |
| - | to duplex NE/side power pole | |
| | to NE corner Sec. 24, Harrison Twp. (1980 Tie) | |
| | | |
| | | |
| | | |
| | | |
| | | |
| Section | 19 | N1/4 |
| Corner | N1⁄4 | N74 |
| Date | 6/29/2010 | |
| Marker | Small RR Spike | |
| | E to duplex W/side power pole | |
| | o duplex W/side power pole | |
| | V to 5/8" iron pin at edge of pavement of radius | |
| - | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| Section | 19 | |
| Corner | W ¹ / ₄ | |
| Date | 6/29/2010 | |
| Marker | Small RR Spike | W¼ |
| | to duplex NW/side power pole | VV/4 |
| | V to duplex NW/side telephone pole (P) | |
| | V to 5/8" iron pin at west edge of pavement | |
| 39.89' NE | to duplex SE/side power pole | |
| | | |

Tuesday, July 13, 2021 Page 16 of 52

| Section | 19 | | I |
|-----------|--|------|-----------------|
| Corner | CENTER | | |
| Date | 6/29/2010 | | |
| Marker | RR Spike | | |
| 23.07' NW | V to PK nail NE/side power pole | | K CENTER |
| 25.55' SW | / to sawed "+" in face of concrete corner post (near NE corr | ner) | |
| 18.41' NE | to iron pin at edge of pavement of radius | | |
| | | | |
| | | | |
| | | | |

Tuesday, July 13, 2021 Page 17 of 52

| Section | 20 | | |
|-----------|--|-------------------------------|--|
| Corner | NW | NW | |
| | 6/29/2010 | | |
| Date | | | |
| Marker | Small RR Spike | | |
| | o duplex NW/side wood corner post | | |
| | to mag nail 12" from end of corr. plastic pipe (P) | | |
| | / to mag nail 12" from end of corr. plastic pipe (P) | | |
| 8.76' SSE | to 5/8" iron pin at south edge of pavement | | |
| | | | |
| Section | 20 | N1/4 | |
| Corner | N1/4 | 1974 | |
| Date | 6/29/2010 | | |
| Marker | Small RR Spike | | |
| 31.84' NV | / to "+" SE corner catch basin | | |
| | E to duplex W/side power pole | | |
| b | / to "+" NE corner catch basin | | |
| 45.21' NV | V to duplex SW/side power pole | | |
| | | | |
| | | | |
| Section | 20 | | |
| Corner | W1/4 | | |
| Date | 6/29/2010 | | |
| Marker | Iron Pin | W ¹ / ₄ | |
| | o sawed "+" in south face of corner post | | |
| | to duplex S/side power pole | | |
| | to 5/8" iron pin at north edge of pavement | | |
| | V to 5/8" iron pin at north edge of pavement | | |
| | | | |

Tuesday, July 13, 2021 Page 18 of 52

| ENTER | |
|---|--|
| | |
| 6/29/2010 | |
| all RR Spike | |
| uplex SE/side power pole | CENTER |
| mag nail east end corr. plastic pipe (P) | |
| mag nail south end corr. plastic pipe (P) | |
| uplex NW/side cable marker post | |
| | |
| r | all RR Spike uplex SE/side power pole mag nail east end corr. plastic pipe (P) mag nail south end corr. plastic pipe (P) |

Tuesday, July 13, 2021 Page 19 of 52

| | 21 | NW |
|----------------|---|-------------------------------|
| Corner | NW | livv |
| Date | 6/30/2010 | |
| Marker | Small RR Spike | |
| 23.21' N t | to sawed "+" W/side conc. corner post | |
| - | V to spike W/side power pole | |
| 41.11' SV | V to sawed "+" NE corner conc. slab | |
| 22.01' NV | V to sawed "+" NW corner catch basin (P) | |
| | | |
| Section Corner | 21 N¼ | N ¹ / ₄ |
| Date | 6/30/2010 | |
| | | |
| <i>Marker</i> | Small RR Spike | |
| | to PK nail west end CMP (P) | |
| - | E to PK nail east end CMP (P) V to 5/8" iron pin at south edge of pavement | |
| 10.90 37 | v to 5/6 from pin at south eage of pavement | |
| | | |
| | | |
| | | |
| | | |
| | | |
| Section | 21 | |
| Corner | W ¹ / ₄ | |
| Date | 6/30/2010 | |
| | Small RR Spike | W1⁄4 |
| Marker | | V V / 4 |
| | IW to spike SE/side power pole | |
| 34.68' NN | IW to spike SE/side power pole to sawed "+" E/side conc. post | |
| 20.44' N t | | |

Tuesday, July 13, 2021 Page 20 of 52

| Section | 21 | |
|------------|---|--------|
| Corner | CENTER | |
| Date | 6/30/2010 | |
| Marker | Small RR Spike | |
| 14.28' NN | IW to sawed "+" in north end conc. pipe (P) | CENTER |
| 17.87' S t | o sawed "+" in east end conc. headwall (P) | |
| 19.60' SV | V to sawed "+" in west end conc. headwall (P) | |
| 45.48' SS | W to duplex E/side power pole | |
| | | |
| | | |

Tuesday, July 13, 2021 Page 21 of 52

| Section | 22 | DDA/ | |
|-----------|--|-------|--|
| Corner | NW | NW | |
| Date | 6/30/2010 | | |
| Marker | Nail/Shiner | | |
| 40.35' NV | V to nail/shiner SE/side power pole | | |
| | E to sawed "+" top west end conc. headwall (P) | | |
| 38.61' NE | to sawed "+" SW corner catch basin (P) | | |
| 45.91' SV | V to nail/shiner NE/side power pole | | |
| | | | |
| Section | 22 | N1/4 | |
| Corner | N1/4 | 11,74 | |
| Date | 6/30/2010 | | |
| Marker | Small RR Spike | | |
| 77.17' EN | IE to duplex S/side power pole (P) | | |
| 57.60' NN | IE to duplex W/side power pole | | |
| 46.03' SV | V to duplex SE/side power pole | | |
| 57.44' SS | E to mag nail W/side 24" tree | | |
| | | | |
| Section | 22 | | |
| Corner | W1/4 | | |
| Date | 6/30/2010 | | |
| Marker | Nail/Shiner | W1/4 | |
| 35.19' NV | V to nail/shiner SW/side power pole | VV74 | |
| | SW to duplex N/side power pole | | |
| | IE to duplex NW/side telephone pole | | |
| | to nail/shiner NW/side light pole | | |
| 26.57' NV | V to sawed "+" NW corner conc. catch basin | | |

Tuesday, July 13, 2021 Page 22 of 52

| Section | 22 | | |
|-----------|---|---|--------|
| Corner | CENTER | | |
| Date | 6/30/2010 | | |
| Marker | Small RR Spike | | _ |
| 29.75' SE | to duplex NE/side brace pole | 7 | CENTER |
| 29.81' SW | / to nail/shine NE/side power pole | | |
| 37.97' NW | / to mag nail E/side 18" maple | | |
| 20.63' NN | E to 5/8" iron pin at east edge of pavement | | |
| 54.54' NW | / to SE corner foundation stone "Morris" | | |
| | | | |

Tuesday, July 13, 2021 Page 23 of 52

| Section | 23 | NVA/ | |
|--|---|-------------------------------|--|
| Corner | NW | NW | |
| Date | 6/30/2010 | | |
| Marker | Small RR Spike | | |
| 53.92' NE | to duplex SE/side power pole | | |
| 22.07' NV | N to 5/8" iron pin at north edge of pavement | | |
| 7.72' SSE | E to 5/8" iron pin at south edge of pavement | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 23 | | |
| Section Corner | 23 N¼ | N ¹ / ₄ | |
| | | N1/4 | |
| Corner | N½ | N ¹ / ₄ | |
| Corner Date Marker | N½ 6/30/2010 | N1/4 | |
| Corner Date Marker 75.89' EN | N1/4 6/30/2010 Small RR Spike | N ¹ / ₄ | |
| Corner Date Marker 75.89' EN 76.16' ES | N ¹ / ₄ 6/30/2010 Small RR Spike NE to duplex S/side power pole | N ¹ / ₄ | |
| Corner Date Marker 75.89' EN 76.16' ES 30.22' SV | 6/30/2010 Small RR Spike NE to duplex S/side power pole SE to duplex S/side power pole | N ¹ / ₄ | |

Tuesday, July 13, 2021 Page 24 of 52

| Section | 24 | | |
|-----------|--|------|-----|
| Corner | NW | NW | |
| Date | 6/30/2010 | | |
| Marker | Small RR Spike | | |
| | E to "+" W/side steel casing | | |
| - | to duplex SW/side wood post | | |
| | / to PK nail NW/side power pole | | |
| 64.97' NV | / to duplex SW/side tree trunk | | |
| 91.70' WI | NW to mag nail W/end N12 pipe (P) | | |
| | | | |
| Section | 24 | N1/4 | |
| Corner | N1⁄4 | | |
| Date | 6/30/2010 | | |
| Marker | Small RR Spike | | |
| 49.46' SE | to duplex SW/side power pole | | |
| 20.21' SS | E to mag nail 18" from west end plastic pipe (P) | | |
| 15.11' NE | to 5/8" iron pin at north edge of pavement | | |
| | | | |
| | | | |
| | | | |
| Section | 24 | | NE |
| Corner | NE | | .,_ |
| Date | 6/30/2010 | | |
| Marker | Small RR Spike | | |
| 32.60' NV | / to nail/shiner SW/side telephone pole | | |
| 49.68' NE | to nail/shiner NW/side power pole | | |
| 40.43' SE | to duplex SW/side power pole (P) | | |
| 3.78' WS | N to harrow tooth (Wood County?) | | |
| 38.04' NE | to iron pin E/side concrete monument(1980 tie) | | |

Tuesday, July 13, 2021 Page 25 of 52

| Section Corner Date Marker | W1/4 6/30/2010 | | |
|-------------------------------------|---|------|--------------|
| Date Marker | | | |
| Marker | | | |
| | Small RR Spike | | |
| 00 741 15 | · · · · · · · · · · · · · · · · · · · | W1⁄4 | |
| | to duplex SE/side cable marker post | | |
| | to duplex NW/side power pole | | |
| 10.08 NE | to 5/8" iron pin 12" west of edge of pavement | | |
| | | | |
| | | | 1 |
| | | | |
| | | | |
| | | | |
| Section | 24 | | |
| | CENTER | | |
| Corner | | | |
| Date | 6/30/2010 | | |
| Marker | RR Spike | | \downarrow |
| 23.25' NW | to 5/8" iron pin at north edge of pavement | | CENTER |
| 16.88' NE | to 5/8" iron pin at north edge of pavement | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 24 | | |
| Corner | <u>E¼</u> | | |
| Date | 6/30/2010 | | |
| Marker | RR Spike | | E1/4 |
| | to "+" center concrete headwall (P) | | L/4 |
| | to concrete witness monument | | |
| | to "+" SW corner catch basin (P) | | |
| | to duplex NW/side cable marker post | | |
| | 1/4 post, Sec. 19, Grand Rapids Twp., Wood County, Ohio | | |

Tuesday, July 13, 2021 Page 26 of 52

| Section | 25 | NW | |
|-----------|---------------------------------------|------|----|
| Corner | NW | | |
| Date | 6/30/2010 | | |
| Marker | Nail/Shiner | | |
| 73.58' NN | IE to nail/shiner S/side power pole | | |
| 38.43' SV | V to nail/shiner NE/side power pole | | |
| 48.96' SE | to mag nail east end plastic pipe (P) | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 25 | | NE |
| Corner | NE | | |
| Date | 6/30/2010 | | |
| Marker | Nail/Shiner | | |
| 48.77' NE | to "+" east end concrete headwall (P) | | |
| b- | to "+" center concrete headwall (P) | | |
| 58.64' SV | V to nail/shiner NE/side power pole | | |
| 56.51' SE | to duplex SW/side power pole | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 25 | | |
| Corner | W ¹ / ₄ | | |
| Date | 6/30/2010 | | |
| Marker | RR Spike | W1/4 | |
| | V to spike S/side power pole | | |
| | to "+" SE corner CB riser (P) | | |
| | SW to mag nail E/side pine tree | | |
| | | | |
| | | | |
| | | | |

Tuesday, July 13, 2021 Page 27 of 52

| Section | 25 | | |
|-----------|---|------|------|
| Corner | E1/4 | | |
| Date | 6/30/2010 | | |
| Marker | RR Spike | | E1/4 |
| 98.25' NN | E to duplex SE/side power pole | | |
| 15.99' SE | to 5/8" iron pin 4.5' east of edge of paven | nent | |
| 10.19' SW | I to 5/8" iron pin 4' west of edge of pavem | nent | |
| | | | |
| | | | |
| | | | |

Tuesday, July 13, 2021 Page 28 of 52

| Section | 26 | NW | |
|-----------|--|-------|--|
| Corner | NW | INVV | |
| Date | 6/30/2010 | | |
| Marker | Nail/Shiner | | |
| 31.89' NE | E to "+" NW corner catch basin (P) | | |
| | to nail/shiner NW/side power pole | | |
| 32.94' SV | V to "+" SE corner catch basin | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 26 | N1/4 | |
| Corner | N1/4 | 111/4 | |
| Date | 6/30/2010 | | |
| Marker | Small RR Spike | | |
| 63.01' ES | E to center R/W monument | | |
| 31.40' SS | SW to nail/shiner N/side power pole | | |
| - | · · | | |
| _ | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 26 | | |
| Corner | W1/4 | | |
| Date | 6/30/2010 | | |
| Marker | Small RR Spike | W1⁄4 | |
| | NE to duplex W/side 24" tree | VV 74 | |
| | to duplex W/side 6" tree | | |
| | SW to duplex SE/side power pole | | |
| | The second secon | | |
| | | | |

Tuesday, July 13, 2021 Page 29 of 52

| Section | 27 | | |
|-----------|---|------|--|
| Corner | NW | NW | |
| Date | 6/30/2010 | | |
| Marker | Nail/Shiner | | |
| | V to "+" on face concrete island guard | | |
| - | to nail/shiner SW/side power pole | | |
| | to "+" top concrete slab | | |
| | / to nail/shiner NE/side power pole | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 27 | | |
| Corner | N¹⁄4 | N1/4 | |
| Date | 6/30/2010 | | |
| Marker | Nail/Shiner | | |
| | | | |
| | to nail/shiner SW/side telephone pole | | |
| | to center brass plate R/W monument | | |
| | E to nail/shiner W/side power pole | | |
| | / to nail/shiner NE/side power pole IW to nail/shiner SE/side power pole | | |
| 100.30 1 | www.to fram/shifter 3E/side power pole | | |
| | | | |
| | | | |
| | | | |
| Section | 27 | | |
| | | | |
| Corner | W½ | | |
| Date | 6/30/2010 | | |
| Marker | Iron Pipe | W½ | |
| 32.03' W | to "+" in face concrete fence post | | |
| | E to nail/shiner W/side power pole (P) | | |
| 38.02' SE | to "+" cut in NE flange bolt of fire hydrant (P) | | |
| | | | |
| | | | |

Tuesday, July 13, 2021 Page 30 of 52

| Section | 27 | | |
|-------------|--------------------------------------|-------------|--------|
| Corner | CENTER | | |
| Date | 6/30/2010 | | |
| Marker | RR Spike | | , |
| 24.78' NW | to mag nail SE/side power pole | | CENTER |
| 14.15' E to | "+" east end concrete headwall (P) | | |
| 15.80' NE | to 5/8" iron pin at edge of pavement | | |
| | | | |
| | | | |
| | | | |
| | | | |

Tuesday, July 13, 2021 Page 31 of 52

| Section | 28 | | |
|---------------|--|------|--|
| Corner | NW | NW | |
| Date | 7/2/2010 | | |
| <i>Marker</i> | Nail/Shiner | | |
| | | | |
| | to "+" east end 18" concrete pipe | | |
| | Et o nail/shiner NW/side power pole | | |
| | V to easterly corner concrete slab porch floor V to "+" in SW corner catch basin | | |
| | to duplex NW/side power pole | | |
| | to daplox (VIV) clas perior pole | | |
| | | | |
| Section | 28 | N¹¼ | |
| Corner | N1/4 | | |
| Date | 6/30/2010 | | |
| Marker | Nail/Shiner | | |
| 39.92' N | to 3/8" iron pin (P) | | |
| | o nail/shiner N/side power pole | | |
| - | V to nail/shiner NE/side power pole | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 28 | | |
| Corner | W1/4 | | |
| Date | 7/2/2010 | | |
| | RR Spike | | |
| Marker | | W1⁄4 | |
| | to "+" N/side concrete corner post | | |
| 51.37' NE | to duplex W/side power pole | | |
| | | | |
| | | | |
| - | | | |

Tuesday, July 13, 2021 Page 32 of 52

| Section | 29 | | |
|-----------|---|------|---|
| Corner | NW | NW | |
| Date | 7/2/2010 | | |
| Marker | Nail/Shiner | | |
| | to "+" S/side concrete corner post | | |
| | IE to nail/shiner S/side power pole | | |
| | to nail/shiner NW/side power pole | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | | N1/4 | |
| Corner | N¹⁄4 | 1974 | |
| Date | 7/2/2010 | | |
| Marker | Not Found | | |
| 44.62' NV | V to nail/shiner SE/side cable marker (1980 ties) | | |
| | EE to "+" east end 24" RCP (P) (1980 ties) | | |
| 49.88' SE | to NW corner concrete post (1980 ties) | | |
| 51.01' SE | to nail/shiner NW/side power pole (1980 ties) | | |
| 45.47' SV | V to "+" west end 24" RCP (P) (1980 ties) | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | | | _ |
| Corner | W ¹ / ₄ | | |
| Date | 7/2/2010 | | |
| Marker | Iron Pin | W1⁄4 | |
| | to "+" south end 54" RCP (P) | | |
| | IE to "+" NE corner catch basin (P) | | |
| | . , | | |
| | | | |
| | | | |
| - | | | |

Tuesday, July 13, 2021 Page 33 of 52

| Section | 29 | |
|---------------------------------------|---|--------|
| Corner | CENTER | |
| Date | 7/2/2010 | |
| Marker | Iron Pin Set new mag nails 6' NE and SE | |
| 18.10' E t | o "+" W/side concrete corner post | CENTER |
| 107.76' S | SE to duplex E/side power pole | |
| 42.91' SV | V to 5/8" iron pin on west ditch bank (1980 tie) | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| Section | 29 | |
| Section Corner | 29 W¼ SW | |
| | | |
| Corner | W1/4 SW | |
| Corner Date Marker | W1/4 SW 7/2/2010 | |
| Corner Date Marker 81.78' NN | W1/4 SW 7/2/2010 Iron Pin Set new mag nails 6' NW and SW | |
| Corner Date Marker 81.78' NN | W¹¼ SW 7/2/2010 Iron Pin Set new mag nails 6' NW and SW W to "+" E/side concrete corner post | V |
| Corner Date Marker 81.78' NN | W¹¼ SW 7/2/2010 Iron Pin Set new mag nails 6' NW and SW W to "+" E/side concrete corner post | v |

Tuesday, July 13, 2021 Page 34 of 52

| Section | 30 | NW |
|-----------|-------------------------------------|------|
| Corner | NW | INVV |
| Date | 7/2/2010 | |
| Marker | Small RR Spike | |
| 44.95' NE | E to duplex NW/side power pole (P) | |
| | to mag nail east root of tree (P) | |
| 32.57' NE | to duplex SE/side power pole | |
| 73.01' SS | E to "+" SE/side catch basin (P) | |
| 77.87' SS | SW to "+" SE/side catch basin (P) | |
| | | |
| | | |
| | | |
| | | |
| Section | 30 | N1/4 |
| Corner | N½ | |
| Date | 7/2/2010 | |
| Marker | Nail/Shiner | |
| 47.54' NV | V to SE corner concrete anchor post | |
| | JW to nail/shiner S/side wood post | |
| | EE to nail/shiner N/side power pole | |
| 59.90' SS | W to nail/shiner N/side power pole | |
| 50.20' SV | V to "+" top 24" concrete pipe (P) | |
| | | |
| | | |
| | | |
| | | |
| Section | 30 | |
| Corner | W¼ NE | W¼NE |
| Date | 7/2/2010 | |
| Marker | RR Spike | |
| | INW to duplex E/side power pole | |
| | to mag nail SE/side 12" hickory | |
| 31.33 INL | | |
| | to mag nail S/side 36" hickory | |

Tuesday, July 13, 2021 Page 35 of 52

| Section | 30 | | |
|---|---|----|--------------------|
| Corner | W ¹ / ₄ | | |
| Date | 7/2/2010 | | |
| Duie Marker | RR Spike | | |
| | | W½ | |
| | SE to duplex N/side power pole to Harrison Twp. stone | | |
| | V to mag nail S/side tree | | |
| | , to mag name of older and | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 30 | | |
| Corner | CENTER | | |
| Date | 7/2/2010 | | |
| Marker | RR Spike | | |
| | NW to "+" SE corner catch basin (P) | | CENTER |
| | NE to "+" concrete headwall (P) | | CENTER |
| | duplex S/side power pole | | |
| | V to duplex NW/side cable marker post | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 30 | | |
| Corner | W¼ SE | | |
| Date | 7/2/2010 | | |
| Marker | RR Spike | | |
| | E to mag nail NW/side 24" tree | | |
| | SE to mag nail N/side 14" pine | | |
| | to mag nail SW/side 36" maple | | kw ₄ se |
| 101.85' SSE to duplex W/side power pole | | | VV/40L |
| | | | |
| - | | | |

Tuesday, July 13, 2021 Page 36 of 52

| Section | 30 | | |
|-----------|--|--|---------|
| Corner | E¼ SE | | |
| Date | 5/9/1980 | | |
| Marker | Iron Pin | | |
| 25.94' W | to SE corner concrete corner post (P) | | |
| 32.89' NE | to 5/8" iron pin on east ditch bank(P) | | |
| 43.92' SE | to 5/8" iro pin on east ditch bank (P) | | E1/4SE> |
| | | | |
| | | | |
| | | | |

Tuesday, July 13, 2021 Page 37 of 52

| Section | 31 | NW | |
|------------|--|----------|--|
| Corner | NW | INVV | |
| Date | 7/2/2010 | | |
| Marker | Small RR Spike | | |
| 33.21' NE | to spike W/side power pole | | |
| | to duplex NE/side telephone pole | | |
| 81.04' ES | E to duplex NE/side power pole | | |
| 115.49' S | to NE corner, Sec. 36, Harrison Twp (1980 tie) | | |
| | | | |
| Section | 31 | N/NW | |
| Corner | N¼ NW | IN74INVV | |
| Date | 5/22/1980 | | |
| Marker | RR Spike | | |
| 22.33' NN | IW to SE corner concrete corner post | | |
| 42.43' SE | to 5/8" iron pin on south ditch bank | | |
| 14.50' S t | o "+" north end concrete headwall (P) | | |
| 48.44' SV | V to 5/8" iron pin on south ditch bank (P) | | |
| | | | |
| Section | 31 | | |
| Corner | N1/4 | N½ | |
| Date | 7/2/2010 | | |
| Marker | Small RR Spike | | |
| | V to duplex S/side telephone pole | | |
| | to duplex SW/side power pole | | |
| | E to PK nail NW/side power pole | | |
| | | | |
| | | | |

Tuesday, July 13, 2021 Page 38 of 52

| Section | 31 | | 1 |
|------------|---|------|--------|
| Corner | W ¹ / ₄ | | |
| Date | 7/2/2010 | | |
| Marker | Small RR Spike | W1⁄4 | |
| 33.18' NE | E to SW corner concrete corner post (P) | 1174 | |
| | V to duplex NE/side power pole | | |
| | SW to duplex SE/side power pole | | |
| 58.30' S t | to Harrison Twp. corner | | |
| | | _ | 1 |
| Section | 31 | | |
| Corner | CENTER | | |
| Date | 7/2/2010 | | |
| Marker | Small RR Spike | | |
| | E to duplex SE/side power pole | | CENTER |
| | SE to mag nail SW/side 36" elm | | CENTER |
| b- | V to NE corner flag pole base | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 31 | | |
| Corner | SW | | |
| Date | | | |
| Marker | See NE corner, Sec. 1, Monroe Twp. | | |
| | | _ | |
| | | | |
| | | | |
| | | | |
| | | SW | |
| | | | |

Tuesday, July 13, 2021 Page 39 of 52

| Section | 31 | |
|---|-------------------------------------|------|
| Corner | S1/4 | |
| Date | 7/2/2010 | |
| Marker | Small RR Spike | |
| 28.52' NN | IW to "+" top concrete headwall (P) | |
| 62.11' WNW to "+" top concrete headwall (P) | | |
| 17.22' SE to "+" concrete headwall (P) | | |
| 57.82' SW to "+" concrete headwall (P) | | |
| 57.23' W | to N¼ post, Sec. 6, Richfield Twp. | S1/4 |

Tuesday, July 13, 2021 Page 40 of 52

| | NW | NW | |
|-------------|---------------------------------------|------|--|
| | | | |
| Date | 7/2/2010 | | |
| | 2" Iron Pin | | |
| _ | to duplex NE/side power pole | | |
| - | to nail/shiner in power pole | | |
| | to "+" in concrete pipe (P) | | |
| | to "+" east end headwall | | |
| | | | |
| Section | 32 | | |
| Corner | N¹⁄4 | N1⁄4 | |
| Date | 7/7/2010 | | |
| Marker | Small RR Spike | | |
| _ | V to PK nail top west end 10" CMP (P) | | |
| | to duplex N/side power pole | | |
| | to duplex in power pole | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 32 | | |
| Corner | <u>W¼</u> | | |
| Date | 7/2/2010 | | |
| Marker _ | RR Spike | W1/4 | |
| 72.97' SW 1 | to duplex NW/side power pole | | |
| 82.39' WNV | N to duplex S/side power pole | | |
| 48.76' NW | to duplex E/side power pole | | |
| | | | |
| | | | |

Tuesday, July 13, 2021 Page 41 of 52

| Section | 32 | | | |
|-----------|---|------------|---|--------|
| Corner | CENTER | | | |
| Date | 7/7/2010 | | | |
| Marker | Small RR Spike | | _ | _ |
| 27.99' EN | E to "+" west side concrete corner post | | | CENTER |
| 18.24' WI | NW to mag nail N/side 12" tree | | | |
| 25.88' SE | to "+" SE corner concrete slab | | | |
| 49.34' SE | to duplex SW/side power pole | _ | | |
| | | | | |
| Section | 32 | | | |
| Corner | SW | | | |
| Date | 7/2/2010 | | | |
| Marker | Small RR Spike | | | |
| 50.97' NN | IW to "+" SE corner concrete catch basin | | | |
| 101.77' N | E to SE corner house foundation | | | |
| 42.19' NE | to duplex NW/side telephone pole | | | |
| 50.19' SS | W to duplex NW/side power pole | | | |
| 57.52' W | to NW corner, Sec. 5, Richfield Twp. (1979 tie) | SV | V | |
| Caption | 32 | _ _ | | |
| Section | | | | |
| Corner | <u>\$¼</u> | | | |
| Date | 7/7/2010 | | | |
| Marker | Small RR Spike | _ | | |
| 90.42' ES | E to duplex N/side power pole | | | |
| 63.90' SV | V to duplex N/side 18" locust | | | |
| 70.30' W | SW to "+" SE bridge wing (south end) | | | |
| 58.61' W | to N¼ post, Sec. 5, Richfield Twp. | | | |
| | | L_ | | S1/4 |

Tuesday, July 13, 2021 Page 42 of 52

| Section | 33 | NW |
|-----------|--|-------|
| Corner | NW | INV |
| Date | 7/7/2010 | |
| Marker | Small RR Spike | |
| 47.02' SV | V to duplex NW/side power pole | |
| 107.94' N | INE to duplex E/side power pole | |
| 46.13' ES | SE to "+" east end RCP (P) | |
| 46.34' W | SW to "+" west end RCP (P) | |
| | | |
| | | |
| | | |
| | | |
| | | |
| Section | 33 | N1/4 |
| Corner | N1⁄4 | 111/4 |
| Date | 7/7/2010 | |
| Marker | Small RR Spike | |
| | E to "+" north end 12" cast iron pipe (P) | |
| | to duplex W/side power pole | |
| | E to "+" SW corner catch basin (P) | |
| - | , , | |
| | | |
| | | |
| | | |
| | | |
| | | |
| Section | 33 | |
| Corner | W ¹ / ₄ | |
| Date | 7/7/2010 | |
| Marker | Iron Pin | l |
| | | W¼ |
| | to "+" west end RCP (P) SE to duplex E/side power pole | |
| | V to duplex E/side power pole V to duplex NW/side cable marker post | |
| | to "+" east end RCP (P) | |
| | | |

Tuesday, July 13, 2021 Page 43 of 52

| Section | 33 | | |
|-----------|--|---------------|--|
| Corner | | | |
| | 5/7/1980 | | |
| Date | Iron Pin | | |
| Marker | | | |
| - | to NE corner concrete corner post | | |
| 39.02 E I | to iron pipe on top of east ditch bank | | |
| | | \ \ \W1\/\s\\ | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 33 | | |
| Corner | SW | | |
| Date | 7/7/2010 | | |
| Marker | Small RR Spike | | |
| | NE to "+" center concrete wingwall | | |
| - | IE to duplex W/side wood post | | |
| - | V to "+" west end concrete wingwall | | |
| | to NW corner, Sec. 4, Richfield Twp. | | |
| - | | SW | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 33 | | |
| Corner | S1/4 | | |
| Date | 7/7/2010 | | |
| Marker | Small RR Spike | | |
| 67.40' WI | NW to center USC&G Δ Sta. Stoner-1947 (P) | | |
| | to "+" W/side concrete anchor post (leans south) | | |
| | SW to duplex W/side power pole | | |
| 40.93' W | to N¼ post, Sec. 4, Richfield Twp. | | |
| 70.46' SS | E to "+" concrete foundation | S1/4 | |

Tuesday, July 13, 2021 Page 44 of 52

| Section | 34 | | |
|-----------|---|-------------|--|
| Corner | NW | NW | |
| Date | 7/7/2010 | | |
| Marker | Nail/Shiner | | |
| | / to duplex NE/side telephone pole | | |
| | to "+" in west bonnet bolt of fire hydrant | | |
| - | to duplex SW/side power pole | | |
| | W to "+" SW corner concrete catch basin (P) | | |
| | () | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 34 | | |
| Corner | N¹/4 | N1⁄4 | |
| Date | 7/7/2010 | | |
| Marker | RR Spike | | |
| | · · · · · · · · · · · · · · · · · · · | | |
| | / to duplex SW/side power pole | | |
| | W to "+" north end 48" RCP (P) | | |
| 28.72 50 | / to "+" south end 48" RCP (P) | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 34 | | |
| | | | |
| Corner | <u>W¼</u> | | |
| Date | 7/7/2010 | | |
| Marker | Nail/Shiner | W1⁄4 | |
| 83.62' NN | E to duplex SE/side power pole | | |
| 30.59' SE | to "+" east end 84" RCP (P) | | |
| 86.24' SS | E to duplex NE/side power pole | | |
| 28.93' SV | / to "+" west end 84" RCP (P) | | |
| | | | |

Tuesday, July 13, 2021 Page 45 of 52

| Section | 34 | | | |
|-----------|--------------------------------------|-----|--------------|--------------|
| Corner | CENTER | | | |
| Date | 7/7/2010 | | | |
| | Iron Pin | | | |
| Marker | | |) | (|
| - | to duplex N/side power pole | | | CENTER |
| - | to 5/8" iron pin at edge of pavement | | | |
| 21.81 SE | to 5/8" iron pin at edge of pavement | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | 34 | | | |
| Section | | | | |
| Corner | SW | | | |
| Date | 7/7/2010 | | | |
| Marker | Iron Pin in Monument Box | | | |
| 32.39' SE | to "+" in concrete headwall | | | |
| 42.48' WS | SW to center drill lhole in headwall | | | |
| 28.71' W | to NW corner, Sec. 3, Richfield Twp. | | | |
| 42.04' EN | IE to nail/shiner SW/side wood post | | | |
| 64.40' NE | to nail/shiner SW/side power pole | | SW | |
| 66.79' NV | V to nail/shiner SE/side power pole | | | |
| | | | | |
| | | | | |
| | | | | |
| Section | 34 | | | |
| Corner | S1/4 | | | |
| | 7/7/2010 | | | |
| Date | | | | |
| Marker | Nail/Shiner | — I | | |
| | V to duplex W/side power pole | | | |
| | W to duplex N/side power pole | | | |
| 30.82' W | to N¼ post, Sec. 3, Richfield Twp. | | | |
| | | | | 61/ |
| | | | | S1/4 |

Tuesday, July 13, 2021 Page 46 of 52

| 44.53' NW to duplex SW/side power ole 26.05' NW to "+" north end 48" RCP (P) 30.65' SW to "+" south end 48" RCP (P) 39.04' SE to mag nail east end plastic pipe (P) Section 35 | |
|--|-----|
| Marker RR Spike 44.53' NW to duplex SW/side power ole 26.05' NW to "+" north end 48" RCP (P) 30.65' SW to "+" south end 48" RCP (P) 39.04' SE to mag nail east end plastic pipe (P) Section 35 | |
| 44.53' NW to duplex SW/side power ole 26.05' NW to "+" north end 48" RCP (P) 30.65' SW to "+" south end 48" RCP (P) 39.04' SE to mag nail east end plastic pipe (P) Section 35 | |
| 26.05' NW to "+" north end 48" RCP (P) 30.65' SW to "+" south end 48" RCP (P) 39.04' SE to mag nail east end plastic pipe (P) Section 35 | |
| 26.05' NW to "+" north end 48" RCP (P) 30.65' SW to "+" south end 48" RCP (P) 39.04' SE to mag nail east end plastic pipe (P) Section 35 | |
| 39.04' SE to mag nail east end plastic pipe (P) Section 35 | |
| Section 35 | |
| N ₂ / ₄ | |
| N ₂ / ₄ | |
| Corner N ¹ / ₄ | . 1 |
| | 1 |
| Date7/7/2010 | |
| Marker Small RR Spike | |
| 35.73' NW to "+" SW corner catch basin (P) | |
| 23.47' NNE to "+" north end 48" RCP (P) | |
| 32.38' SSE to "+" south end 48" RCP (P) | |
| | |
| | |
| | |
| | |
| Section 35 | |
| Corner W1/4 | |
| Date 7/7/2010 | |
| Marker Iron Pin W1/4 | |
| 26.68' NE to mag nail east end CMP (P) | |
| 28.97' SE to 5/8" iron pin at edge of pavement | |
| | |
| | |
| | |

Tuesday, July 13, 2021 Page 47 of 52

| Section | 35 | | _ |
|------------|--|-------|---|
| Corner | W1/4 SW | | |
| Date | 9/9/1975 | | |
| Marker | RR Spike | | |
| 15.82' WI | | | _ |
| | E to "+" west edge 24" dia. catch basin | | |
| | | Kw¼sw | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 35 | | _ |
| Corner | SW | | |
| Date | 7/7/2010 | | |
| Marker | Small RR Spike | | |
| 24.45' S t | o "+" east end 48" RCP (P) | | _ |
| 56.67' SV | / to "+" south end concrete headwall (P) | | |
| 42.22' S t | o duplex E/side power pole | | |
| | W to duplex E/side power pole | | |
| 32.37' W | to Richfield corner | SW | |
| | | | |
| | | | |
| | | | |
| <u></u> | 35 | | |
| Section | | | |
| Corner | S1/4 SW | | |
| Date | 10/2/1975 | | |
| Marker | RR Spike | | |
| 55.45' NV | I to duplex NE/side telephone pole | | |
| | to duplex N/side power pole | | |
| 103.24' W | /SW to PK nail top CMP (P) | | |
| | | S¼SW | |
| | | | |

Tuesday, July 13, 2021 Page 48 of 52

| Section | 35 | |
|------------|--|------|
| Corner | S1/4 | |
| Date | 7/7/2010 | |
| Marker | RR Spike | |
| 37.11' SV | V to duplex NW/side power pole (leaning north) | |
| 25.51' N | to "+" west end concrete headwall (P) | |
| 27.11' NE | to "+" west end concrete headwall (P) | |
| 11.91' E 1 | to N¼ post, Sec. 2, Richfield Twp. (1979 tie) | |
| | | S1/4 |

Tuesday, July 13, 2021 Page 49 of 52

| | • | | |
|-----------|---|------|-----|
| Section | 36 | NW | |
| Corner | NW | | |
| Date | 7/26/2010 | | |
| Marker | Small RR Spike | | |
| 45.56' NV | V to mag nail SE/side 30" tree | | |
| | to mag nail SW/side 8" pine | | |
| 33.04' SV | V to duplex NW/side power pole | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 36 | N1/4 | |
| Corner | N¼ | 11/4 | |
| Date | 7/25/2010 | | |
| Marker | Set new RR Spike | | |
| | o "+" north end RCP (P) | | |
| | o "+" south end RCP (P) | | |
| | to PK nail NW/side power pole | | |
| | | | |
| - | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 36 | | NIE |
| Corner | NE . | | NE |
| Date | 7/26/2010 | | |
| Marker | Small RR Spike | | |
| | V to "+" SW corner catch basin (P) | | |
| | to duplex SW/side power pole | | |
| | V to duplex NW/side underground cable marker post | | |
| | to NE corner concrete catch basin (P)(1980 tie) | | |
| | (// / | | |
| | | | |
| | | | |

Tuesday, July 13, 2021 Page 50 of 52

| | • | | |
|-----------|--|------|------|
| Section | 36 | | |
| Corner | W1⁄4 | | |
| Date | 7/26/2010 | | |
| Marker | Small RR Spike | W½ | |
| 64.85' NN | IW to duplex NE/side power pole (leaning east) | 1774 | |
| | V to mag nail south end plastic tile | | |
| | V to mag nail north end 12" plastic pipe | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 36 | | |
| Corner | <u>E¼</u> | | |
| Date | 7/26/2010 | | |
| Marker | Small RR Spike | | E1⁄4 |
| 24.05' SE | to 5/8" iron pin 2' east of edge of pavment | | |
| | V to 5/8" iron pin 2' west of edge of pavment | | |
| 22.59' EN | IE to duplex NW/side power pole | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Section | 36 | | |
| Corner | SW | | |
| Date | 7/26/2010 | | |
| Marker | Small RR Spike | | |
| 54.23' WS | SW to "+" east end RCP (P) | | |
| 38.92' SV | V to duplex SE/side power pole | | |
| 43.24' SV | V to "+" west end RCP | | |
| | | | |
| | | SW | |

Tuesday, July 13, 2021 Page 51 of 52

| Section | 36 | | |
|-----------|---|-------|------|
| | S ¹ / ₄ | | |
| Corner | 5/4 | | |
| Date | | | |
| Marker | See N¼ Post, Sec. 1, Richfield Twp. (Common Corner) | | |
| | | | |
| - | | | |
| | | | |
| | | | S1/4 |
| | | • | |
| | | | |
| | | | |
| | | | |
| Section | 36 | | |
| Corner | SE | | |
| Date | 7/26/2010 | | |
| Marker | Mag Nail in Bridge Deck | | |
| 32.28' NE | E to SW corner bridge abutment (Wood Co.) | | |
| | to NW corner bridge abutment (Wood Co.) | | |
| | | | |
| | | | |
| | | | SE |
| | | | |

Tuesday, July 13, 2021 Page 52 of 52