Section 1		
Date Established 10/30/2007	NW	
Corner NW		
<del>-</del>		
Marker Small RR Spike		
86.22' NW to duplex S/side power pole		
49.18' ESE to PK east end 21" aluminum pipe (P)		
69.23' SSE to duplex W/side power pole 22.49' NW to duplex S/side power pole		
78.94' W to Napoleon Twp. Corner		
78.74 W to Naboleon I wb. Comer		
Section 1		N¹⁄4
Date Established 10/30/2007		IN /4
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike at south edge of pavement		
Found PK Nails 6' NE & NW		
16.95' NE to 5/8" iron pin at north edge of pavement		
39.08' W to Napoleon Twp. Stone		
22.70' NW to 5/8" iron pin at north edge of pavement		
<b>Section</b> 1		NE
Date Established 10/30/2007		
Corner NE		
Marker Iron Pipe 3" below surface		
44.32' SE to duplex N/side power pole		
29.80' SW to "+" NE corner CB		
29.72' NW to "+" SE corner CB		
19.44' N to spike W/side power pole		
	UL	1

Tuesday, July 13, 2021 Page 1 of 54

		•
Section 1		
Date Established 10/30/2007		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
27.60' SW to spike N/side power pole	W1⁄4	
34.17' NNE to RR spike (center punched) W/side power pole		
41.35' SW to mag nail south end plastic pipe (P)		
27.48' NW to duplex S/side telephone pole		
44.00' NW to mag nail north end plastic pipe	_	
	_	
	_	
	_	
Section1		
Date Established 10/30/2007		
Corner CENTER		
Marker Small RR Spike	,	<u> </u>
16.07' SW to "+" top NE corner concrete CB	CEN	TER
16.07' NW to "+" top SE corner concrete CB		
67.78' WSW to duplex S/side power pole		
	_	ı
	_	
	_	

Tuesday, July 13, 2021 Page 2 of 54

Date Established 5/25/2021	
Corner W <sup>1</sup> / <sub>4</sub>	
Marker Found stone 6" deep.	
Top of 5" dia. stone has old red paint on surface.	1/4
Set 5/8" Iron Pin on N/side of stone for locating	
purposes only. Placed broken tile around stone. Placed survey	
marker and post on E/side of stone. Found steel fence post	
on W/side of stone. Many field stones were on top of corner	
stone.	
Survey Reference. Vol. 18. Pg. 210.	
<b>Section</b> 2	
Date Established 10/30/2007	\
Corner OTHER	$R_{\text{d. Z}}$
Marker RR Spike 3" below surface	
34.23' N to duplex W/side guard rail end post	/Â
54.25 IV to duplex W/side guard rail end post	
111.05' NE to SW corner porch foundation	,
111.05' NE to SW corner porch foundation	
111.05' NE to SW corner porch foundation 85.83' ESE to NW corner house foundation	
111.05' NE to SW corner porch foundation 85.83' ESE to NW corner house foundation	

Tuesday, July 13, 2021 Page 3 of 54

Section 3	NW	
Date Established11/1/2007		
Corner NW		
Marker Small RR Spike		
24.40' SE to 5/8" iron pin on south ditch bank		
21.05' S to 5/8" iron pin on south ditch bank		
25.50' SW to 5/8" iron pin on south ditch bank		
14.31' NE to 5/8" iron pin at north edge of pavement		
15.95' NW to 5/8" iron pin at north edge of pavement	_	
Section 3	_	N½
Date Established 11/1/2007		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
30.31' SW to "+" in north end granary foundation		
26.46' SSE to "+" in north end granary foundation		
17.33' SE to "+" NE corner CB		
	_	
	_	

Tuesday, July 13, 2021 Page 4 of 54

Section 4	NW	
Date Established 11/1/2007		
Corner NW		
Marker Small RR Spike		
28.77' SW to ¾" iron pin		
20.07' S to 5/8" iron pin		
25.91' SE to 5/8" iron pin (new)		
13.87' S to center of iron pipe (P)		
Section 4		l
Date Established11/1/2007		N <sup>1</sup> / <sub>4</sub>
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
18.53' S to <sup>3</sup> / <sub>4</sub> " iron pin (P)		
25.28' SW to <sup>3</sup> / <sub>4</sub> " iron pin (P)		
22.83' NW to 5/8" iron pin (new)		
21.37' NE to 5/8" iron pin (new)		
Section4	,	_
Date Established 9/25/2019		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker 5" x 5" stone found approximately 6" below surface		
5" South to witness post	W¼	_
1'± Northeast to top of iron pipe		
Surveys Vol. 29, Pg. 55, & Vol. 34, Pg. 1 call out stone		
Sarion in Exit E. Son war on Sin I and out stone		
		- 1

Tuesday, July 13, 2021 Page 5 of 54

Section	4		OTHER
Date Esta	ablished	11/7/2007_	<del>2</del> 47.6'
Corner	OTHER	2	면
Marker	Fd. Nai	10.89' north of noted RR Spike (1980 Ties)	
Placed S	mall RR	Spike on surface over noted RR Spike	
38.12' S	E to duple	ex SW/side cable marker	
12.09' S	to PK na	il west end 24" CMP (P)	
25.40' S	E to PK n	ail east end 24" CMP	
21.46' N	W to 5/8'	' iron pin 6' north of north edge of pavement	
56.80' N	E to mag	nail near root of large oak	

Tuesday, July 13, 2021 Page 6 of 54

Section 5	NDA/	
Date Established11/1/2007_	NW	
Corner NW		
Marker PK Nail 2" deep. Placed small RR Spike over		
PK Nail. 10/30/2017		
50.90' SE to PK nail SW/side power pole		
49.74' NNW to duplex E/side telephone pedestal marker		
39.98' S to PK nail in 24" N12 pipe		
62.83' SSE to "+" in north bonnet bolt of fire hydrant		
<b>Section</b> 5		
<b>Date Established</b> 11/1/2007	<sup>10.42</sup> '√←17D	
Corner OTHER	\	
Marker Small RR Spike		
41.98' SE to PK nail SW/side power pole		
69.50' SSE to "+" in north bonnet of fire hydrant		
38.99' S to PK nail in 24" N12 pipe		
42.08' NW to duplex E/side telephone pedestal marker		
Section 5		N¹/4
Date Established 11/1/2007		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike 3" deep		
9.18' NW to 5/8" x 30" iron pin at north edge of pavement		
8.73' NE to 5/8" x 30" iron pin at north edge of pavement		
25.09' S to PK nail N/side power pole		
33.25' SE to 5/8" iron pin at edge of stone drive		

Tuesday, July 13, 2021 Page 7 of 54

Section	5_		
Date Esta	ablished11/1/2007_		
Corner	<u>W<sup>1</sup>/<sub>4</sub></u>		
Marker	Mag Nail at south edge of pavement		
27.41' SI	E to 5/8" iron pin on east ditch bank (new iron pin)	W1⁄4	
29.55' S'	W to 5/8" iron pin on south ditch bank		
10.46' N	to 5/8" iron pin at north edge of pavement (new iron pin)		
37.23' E	NE to 5/8" iron pin at north edge of pavement		
		_	
		_	
		_	
		_	

Tuesday, July 13, 2021 Page 8 of 54

Section 6	NW	
Date Established11/1/2007_		
Corner NW		
Marker Small RR Spike		
42.24' NW to PK nail E/side cable marker		
50.82' NNE to duplex W/side power pole		
32.10' SE to center USGS bench mark "B300 1963"		
34.24' NE to GIS Monument ("Nap 31")		
	_	
Section 6		
		N¹⁄₄
Date Established11/1/2007_		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
47.39' WNW to PK nail top west end 12" CMP (P)		
23.61' NW to spike NE/side cable marker		
13.00' SE to 5/8" x 30" iron pin at south edge of pavement		
10.72' SW to 5/8" x 30" iron pin at south edge of pavement		
	_	
Section 6		N¹⁄₄NE
Date Established11/1/2007_		
Corner N <sup>1</sup> / <sub>4</sub> NE		
Marker RR Spike 2" deep		
15.70' NW to 5/8" x 30" iron pin at north edge of pavement		
18.56' NE to 5/8" x 30" iron pin at north edge of pavement		
21.47' SE to 5/8" x 30" iron pin on top of bank (P)		
19.48' SW to 5/8" x 30" iron pin on top of bank (P)		

Tuesday, July 13, 2021 Page 9 of 54

Section 6		
Date Established11/1/2007_		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
19.95' W to capped iron pin	W1⁄4	
61.65' ENE to duplex SE/side wood post		
20.00' WSW to duplex SE/side power pole		
40.13' SE to mag nail NW/side wood post	_	
	-	
Section 6	-	
Date Established11/1/2007		
Corner CENTER		
Marker Small RR Spike		(
21.64' S to duplex W/side power pole	CEN	ITER
14.08' SW to 5/8" iron pin at south edge of pavement		
12.36' NW to 5/8" iron pin at north edge of pavement	_	
14.80' N to duplex E/side wood post	_	
	-	
	-	
	-	

Tuesday, July 13, 2021 Page 10 of 54

Section 7	NW	
Date Established11/1/2007		
Corner NW		
Marker RR Spike 4" below surface		
35.61' NW to iron pin in concrete monument (P)		
35.85' NE to center USGS bench mark "C-300" (P)		
34.24' SW to iron pin in concrete monument (P)		
50.40' SSW to PK nail W/side power pole		
Section7		N1⁄4
Date Established 11/1/2007		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
38.33 NW to duplex SW/side power pole		
66.23' ESE to duplex NE/side telephone pole		
17.84' SSE to "+" NW corner CB (P)		
73.60' WSW to duplex NW/side telephone pole		
Cention 7		1
Section 7		
Date Established11/1/2007		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker RR Spike	10/1/	
23.84' E to 5/8" iron pin	W1⁄4	
25.04' NW to 5/8" iron pin on west ditch bank (P)		
64.65' N to E <sup>1</sup> / <sub>4</sub> Post, Sec. 12. Richland Twp. Defiance. Co.		
25.81' SE to 5/8" iron pin at east edge of pavement		

Tuesday, July 13, 2021 Page 11 of 54

Section 8	Ī
Date Established 12/8/2009	NW
Mankon DD Cuille III de cu	
Marker RR Spike 1" deep	
21.57' NNE to mag nail, north end 48" N12 plastic (P)	
21.64' SSE to mag nail, south end 48" N12 plastic (P)	
74.60' ESE to spike NE/side telephone pole	
63.40' WSW to spike SE/side telephone pole	
Section 8	17D
<b>Date Established</b> 11/1/2007_	170
Corner OTHER	
Marker Small RR Spike	
30.03' ESE to duplex N/side power pole	
29.30' SE to "+" west cap bolt of fire hydrant	
83.65' SSW to "+" in east rim of sanitary sewer m.h. cover	
<b>Section</b> 8	
Date Established10/30/2007	N1/4
Corner N <sup>1</sup> / <sub>4</sub>	17C
Marker Mag Nail	
20.75' E to duplex S/side wood fence post	
27.85' W to duplex S/side wood fence post	
53.96' SW to "+" in face of concrete retaining wall, west end	
25.58 WSW to "+" in west wall of CB (P)	
59.15' S to duplex E/side power pole	<u>.</u>

Tuesday, July 13, 2021 Page 12 of 54

Section	9				
Date Esta	ablished	10/30/2007_			
Corner	<u>W¹/4</u>				
Marker	Small R	R Spike			
19.87' N	E to 5/8" i	iron pin at edge of berm	W1	1/4	
21.84' SI	E to 5/8" i	ron pin at edge of berm			
18.56' S'	W to 5/8"	iron pin at edge of berm			

Tuesday, July 13, 2021 Page 13 of 54

9-4: 10		
Section 10	OTHER RD Z	
<b>Date Established</b> 10/30/2007	TOTHER	
Corner OTHER		
Marker Small RR Spike		
35.36' SE to spike SW/side buried cable marker		
30.73' NNW to duplex W/side power pole		
37.65' SW to PK nail NE/side power pole		
<b>Section</b> 10		
Date Established 10/30/2007		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
30.62' NW to 5/8" iron pin on west ditch bank (P)	W1⁄4	
28.59' NE to 5/8" iron pin on east ditch bank (P)		
20.45' SE to 5/8" iron pin at east edge of pavement		
21.22' SSW to 5/8" iron pin 2' west of edge of pavement		
35.18' SSW to "+" south end concrete pipe (P)		

Tuesday, July 13, 2021 Page 14 of 54

Section 11	NW	
Date Established 10/30/2007	INVV	
Corner NW		
Marker Iron Pipe and Witness Post		
14.75' N to mag nail west root of 15" dia. tree		
48.90' W to PK nail S/side 15" tree		
39.80' SW to PK nail SE/side 18" tree		
Section 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		N1⁄4
Date Established 10/30/2007		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin (½")		
19.85' NE to 5/8" x 30" iron pin at west edge of pavement (P)		
34.67' E to 5/8" iron pin at edge of pavement		
69.11' NE to duplex S/side of power pole		
Section 11		
Date Established 10/30/2007	<w¼nw< td=""><td></td></w¼nw<>	
Corner W <sup>1</sup> / <sub>4</sub> NW		
Marker RR Spike 3" deep		
25.00' E to "+" in concrete filled pipe (P)		
75.74' NNW to duplex E/side power pole (P)		
17.00' SE to "+" NE corner CB (P)		
18.42' W to duplex S/side wood post		
	-	

Tuesday, July 13, 2021 Page 15 of 54

Section 11	
<b>Date Established</b> 10/30/2007	
Corner W <sup>1</sup> / <sub>4</sub>	
Marker Small RR Spike	
21.43' W to "+" N/side concrete corner post	W1⁄4
12.15' NE to 5/8" iron pin at east edge of pavement	
11.89 SE to 5/8" iron pin at east edge of pavement	

Tuesday, July 13, 2021 Page 16 of 54

Section 12	IW
Date Established 10/30/2007	
Corner NW	
Marker Small RR Spike	
35.79' SE to duplex N/side power pole	
34.15' SW to "+" NE corner CB (P)	
43.04' NE to duplex NW/side wood post	
13.01 11E to dublex 11 W/ side Wood bost	
	·
Section 12	I,
Date Established10/30/2007	N <sup>1</sup> ⁄ <sub>4</sub>
Corner N <sup>1</sup> / <sub>4</sub>	
Marker RR Spike	
15.67' NNW to "+" SW corner CB (P)	
50.18' SE to duplex NE/side power pole (leaning north)	
20.80' N to "+" E/side concrete corner post	
20.80' SSW to "+" top center concrete headwall (P)	
Section 12	l NE
Date Established10/30/2007_	
Corner NE	
Marker RR Spike 2" below surface	
37.46' S to PK nail W/side wood corner post	
16.50' S to NW corner, Sec. 7, Monroe Twp.	
27.45' SE to 5/8" iron pin at south edge of pavement	
25.95' SW to 5/8" iron pin at south edge of pavement	
75.38' E to duplex N/side power pole	1

Tuesday, July 13, 2021 Page 17 of 54

Section 12		
<b>Date Established</b> 10/27/2007_		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
55.55' SW to duplex E/side power pole	W 1/4	
23.40' W to duplex E/side power pole		
19.11' SE to 5/8" iron pin at edge of berm		
	_	
	_	
	_	
	_	
Section 12		1
Date Established 4/19/2021		
<i>Corner</i> <u>E<sup>1</sup>/<sub>4</sub></u>		
Marker		92.55
Searched for stone by County crew, Did not find stone.	-	——E%
Found old buried fence line running N & S (3 hr. search).		1
Area appeared undisturbed and feel stone is there somewhere.		1
Began search midway and on line with NE corner and		1
SE corner. Sec. 12. Flatrock Twb.	_	
(Did not re-establish)	_	
	_	

Tuesday, July 13, 2021 Page 18 of 54

Gardian 12		
Section 13	NW	
Date Established 11/7/2007		
Corner NW		
Marker Small RR Spike		
39.43' NW to duplex NE/side power pole (new)		
61.61' WSW to "+" NE corner CB (P)		
61.61' WNW to "+" top east end concrete headwall (P)		
33.97' SE to 5/8" iron pin at edge of berm		
	_	
<b>Section</b> 13		N¹/4
Date Established11/7/2007		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
18.55' WSW to "+" top east end concrete headwall		
32.56' WNW to"+" east end concrete headwall		
21.44' S to nail/shiner N/side wood corner post		
49.62' ENE to duplex W/side power pole		
<b>Section</b> 13		NE
<b>Date Established</b> 11/7/2007		
Corner NE		
Marker Iron Pipe, 4' north of edge of pavement		
50.55' NNW to SE corner brick house foundation		
103.29' N to duplex E/side power pole (new)		
82.32' E to "+" SW corner CB		
65.59' SE to "+" SW corner CB (P)		
36.34' S to duplex N/side power pole		•
15.81' S to Monroe Twp. Corner		

Tuesday, July 13, 2021 Page 19 of 54

Section 13		
Date Established 11/7/2007		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
49.22' SE to duplex W/side power pole	W1⁄4	
86.59' NNW to duplex E/side power pole		
63.05' SW to "+" near face 2" gas pipe		
20.68' NE to 5/8" iron pin at edge of berm		

Tuesday, July 13, 2021 Page 20 of 54

Castion 14		
Section 14	NW	
Date Established 11/7/2007		
Corner NW		
Marker Small RR Spike		
24.65' NW to "+" south end concrete headwall (P)		
43.97' NNW to "+" north end concrete headwall (P)		
30.52' SE to "+" SE corner CB (P)		
30.64' NE to duplex SW/side GR post at approx. mid radius		
Section 14		
Date Established11/7/2007		N½
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
95.77' WNW to duplex S/side power pole		
15.01' N to PK nail west end 10" CMP (P)		
23.70' NE to PK nail east end 10" CMP (P)		
Section 14		
Date Established11/7/2007_		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
58.17' SSE to spike W/side power pole	W <sup>1</sup> / <sub>4</sub>	
21.59' ESE to "+" in witness stone		
60.13' NNE to duplex W/side power pole		
21.69' SW to duplex NE/side tree root		
19.90' W to 1" square bar		I

Tuesday, July 13, 2021 Page 21 of 54

G		
Section 15	NW	
Date Established 11/7/2007		
Corner NW		
Marker RR Spike		
21.94' ESE to "+" top east end concrete headwall (P)		
23.91' WSW to "+" top west end concrete headwall (P)		
26.39' WNW to "+" top west end concrete headwall (P)		
24.69' NNE to "+" top north end concrete headwall (P)		
38.90' SW to duplex SE/side power pole	_	
g 15		
Section 15		N1/4
Date Established 11/7/2007		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
29.49' S to duplex E/side power pole (new)		
19.06' NNW to PK nail west end 8" CMP (P)		
24.37' NE to PK nail east end 8" CMP (P)		
49.34' WSW to mag nail in 18" helical pipe		
Section 15		
Date Established11/7/2007		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike	W <sup>1</sup> / <sub>4</sub>	
18.30' SW to 5/8" iron pin 6' west of edge of pavement	W 74	
16.99' NW to 5/8" iron pin 6' west of edge of pavement		
12.45' SE to 5/8" iron pin 2' east of east edge of pavement		
20.80' NE to "+" in south end concrete drive pipe 33.99' NNE to "+" in north end concrete drive pipe		
33.99 ININE to T III HOLLII CHA CONCICLE ALIVE DIDE		

Tuesday, July 13, 2021 Page 22 of 54

6 4 16		
Section 16	NW	
Date Established 11/7/2007		
Corner NW		
Marker Small RR Spike	_	
54.42' NE to duplex NW/side power pole		
27.85' SW to duplex SE/side power pole		
20.93' SW to "+" in NE corner CB		
12.65' NW to 5/8" iron pin at edge of berm		
Section 16		N1/4
Date Established11/7/2007_		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike	_	
15.98' SSE to PK nail top east end 10" CMP (P)		
19.54' SW to PK nail top west end 10" CMP		
18.10' NNW to iron pin (P)		
18.65' NE to 5/8" iron pin at north edge of pavement		
Section 16		
Date Established11/7/2007_		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker RR Spike	_	
26.37' WNW to duplex S/side power pole	W¹⁄₄	
19.80' E to 5/8" capped iron pin		
17.40' W to PK nail in north end 15" N12 pipe		
26.87' SW to PK nail in south end 15" N12 pipe		

Tuesday, July 13, 2021 Page 23 of 54

Date Established 11/7/2007  Corner NW  Marker RR Spike 3" deep  81.58' NNE to nail/shiner NW/side power pole	
Marker RR Spike 3" deep	
81.58' NNE to nail/shiner NW/side power note	
61.56 TAINE to Hall/Shiller IN W/Side bower bole	
18.65' ENE to "+" SW side CB (P) (in concrete)	
78.42' SSE to duplex E/side power pole	
Section17_	
Date Established 11/7/2007	
Corner W <sup>1</sup> / <sub>4</sub>	
Marker RR Spike 2" deep	
21.85' ESE to PK nail W/side power pole W1/4	
28.02' SSW to "+" east end concrete headwall	
32.09' SW to "+" center concrete headwall	
37.38' SW to "+" west end concrete headwall	
55.80' WSW to PK nail NE/side power pole	

Tuesday, July 13, 2021 Page 24 of 54

~ .		
Section 18	NW	
Date Established11/1/2007_		
Corner NW		
Marker Small RR Spike		
29.07' NW to 5/8" iron pin on west ditch bank (P)		
23.64' NE to 5/8" iron pin 2' east of east edge of pavement		
14.45' SE to 5/8" iron pin 2' east of east edge of pavement		
131.91' N to Defiance Co. stone (Small RR Spike)		
Section18_		IN%
Date Established 4/30/2018		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Stone - found per survey Vol. 3, Pg. 140 & Sec. 18		
in old rewritten Field Book. Stone lies under remnants		
of wire fence running East & West.		
Placed witness post 0.8' north of stone.		
Cut "x" into high point of stone near center of stone.		
Stone lies 318'± W of c/l CR 424 (Section Line extended)		
Stone lies 318'± W of c/l CR 424 (Section Line extended)  Stone is 12"± in diameter. Placed broken clav tile around stone.		

Tuesday, July 13, 2021 Page 25 of 54

Section 19	NW	
<b>Date Established</b> 12/4/2007	INVV	
Corner NW		
Marker Iron Pipe		
Found mag nails 18' east and southeast		
54.29' SSE to "+" center west wall of CB (P)		
122.70' S to RR spike (Defiance Co. corner)		
45.41' NE to duplex S/side power pole		
Section 19		N <sup>1</sup> / <sub>4</sub>
<b>Date Established</b> 12/4/2007		1474
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
20.98' N to duplex E/side wood post		
34.81' SE to 5/8" iron pin on south ditch bank		
17.49' NE to 5/8" iron pin 3' north of edge of pavement		
8.36' SW to 5/8" iron pin at edge of berm		
Section 19		
<b>Date Established</b> 12/4/2007_		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin		
30.60' NW to 5/8" iron pin on west ditch bank	W¹⁄₄	
33.30' SW to 5/8" iron pin on west ditch bank		
37.96' E to mag nail N/side 18" walnut tree		

Tuesday, July 13, 2021 Page 26 of 54

Section 20	NW	
Date Established 12/4/2007		
Corner NW		
Marker RR Spike		
57.89' SSW to spike SE/side power pole		
32.89' SW to "+" south end RCP (P)		
47.67' NW to "+" north end RCP (P)		
39.14' NW to duplex SE/side power pole		
68.50' NNE to duplex W/side power pole		
	-	
Section20		N¹⁄4
Date Established 12/4/2007		
<i>Corner</i> <u>N<sup>1</sup>/<sub>4</sub></u>		
Marker Small RR Spike		
46.37' WSW to "+" top east end conc. block drainage structure		
16.82' NW to 5/8" iron pin 2' north of edge of pavement		
20.00' N to 5/8" iron pin		
17.11' NE to 5/8" iron pin 2'north of edge of pavement		
47.96' WNW to duplex S/side power pole		
Section20		
Date Established 12/4/2007		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
71.51' NNW to spike NE/side power pole	W1⁄4	
18.52' NE to 5/8" iron pin at east edge of pavement		
24.69' SE to 5/8" iron pin at east edge of berm		
19.44' W to PK nail east end 12" CMP	]	
	-	
	-	
	-	

Tuesday, July 13, 2021 Page 27 of 54

Section 21	NIVA/	
Date Established 12/4/2007	NW	
Corner NW		
Marker RR Spike		
34.81' NW to duplex NE/side power pole		
70.27' NE to SW corner brick veneer		
43.17' SW to PK nail in south end 24" N12 pipe		
Section 21  Details 12/1/2005		N1⁄4
Date Established 12/4/2007		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike	_	
38.55' NE to iron pin (P)		
24.25' S to PK nail north end 12" CMP (P) 24.20' N to duplex W/side wood corner post		
24.20 IN to duplex W/side wood corner post		
Section21		
Date Established 12/4/2007		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
31.73' NW to duplex SW/side power pole	W1⁄4	
26.51' NE to 5/8" iron pin at edge of berm		
23.35' W to duplex E/side 18" tree		

Tuesday, July 13, 2021 Page 28 of 54

Section 22	NIVA/	
Date Established 12/4/2007	NW	
Corner NW		
Marker Small RR Spike		
32.56' NW to "+" east end concrete headwall (P)		
30.00' NE to "+" east end concrete headwall (P)		
33.68' NW to spike SW/side power pole		
21.26' SE to 5/8" iron pin at edge of berm		
92.19' SW to "+" NE corner concrete slab		<b> </b>
Section 22		N <sup>1</sup> / <sub>4</sub>
<b>Date Established</b> 12/4/2007		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
29.23' NW to "+" in concrete headwall (P)		
20.15' NE to "+" in concrete headwall (P)		
19.54' SE to "+" in concrete headwall (P)		
28.90' SW to "+" in concrete headwall (P)		
Section 22		N½NE
Date Established 12/4/2007		
Corner N <sup>1</sup> / <sub>4</sub> NE		
Marker RR Spike 3" below surface		
29.94' SE to 5/8" iron pin on south ditch bank (P)		
21.81' NNW to 5/8" iron pin (P)		
46.91' SW to 5/8" iron pin on ditch bank (P)		
21.63' N to duplex S/side of power pole		

Tuesday, July 13, 2021 Page 29 of 54

Section	22_		
Date Esta	blished <u>12/4/2007</u>		
Corner	<u>W¹/4</u>		
Marker	Small RR Spike		
7.97' SW	to 5/8" iron pin at edge of pavement	W1⁄4	
19.22' SI	E to 5/8" iron pin at edge of pavement		
12.65' E	to 5/8" iron pin at edge of pavement		
		ı	

Tuesday, July 13, 2021 Page 30 of 54

Section 23	NW	
Date Established 12/4/2007		
Corner NW		
Marker RR Spike	_	
72.02' SSE to spike NW/side power pole		
48.14' WNW to duplex SW/side power pole		
53.30' NNE to spike NW/side power pole		
43.61' NE to duplex NW/side buried cable marker		
58.07' ESE to spike NW/side power pole		
Section 23		N1/4
Date Established 12/4/2007		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike	_	
23.10' NW to duplex NE/side buried cable marker		
24.57' NE to iron pin at edge of field		
14.13' S to "+" in NW corner CB		
19.91' S to 5/8" capped iron pin		
σ		
Section 23		
Date Established 12/4/2007		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike	_	
22.70' NE to 5/8" iron pin at east edge of pavement	W1⁄4	
21.65' SE to 5/8" iron pin at east edge of pavement		
20.83' E to duplex S/side power pole		

Tuesday, July 13, 2021 Page 31 of 54

S .: 24	r	
Section 24	NW	
Date Established 12/4/2007		
Corner NW		
Marker Small RR Spike		
33.95' NE to spike SE/side power pole		
99.20' SW to NE corner stone face of frame house		
38.39' SE to 5/8" iron pin in shoulder		
Section 24		N11/
Date Established 12/4/2007		N1⁄4
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
22.83' N to near face steel corner post 58.52' NE to nail/shiner SW/side power pole		
30.56' SW to duplex E/side 30" oak		
28.01' SE to 5/8" iron pin on south ditch bank		
20.01 SE to 5/6 Hon pin on south their bank		
Section 24		NE
Date Established 12/4/2007		
Corner <u>NE</u>		
Marker Small RR Spike		
23.70' N to duplex W/side power pole		
71.12' SW to NE cor. conc. foundation "James Dietrich" grave stone		
5.18' S to Monroe Twp. Corner		
28.82' SE to NW cor. conc. foundation "Cassie Bilow" grave stone		

Tuesday, July 13, 2021 Page 32 of 54

Section	24		
Date Esta	ablished <u>12/4/2007</u>		
Corner	<u>W<sup>1</sup>/<sub>4</sub></u>		
Marker	RR Spike		
62.58' N	NW to spike NE/side power pole	W1⁄4	
34.97' S'	W to iron pin on west ditch bank (P)		
24.01' N	E to iron pin at edge of berm		
		_	
		_	
		_	
		_	
		_	

Tuesday, July 13, 2021 Page 33 of 54

6 4		
Section 25	NW	
Date Established 12/7/2007		
Corner NW		
Marker PK Nail	_	
64.97' NNW to duplex SW/side power pole		
38.86' NE to PK nail east end 12" CMP (P)		
45.05' SE to PK nail east end 12" CMP (P)		
50.09' SE to nail/shiner NW/side telephone pole		
50.69' SW to duplex NE/side power pole		•
32.86' SW to "+" SW corner CB (P)		
51.01' NE to duplex SW/side power pole		
Section 25		N <sup>1</sup> / <sub>4</sub>
<b>Date Established</b> 12/7/2007		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Nail/Shiner		
37.73' NE to nail/shiner SW/side power pole		
25.57' SW to PK nail west end 8" N12 pipe		
31.37' SE to PK nail in east end 8" N12 pipe		
Section 25		l NE
		NE
Date Established 12/7/2007		
Corner <u>NE</u>		
Marker Nail/Shiner	_	
53.35' NW to "+" top south end concrete headwall		
44.23' N to nail/shiner S/side power pole		
29.11' NNE to "+" in SW corner CB		
58.56' SW to "+" in center south wall CB		
32.40' SE to "+" in center NE wing wall		1
6.80' S to Monroe Twp. corner		

Tuesday, July 13, 2021 Page 34 of 54

Section	25		
Date Esta	ablished <u>12/7/2007</u>		
Corner	<u>W¹/4</u>		
Marker	RR Spike 3" deep		
30.25' N	W to duplex NE/side power pole (pole leans east)	W <sup>1</sup> ⁄ <sub>4</sub>	
44.79' S'	W to 5/8" iron pin on west ditch bank (P)		
69.39' S	SE to "+" NE corner concrete CB		

Tuesday, July 13, 2021 Page 35 of 54

Section 26	NW	
Date Established 12/7/2007		
Corner NW		
Marker PK Nail	_	
58.41' SE to nail/shiner NW/side power pole		
59.61' NE to nail/shiner S/side power pole		
95.45' ENE to duplex S/side buried cable marker		
24.85' SW to "+" west end 36" RCP (P)		
31.63' SE to "+" east end 36" RCP (P)		•
Section26		N1/4
Date Established 12/7/2007		
<i>Corner</i> N <sup>1</sup> / <sub>4</sub>		
Marker Nail/Shiner		
42.84' S to nail/shiner N/side oak tree		
21.84' S to "+" west end concrete pipe (P)		
36.75' SE to "+" east end CIP (P)		
92.15' SE to duplex N/side power pole		
Section26		
Date Established12/7/2007_		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
20.16' E to SW corner concrete anchor post	W1⁄4	
88.90' SSE to duplex W/side buried cable marker		
106.93' SSE to "+" northeast end RCP (P)		
34.48 NW to duplex SW/side power pole		

Tuesday, July 13, 2021 Page 36 of 54

9.00		
Section 27	NW	
Date Established 12/7/2007		
Corner NW		
Marker Nail/Shiner		
38.78' NW to nail/shiner SE/side power pole		
40.21' SW to duplex SE/side power pole		
34.43' SE to "+" in SW corner CB top		
53.73' WNW to "+" SE corner CB		
Section 27		
		N <sup>1</sup> / <sub>4</sub>
Date Established 12/7/2007		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker PK Nail		
43.78' N to duplex S/side 12" arborvitae		
24.56' NE to 5/8" iron pin at edge of pavement		
23.75' NW to 5/8" iron pin at edge of pavement		
Section 27		
Date Established 12/7/2007		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
52.70' SE to duplex SW/side power pole	W <sup>1</sup> / <sub>4</sub>	
17.61' ENE to "+" north end concrete headwall		
14.51' W to "+" west end CMP (P)		
30.29' NNE to 5/8" iron pin 2' east of east edge of pavement		

Tuesday, July 13, 2021 Page 37 of 54

Section 28		<u> </u>
<b>Date Established</b> 12/7/2007	NW	
Corner NW		
Marker Nail/Shiner		
•		
36.62' NW to nail/shiner SE/side power pole		
45.75' SW to "+" west end 36" RCP (P) 52.16' SE to "+" east end 36" RCP (P)		
32.10 SE to + east end 30 RCF (F)		
Section 28		NII /
Date Established 12/7/2007		N1/4
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Nail/Shiner		
129.85' ENE to nail/shiner SW/side power pole		
142.41' WNW to duplex SE/side power pole		
30.47' NW to PK nail west end 12" CMP (P)		
25.85' NNW to PK nail east end 12" CMP (P)		
17.29' SW to 5/8" iron pin at edge of pavement		
Section28_		
Date Established 12/7/2007		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
39.25' NW to spike SW/side power pole	W¹⁄₄	
40.16' SW to 5/8" iron pin on west ditch bank (P)		
20.43' NE to 5/8" iron pin 4' east of east edge of pavement		
26.35' SE to 5/8" iron pin 5' east of east edge of pavement		

Tuesday, July 13, 2021 Page 38 of 54

g .: 20		<del></del>
Section 29	NW	
Date Established 8/29/2016		
Corner NW		
Marker Small RR spike		
58.00' NW to chiseled "+" in north end 78" Helical pipe		
54.67' SW to chiseled "+" in south end 78" Helical pipe		
58.01' NW to nail/shiner SE side power pole (14" above ground)		
45.88' NNW to "+" in US Coast & Geodetic Marker (D-300-1963)		
	-	
	-	
	-	
Section 29		N¹⁄4
Date Established 12/7/2007		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Nail/Shiner		
28.71' N to nail/shiner S/side corner post		
28.62' N to nail/shiner S/side power pole		
41.42' NE to PK nail west end CMP (P)		
61.49' NE to PK nail east end CMP		
	-	
	-	
	-	
Section 29	-	
Date Established 12/7/2007		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker RR Spike 1" deep		
21.33' E to SW corner angle iron anchor post	W1⁄4	
30.77' WSW to duplex N/side power pole		
23.80' NW to "+" NE wing culvert		
17.91' WNW to SE corner parapet wall		
		<u> </u>
	_	
	-	

Tuesday, July 13, 2021 Page 39 of 54

Section 30	NW	
Date Established 12/7/2007		
Corner NW		
Marker Small RR Spike		
37.26' SE to "+" center west wall CB (P)		
38.32' SE to duplex N/side power pole		
21.40' NW to "+" end of west wingwall		
33.55' NNW to "+" end of east wingwall		
36.15' ESE to center GIS Monument "Flat 30"		
Section30		N1⁄4
Date Established 12/7/2007		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker PK Nail		
22.10' SW to "+" west end concrete headwall		
24.97' SSW to "+" south end concrete headwall		
22.93' NNE to "+" south end concrete headwall (P)		
24.66' NW to "+" west end concrete headwall (P)		
	· ·	
Section 30		
Date Established 12/7/2007		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Replaced PK Nail with RR Spike (9/21/17) (S.K., C		
75.92' NNE to duplex W/side power pole	W1⁄4	
34.54' NE to "+" north end 12" concrete pipe (P)		
35.55' SE to "+" south end 12" concrete pipe (P)		
78.12' NW to duplex W/side power pole		
30.08' E to 5/8" property pin	<u>.                                    </u>	

Tuesday, July 13, 2021 Page 40 of 54

Section 31		
<b>Date Established</b> 12/14/2007	NW	
Corner NW		
Marker PK Nail		
58.28' SW to "+" N/side concrete post (P)		
62.51' NW to SE corner concrete block foundation		
38.96' SSW to NE anchor bolt of railroad signal tower (P)		
27.90' WSW to duplex SE/side power pole		
53.55' NE to "+" SW corner concrete slab	_	I
	-	
Section 31		N1⁄4
<b>Date Established</b> 12/14/2007		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
20.88' N to near face angle iron post		
75.47' SSW to NE corner concrete porch (under wood deck)		
49.73' NE to duplex SW/side tree		
20.35' S to "+" in concrete over tile (P) (1989 tie)		
	_	
Section 31		
Date Established 12/14/2007		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike	T.R. G1	
39.69' N to iron pin at E 1/4 Post. Sec. 36. Richland Twp Def. Co.	W1⁄4	
50.30' ENE to duplex NW/side power pole		
41.48' SE to duplex NE/side power pole		
72.80' NW to duplex S/side power pole	1	
68.54' NNW to "+" north end CMP (P)	_	
40.64' NW to "+ in concrete wing (P)	_	
64.94' SSE to duplex SW/side power pole	_	

Tuesday, July 13, 2021 Page 41 of 54

Section 31		
Date Established 12/14/2007		
Corner CENTER		
Marker Iron Pin 12" deep	,	<i>(</i>
19.48' NE to 5/8" iron pin at north edge of pavement	CEN	ITER
35.45' NW to duplex S/side power pole		
25.98' SE to 5/8" iron pin on S/side ditch bank		
<b>Section</b> 31		
Date Established 12/14/2007		
Corner SW		
Marker RR Spike		
45.22' SW to "+" in concrete wingwall		
36.35' SE to "+" in concrete wingwall		
91.42' NNE to duplex W/side power pole		
49.65' NW to duplex S/side power pole	SW	
41.47' NW to "+" SE corner CB (P)		
Section 31		
Date Established 12/14/2007		
Corner S <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
176.97' E to N <sup>1</sup> / <sub>4</sub> Post, Sec. 6. Pleasant Twp.		
18.61' NW to 5/8" iron pin along north edge of pavement		
19.00' NE to 5/8" iron pin along north edge of pavement		
		S1/4

Tuesday, July 13, 2021 Page 42 of 54

	_	
Section 32	NW	
Date Established 12/14/2007		
Corner NW		
Marker RR Spike		
25.11' NW to SE corner concrete bridge curb		
37.36' NE to center USGS BM "E300 1963"		
18.77' SW to NE corner bridge curb		
27.33' SE to ¾" iron pin at edge of berm		
Section 32		N1/4
Date Established 12/14/2007		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
42.67' SE to PK nail east end N12 pipe (P)		
24.17' S to PK nail north end corrugated pipe (P)		
24.56' N to PK nail north end N12 pipe (P)		
Section 32		N¹4NE
Date Established 12/14/2007		
Corner N <sup>1</sup> / <sub>4</sub> NE		
Marker Small RR Spike		
20.03' SW to 5/8" iron pin at south edge of pavement		
12.07' WNW to 5/8" iron pin at north edge of pavement		
14.65' ENE to 5/8" iron pin at north edge of pavement		

Tuesday, July 13, 2021 Page 43 of 54

Section 32	I	
Date Established 12/14/2007		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
•	W1⁄4	
39.84' NW to "+" north end RCP (P)		
27.07' WSW to "+" in concrete headwall		
64.97' WNW to duplex S/side power pole		
28.72' NE to duplex NW/side buried cable marker		
66.95' NNE to duplex S/side power pole		
Section 32		
Date Established 12/14/2007		
Corner CENTER		
Marker Small RR Spike	y	/
20.09' S to iron pipe (P)	CEN	ITER
106.99' WSW to duplex N/side power pole		
10.14' NE to 5/8" iron pin 3' north of edge of pavement		
9.90' NW to 5/8" iron pin 3' north of edge of pavement		
Section 32		
Date Established 12/19/2007		
Corner OTHER		
Marker Iron Pin		<b>/</b> 991.65' <b>\</b>
44.85' NE to duplex S/side power pole		\
26.31' SE to duplex SW/side power pole		
55.18' SW to NE corner porch foundation		

Tuesday, July 13, 2021 Page 44 of 54

Section 32		
Date Established 12/19/2007		
Corner SW		
Marker Small RR Spike		
44.17' ESE to "+" in concrete anchor for GR		
27.76' WSW to "+" in SE abutment		
40.59' NW to "+" in NE abutment		
33.38' NNW to "+" in concrete anchor GR post	sw	
118.09' E to Pleasant Twp. corner		
	-	
	-	
Section 32	-	
Date Established 12/14/2007		
Corner S <sup>1</sup> / <sub>4</sub>		
Marker PK Nail		
96.45' E to Pleasant Twp. stone		
32.95' NNW to duplex W/side power pole		
70.73' NW to southeast corner concrete block foundation		
45.93' S to duplex E/side power pole		S1/4
84.31' SE to mag nail in west end N12 pipe	_	
	_	
	_	

Tuesday, July 13, 2021 Page 45 of 54

g .: 22		
Section 33	NW	
Date Established 12/14/2007		
Corner NW		
Marker Small RR Spike		
34.84' NW to duplex SW/side power pole		
32.79' SSW to "+" south end 54" concrete pipe (P)		
45.79' NNW to "+" in north end 54" RCP		
34.14' SW to "+" in west end 54" RCP		
Section 33	_	N¹⁄4
Date Established 12/14/2007		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
20.80' S to "+" west face concrete corner post		
19.83' N to duplex E/side power pole		
24.70' SE to "+" in NW corner 22B CB		
37.66' SW to "+" in NE corner CB		
Section 33		
Date Established 4/17/2021		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
55.30' ENE to PK nail S/side electric meter post	W1⁄4	
86.98' SE to PK nail N/side brace pole (5' above ground)		
84.70' S to PK nail N/side power pole (5' above ground)		
23.00' N to center SE bolt stud		
51.05' SE to center NW bolt stud		

Tuesday, July 13, 2021 Page 46 of 54

Section 33		
<i>Date Established</i> 12/14/2007		
Corner W <sup>1</sup> / <sub>4</sub> SW		
Marker Iron Pin 8" deep	_	
35.13' SW to 5/8" iron pin on west ditch bank		
29.20' NW to duplex NE/side power pole	<b>∠</b> W¼SW	
40.59' SE to "+" SW corner CB (P)		
40.04' NE to duplex W/side 8" pine tree		
Section 33		
<b>Date Established</b> 12/14/2007_		
Corner SW		
Marker Mag Nail	_	
46.15' SE to "+" NW corner CB (P)		
42.17' SW to duplex SE/side power pole		
40.00' SSW to nail/shiner N/side buried cable marker		
28.05' NNW to "+" in NE corner concrete box culvert	SW	
25.26' S to center USGS bench mark (P)		
85.15' E to Pleasant Twp. stone		
<b>Section</b> 33		
Date Established 12/14/2007		
Corner S <sup>1</sup> / <sub>4</sub>		
Marker Nail/Shiner		
79.17' E to Pleasant Twp. stone		
80.92' WSW to nail/shiner NE/side power pole		
25.46' NW to 5/8" iron pin at north edge of pavement		
20.69' NE to 5/8" iron pin at north edge of pavement	S1/4	

Tuesday, July 13, 2021 Page 47 of 54

Section 34		I
<b>Date Established</b> 12/14/2007	NW	
Corner NW		
Marker Small RR Spike		
34.06' NE to duplex SE/side power pole		
31.02' SW to NE corner concrete post		
31.21' SW to PK nail SE/side underground cable marker post		
32.80' NE to duplex W/side buried cable marker		
23.53' SE to "+" east end 36" RCP (P)		
24.42' SW to "+" west end 36" RCP (P)		
Section 34		N½
<b>Date Established</b> 12/14/2007_		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
30.99' SW to duplex SE/side underground cable marker (leaning)		
37.89' N to duplex W/side power pole		
35.71' SW to "+" in center north wall CB		
21.42' NNE to duplex S/side 42" oak tree		
65.93' ENE to duplex S/side 40" oak tree		
<b>Section</b> 34		
Date Established 12/14/2007		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin		
32.73' E to "+" SW corner CB	W1⁄4	
44.62' NW to 5/8" iron pin on west ditch bank		
15.61' WNW to rivet NE end CMP (P)		
	<u>.                                    </u>	
	-	

Tuesday, July 13, 2021 Page 48 of 54

~ .		
Section 34		
Date Established 12/14/2007		
Corner SW		
Marker Nail/Shiner		
44.24' NE to duplex SE/side telephone pole		
58.35' SE to duplex NW/side power pole		
50.80' NNW to "+" west end south bridge abutment		
51.60' NNE to "+" east end south bridge abutment	SW	
Section 34	- - -	
Date Established 12/14/2007		
Corner S <sup>1</sup> / <sub>4</sub>		
Marker Nail/Shiner		
25.78' NNE to duplex E/side telephone pole		
63.99' E to Pleasant Twp. corner		
39.16' SW to nail/shiner NE/side power pole	_	
25.40' NW to 5/8" iron pin 1' north of north edge of pavement	_	S1/4
	_	
	-	
	-	

Tuesday, July 13, 2021 Page 49 of 54

Section 35	NW	
Date Established 12/14/2007	INVV	
Corner NW		
Marker RR Spike		
76.03' WNW to duplex S/side power pole		
84.28' NNW to spike E/side power pole		
24.74' SE to "+" south end concrete headwall (P)		
22.18' SW to notch cut in west end CIP (P)		
28.62' SW to spike N/side wood anchor post	_	
	-	
Section 35		N¹/4
<b>Date Established</b> 12/14/2007		
Corner N <sup>1</sup> / <sub>4</sub>		
Marker RR Spike		
13.38' SSW to '+" NE corner CB (P)		
18.50' NNE to "+" NE corner CB (P)		
14.62' SE to 5/8" iron pin 1' south of edge of pavement		
16.63' NE to 5/8" iron pin 1' north of edge of pavement	_	
	- - -	
Section 35		
Date Established 12/14/2007		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Iron Pin		
31.90' SE to "+" center east wall CB (P)	W1⁄4	
96.91' NNW to duplex E/side power pole		
28.24' NE to 5/8" iron pin at east edge of pavement	_	
24.68' SE to 5/8" ironpin at east edge of pavement	_	
20.37' SW to PK in west end 12" N12 pipe (2' from end)	_	
	_	

Tuesday, July 13, 2021 Page 50 of 54

a 25		
Section 35		
<b>Date Established</b> 12/14/2007_		
Corner SW		
Marker Nail/Shiner		
38.53' NNW to "+" north end 52" x 76" RCP (P)		
65.46' SW to duplex N/side power pole (5' above ground)		
39.46' NW to 16d spike NE/side telephone pole		
31.35' SSW to "+" south end 52" x 76" RCP (P)	sw	
65.03' NNW to nail/shiner S/side power pole		
46.43' E to Pleasant Twp. corner	_	
	-	
Section 35		
Date Established 12/14/2007		
Corner S <sup>1</sup> / <sub>4</sub>		
Marker Nail/Shiner		
65.48' E to N <sup>1</sup> / <sub>4</sub> Post, Sec. 2, Pleasant Twp.		
29.14' N to near face iron fence post		
75.15' ESE to nail/shiner NW/side power pole		
75.29' ESE to duplex N/side power pole		S1/4
23.71' SE to mag nail east end N12 pipe (P)		<u> </u>
31.25' SW to mag nail west end N12 pipe (P)	_	
71.70' ESE to iron pin in concrete	_	

Tuesday, July 13, 2021 Page 51 of 54

Section 36	NW	
Date Established 12/19/2007		
Corner NW		
Marker RR Spike		
46.47' ENE to duplex N/side power pole		
67.75' SSE to duplex NE/side telephone pole		
19.29' SW to "+" south end cast iron pipe (P) (1980 tie)		
30.38' NW to duplex SW/side power pole		
	-	
	-	
	_	
Section 36	_	N11/
Date Established 12/19/2007		N1⁄4
Corner N <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
63.94' WNW to PK nail SW/side power pole	-	
13.39' NNE to 5/8" iron pin 2' north of north edge of pavement	_	
11.42' SW to 5/8" iron pin 1½' south of south edge of pavement		
	_	
	_	
	_	
Section 36		NE
Date Established 12/19/2007		
Corner <u>NE</u>		
Marker Small RR Spike		
16.76' NE to "+" north end concrete pipe (P)		
43.60' SE to "+" south end concrete pipe (P)		
33.85' SW to PK in west end 12" N12 pipe		
	_	
	_	
	_	

Tuesday, July 13, 2021 Page 52 of 54

Section 36		
Date Established 12/14/2007		
Corner W <sup>1</sup> / <sub>4</sub>		
Marker Found Iron pipe 8" deep		
Set Small RR Spike on surface	W¹⁄₄	
22.91' W to near face railroad rail		
38.07' NE to nail/shiner SW/side power pole		
27.87' SW to nail/shiner E/side power pole		
27.11' WSW to "+" north wing drainage structure	_	
	_	
	-	
Section 36		
<b>Date Established</b> 12/14/2007		
Corner SW		
Marker Nail/Shiner		
60.33' NNW to duplex S/side power pole		
62.82' SSW to NE corner porch foundation		
35.24' NW to "+" S/side manhole rim		
45.65' SE to "+" SE/side manhole rim	sw	
43.14' NE to duplex S/side power pole		
64.69' SE to duplex N/side power pole	_	
45.17' SSE to "+" north flange bolt of fire hydrant	_	
Section 36		<u> </u>
Date Established 12/14/2007		
Corner S <sup>1</sup> / <sub>4</sub>		
Marker Small RR Spike		
16.40' E to Pleasant Twp. corner		
29.85' NNW to nail/shiner SE/side power pole		
76.17' N to nail/shiner S/side power pole		
55.07' NE to 5/8" iron pin at mid. radius of edge of pavement		S1/4
	_	
	_	

Tuesday, July 13, 2021 Page 53 of 54

Section	36		
Date Esta	ablished9/5/2007_		
Corner	SE		
Marker	Small RR Spike		
59.40' W	NW to shiner SE/side power pole (near ground level)		
35.65' N	to shiner S/side 12" maple		
44.92' N	E to shiner SW/side 15" maple		
33.95' S'	W to PK nail north end 18" CMP (P)		SE
		_	
		_	
		_	

Tuesday, July 13, 2021 Page 54 of 54